



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD Number	CAA-2015-06-004A	發布日期 Date issued	2015/8/24
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	RB211 Trent 768-60, 772-60, 772B-60 and 772C-60 engines, all serial numbers (s/n), except those that have Modification (Mod) 72-H754 applied in production, or have been modified in-service by RR Service Bulletin (SB) RB.211-72-H754. These engines are known to be installed on, but not limited to, Airbus A330 aeroplanes.		
主旨摘要	Engine – High / Intermediate Pressure Turbine Bearing Support Oil Feed Tube Sealing Sleeve – Inspection / Replacement		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主關機構 Original Authorities <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國AD編號 Original AD number	2015-0105R1	
	1. 直接採用原AD之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) ___ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將AD執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 72. This AD revises EASA AD 2015-0105(CAA-2015-06-004) dated 10 June 2015, which superseded EASA AD 2014-0168(CAA-2014-07-015) dated 16 July 2014.		
註：1. AD內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331-3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw Note：1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331-3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw			

EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2015-0105R1</p> <p>Date: 18 August 2015</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EU 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
<p>Design Approval Holder's Name: ROLLS-ROYCE plc</p>	<p>Type/Model designation(s): RB211 Trent 700 engines</p>	
<p>TCDS Number:</p>	<p>EASA.E.042</p>	
<p>Foreign AD:</p>	<p>Not applicable</p>	
<p>Revision:</p>	<p>This AD revises EASA AD 2015-0105 dated 10 June 2015, which superseded EASA AD 2014-0168 dated 16 July 2014.</p>	
<p>ATA 72</p>	<p>Engine – High / Intermediate Pressure Turbine Bearing Support Oil Feed Tube Sealing Sleeve – Inspection / Replacement</p>	
<p>Manufacturer(s):</p>	<p>Rolls-Royce plc (RR)</p>	
<p>Applicability:</p>	<p>RB211 Trent 768-60, 772-60, 772B-60 and 772C-60 engines, all serial numbers (s/n), except those that have Modification (Mod) 72-H754 applied in production, or have been modified in-service by RR Service Bulletin (SB) RB.211-72-H754.</p> <p>These engines are known to be installed on, but not limited to, Airbus A330 aeroplanes.</p>	
<p>Reason:</p>	<p>Several occurrences were reported of high oil consumption on Trent 700 engines, caused by fracture of the High/Intermediate Pressure (HP/IP) turbine support internal oil feed tube Part Number (P/N) FW46689. The oil feed tube threaded end adaptor and sealing sleeve P/N FW15003 are designed to form a sliding joint which, if restrained, can compress the oil feed tube during thermal contraction of the turbine casing at the end of the flight cycle. On each subsequent flight, the thermal growth and contraction of the turbine casing relative to the oil tube, during the heating and cooling phases of the flight cycle, apply a load cycle to the tube, which may lead to low cycle fatigue fracture.</p> <p>This condition, if not detected and corrected, could lead to fire and overheating of the turbine discs and, consequently, an uncontained engine failure, possibly resulting in damage to the aeroplane and injury to occupants and/or persons on the ground.</p>	

	<p>Investigation of the affected oil feed tube sealing sleeve P/N FW15003 found that one supplier of this part had manufactured some sealing sleeves with the internal diameter below the drawing minimum, which can cause binding at the sliding joint. Investigation of the supply history identified a population of engines which have potentially been fitted with an affected sleeve during manufacture, or during Module 51 rework (check, repair or higher level work scope) between 1 July 2009 and 31 October 2013, as identified in RR Non-Modification Service Bulletin (NMSB) RB.211-72-AH673.</p> <p>Prompted by these findings, EASA issued AD 2014-0168 to require a one-time inspection of the affected engines and removal from service of all affected P/N FW15003 oil feed tube sealing sleeves.</p> <p>Since that AD was issued, investigation results confirmed that most occurrences were attributable to the non-conforming sealing sleeve. However, a more recent event of high oil consumption was reported, on an engine which did not have an affected sealing sleeve fitted. Investigation established that some oil feed adaptors P/N FW49471 have been manufactured with an outer diameter larger than the drawing maximum. This condition can restrain the sliding joint in a similar way as an undersized sealing sleeve, possibly resulting in the same unsafe condition addressed by EASA AD 2014-0168.</p> <p>Consequently, EASA issued AD 2015-0105, retaining the requirements of EASA AD 2014-0168, which was superseded, to require a one-time inspection of more oil feed sealing sleeves, and, depending on findings, replacement of the sealing sleeves and tubes.</p> <p>Since that AD was issued, it was determined that for replacement of parts, RR NMSB RB.211-72-AJ035 only made reference to a modification (new P/N parts in accordance with RR SB RB.211-72-H754) of the engine, which implied that the same P/N parts could no longer be installed, thereby contradicting the AD, which does not require a modification. RR have revised the NMSB for clarification. In addition, it was found that EASA AD 2015-0105 inadvertently made reference to 'external' parts (tubes and adaptors).</p> <p>For the reasons described above, this AD is revised to confirm that engine modification is not required, and to remove the references to 'external' parts. This AD also excludes post-Mod/SB 72-H754 engines from the Applicability, since the affected oil feed tube sealing sleeve P/N FW15003 is not part of that engine configuration.</p>
Effective Date:	Revision 1: 18 August 2015 Original issue: 24 June 2015
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>Note: Where, in this AD, reference is made to an RR Mod, SB or NMSB with an 'A' (Alert) in the number, it should be recognised that an earlier or later revision may not have that 'A'. This kind of change does not effectively alter the publication references for the purpose of this AD.</p> <p>Re-statement of the requirements of EASA AD 2014-0168:</p> <p>(1) For engines s/n up to 42330 inclusive, except s/n 42310, 42311, 42312, 42314 to 42317 inclusive, 42321 to 42327 inclusive, and 42329:</p> <p>Within 6 months after 01 August 2014 [the effective date of EASA AD 2014-0168], inspect the P/N FW15003 oil feed tube sealing sleeve and, if it is determined that the oil feed tube sealing sleeve was manufactured by supplier A, as defined in RR NMSB RB211-72-AH673, and does not have the marking 102013, 112013 or 102013L, take a replicast and replace the affected oil feed tube sealing sleeve with a serviceable oil feed tube sealing sleeve in accordance with the instructions of RR NMSB RB211-72-AH673.</p>

	<p>(2) Within 30 days after taking the replicast, as required by paragraph (1) of this AD, send the replicast to RR in accordance with the instructions of RR NMSB RB211-72-AH673.</p> <p>(3) For all engines: From 01 August 2014 [the effective date of EASA AD 2014-0168], it is allowed to install on any engine an oil feed tube sealing sleeve P/N FW15003 manufactured by supplier A (as defined in RR NMSB RB211-72-AH673), provided the part has the marking 102013, 112013 or 102013L.</p> <p>New requirements of this AD:</p> <p>(4) For engines s/n up to 42330 inclusive: Within 1 600 flight cycles or 24 months, whichever occurs first after 24 June 2015 [the effective date of the original issue of this AD], inspect each P/N FW15003 oil feed sealing sleeve to identify the marking 102013, 112013 or 102013L in accordance with the instructions of RR NMSB RB.211-72-AJ035.</p> <p>A review of engine maintenance records is acceptable to make the determination as specified in this paragraph, provided those records can be relied upon for that purpose, and the markings on the P/N FW15003 oil feed sealing sleeve can be conclusively identified from that review.</p> <p>(5) If, during the inspection as required by paragraph (4) of this AD, a sealing sleeve P/N FW15003 is found without marking 102013, 112013 or 102013L, before next flight or (if inspected in shop) before release to service of the engine, as applicable, replace the affected parts with serviceable parts in accordance with the instructions of RR NMSB RB.211-72-AJ035.</p> <p>(6) For all engines: From 24 June 2015 [the effective date of the original issue of this AD], it is allowed to install on any engine an oil feed tube sealing sleeve P/N FW15003, provided the part has the marking 102013, 112013 or 102013L.</p>
Ref. Publications:	<p>Rolls-Royce NMSB RB.211-72-H673 dated 30 January 2014, or Revision 1 dated 21 February 2014, or NMSB RB.211-72-AH673 Revision 2 dated 27 June 2014.</p> <p>Rolls-Royce NMSB RB.211-72-AJ035 dated 11 May 2015, or Revision 1 dated 20 May 2015, or Revision 2 dated 10 August 2015.</p> <p>Rolls-Royce SB RB.211-72-H754 dated 01 October 2014, or Revision 1 dated 29 July 2015.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>
Remarks:	<ol style="list-style-type: none"> If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. The original issue of this AD was posted on 05 May 2015 as PAD 15-056 for consultation until 02 June 2015. The Comment Response Document can be found at http://ad.easa.europa.eu. Enquiries regarding this AD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu. For any question concerning the technical content of the requirements in this AD, please contact your designated Rolls-Royce representative or download the publication from your Aeromanager account at www.aeromanager.com. <p>If you do not have a designated representative or Aeromanager account, please contact Corporate Communications at Rolls-Royce plc., P.O. Box 31, Derby, DE24 8BJ, United Kingdom, Telephone: +44 (0) 1332 242424, or</p>

	<p>send an e-mail through http://www.rolls-royce.com/contact/civil_team.jsp identifying the correspondence as being related to airworthiness directives.</p>
--	---