



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD Number	CAA-2015-08-010	發布日期 Date issued	2015/8/28
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	ARRIEL 2C, 2C1, 2C2, 2S1 and 2S2 engines, all serial numbers, if incorporating Turboméca modification (mod) TU 34 or mod TU34A – “Torque conformation box, increase of resistance to temperature”. These engines are known to be installed on, but not limited to, Airbus Helicopters AS 365 N3, EC155 B/B1 and Sikorsky S-76C+, S76C++ helicopters.		
主旨摘要	Engine – Torque Conformation Box – Check		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主關機構 Original Authorities <input type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input type="checkbox"/> UK CAA <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國AD編號 Original AD number	2015-0177	
	1. 直接採用原AD之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) ____ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將AD執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 72. Ref. Publications: Turboméca MSB 292 72 2860 version A dated 15 July 2015. and Turboméca MSB 292 72 2188 version A dated 02 July 2015.		
註： 1. AD內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw			

EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2015-0177</p> <p>Date: 25 August 2015</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EU 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>	
<p>Design Approval Holder's Name:</p> <p>TURBOMECA</p>	<p>Type/Model designation(s):</p> <p>ARRIEL 2 engines</p>
TCDS Number:	EASA.E.001
Foreign AD:	Not applicable
Supersedure:	None
ATA 72	Engine – Torque Conformation Box – Check
Manufacturer(s):	Turboméca S.A.
Applicability:	<p>ARRIEL 2C, 2C1, 2C2, 2S1 and 2S2 engines, all serial numbers, if incorporating Turboméca modification (mod) TU 34 or mod TU34A – “Torque conformation box, increase of resistance to temperature”.</p> <p>These engines are known to be installed on, but not limited to, Airbus Helicopters AS 365 N3, EC155 B/B1 and Sikorsky S-76C+, S76C++ helicopters.</p>
Reason:	<p>Several cases of torque conformation box (TCB) failures have been reported on engines incorporating mod TU34 or mod TU34A. Investigation concluded that these failures were caused by cracks on soldered joints of TCB resistors.</p> <p>This condition, if not corrected, could lead to limited power availability in a One Engine Inoperative (OEI) case, possibly resulting in reduced control of the helicopter.</p> <p>To address this unsafe condition, Turboméca issued Mandatory Service Bulletin (MSB) 292 72 2860 version A providing instructions for TCB checks.</p> <p>For the reasons described above, this AD requires repetitive TCB checks and, depending on findings, replacement of the TCB with a serviceable one. This AD also provides an optional terminating action for the required repetitive checks.</p>
Effective Date:	08 September 2015

<p>Required Action(s) and Compliance Time(s):</p>	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) Within 600 engine flight hours (EH), or 6 months, whichever occurs first after the effective date of this AD, and, thereafter, at intervals not to exceed 600 EH, accomplish a torque conformation check (comprising two torque conformation box resistance values checks) in accordance with the instructions of Turboméca MSB 292 72 2860. <p>Note: A non-cumulative tolerance of 10% may be applied to the compliance times specified in paragraph (1) of this AD to allow synchronisation of the required inspections with other maintenance tasks for which a non-cumulative tolerance is already granted in the applicable Engine Maintenance Manual.</p> <ol style="list-style-type: none"> (2) If, during any check as required by paragraph (1) of this AD, any discrepancy is identified, before next flight, replace the affected TCB with a serviceable one in accordance with the instructions of Turboméca MSB 292 72 2860. (3) Replacement of the TCB on an engine with a serviceable TU34 or TU34A TCB does not constitute terminating action for the repetitive checks required by paragraph (1) of this AD for that engine. (4) Modification of an engine in accordance with the instructions of Turboméca SB 292-72-2188 constitutes terminating action for the repetitive checks as required by paragraph (2) of this AD for that engine, provided that, following modification, no mod TU34 TCB or mod TU34A TCB is re-installed on that engine.
<p>Ref. Publications:</p>	<p>Turboméca MSB 292 72 2860 version A dated 15 July 2015.</p> <p>Turboméca MSB 292 72 2188 version A dated 02 July 2015.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p>
<p>Remarks:</p>	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. This AD was posted on 22 July 2015 as PAD 15-094 for consultation until 19 August 2015. The Comment Response Document can be found at http://ad.easa.europa.eu. 3. Enquiries regarding this AD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu. 4. For any question concerning the technical content of the requirements in this AD, please contact: Turboméca S.A., ARRIEL 2 Customer Support 40220 Tarnos, France Fax: +33 5 59 74 45 15, or your usual or nearest TURBOMECA technical representative (refer to http://www.turbomeca-support.com).