

 適航指令發布單 Airworthiness Directive Issuance Form			
民航局 AD 編號 AD number	CAA-2016-07-006	發布日期 Date issued	2016/7/15
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342 and A330-343 aeroplanes, all manufacturer serial numbers (MSN), Airbus A340-211, A340-212, A340-213, A340-311, A340-312 and A340-313 aeroplanes, all MSN.		
主旨摘要	Equipment / Furnishings - Emergency Exit Door 3 Type 1 Slide - Identification / Replacement		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input type="checkbox"/> UK CAA <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2016-0137	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 25. Ref. Publications: Airbus AOT A25L009-16 original issue dated 07 July 2016.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2016-0137

Issued: 08 July 2016

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A330 and A340 aeroplanes

Effective Date: 22 July 2016

TCDS Number(s): EASA.A.004, EASA.A.015

Foreign AD: Not applicable

Supersedure: None

ATA 25 – Equipment / Furnishings – Emergency Exit Door 3 Type 1 Slide – Identification / Replacement

Manufacturer(s):

Airbus (formerly Airbus Industrie)

Applicability:

Airbus A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342 and A330-343 aeroplanes, all manufacturer serial numbers (MSN),

Airbus A340-211, A340-212, A340-213, A340-311, A340-312 and A340-313 aeroplanes, all MSN.

Reason:

It has been reported that some door 3 Type 1 escape slides Part Number (P/N) 7A1509-series may have sustained damage to the slide aspirator, due to an incorrect packing during last overhaul. This damage affects the air inlet end of the slide aspirator by either permanently deforming the inlet, or leading to cracks in the supply line to the aspirator nozzle.

This condition, if not detected and corrected, could lead to failure of the slide aspirator to perform its intended function to inflate the evacuation slide, preventing slide deployment during an emergency, possibly resulting in reduced evacuation capacity from the aeroplane and consequent injury to occupants.



Prompted by these findings, Airbus issued Alert Operators Transmission (AOT) A25L009-16 to provide instructions to identify and replace the affected slides.

For the reasons described above, this AD requires identification of the door 3 Type 1 slide installed on the aeroplane, and, depending on findings, the replacement of the slide with a serviceable part.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Note 1: For the purpose of this AD, an affected slide has a P/N and a Serial Number (s/n) as listed in Table 1 of this AD.

Table 1 – Affected Slides

Slide P/N	Slide s/n
7A1509-027	AD0918, AD0975, AD0979, AD1111 and AD1155
7A1509-037	AD0488, AD0759, AD0942, AD0960, AD1025, AD1033, AD1034, AD1080 and AD1184
7A1509-123	AD1231, AD1232, AD1450, AD1565, AD1730, AD1737, AD1805, AD1822 and AD1860
7A1509-125	AD1769, AD1780, AD1781, AD1816, AD1834, AD1841, AD1862, AD1869, AD2066, AD2103, AD2104, AD2178, AD2223, AD2263, AD2279, AD2301, AD2407, AD2409 and AD2497

- (1) Within 30 days after the effective date of this AD, inspect each left hand (LH) and right hand (RH) door 3 Type 1 slide to identify the P/N and the s/n in accordance with the instructions of Airbus AOT A25L009-16. A review of aeroplane delivery and/or maintenance records is acceptable in lieu of this inspection, provided that those records can be relied upon for that purpose and the P/N and the s/n of each slide can be positively identified from that review.

Note 2: Airbus AOT A25L009-16 lists the corresponding aeroplane MSN on which the affected slides (see Table 1 of this AD) were reinstalled after last maintenance. That MSN list is for information only, as it cannot be excluded that a potentially affected slide has been removed from an aeroplane and later re-installed on another aeroplane.

- (2) For each affected slide, identified as required in paragraph (1) of this AD, within the compliance time defined in Table 2 of this AD, as applicable, replace each affected slide with a serviceable one in accordance with the instructions of Airbus AOT A25L009-16.



Table 2 – Slides Replacement

Affected Slide Position(s)	Compliance Time / Action
LH and RH side	Before next flight after identification as required by paragraph (1) of this AD, replace at least one slide, and, within 10 months or 4 100 flight hours (FH), whichever occurs first after the effective date of this AD, replace the second slide
LH or RH side	Within 10 months or 4 100 FH, whichever occurs first after the effective date of this AD, replace the slide

- (3) From the effective date of this AD, it is allowed to install an affected slide (see Table 1 of this AD) on any aeroplane at door 3 Type 1 position, provided it is determined that the slide has been overhauled after 01 May 2016.

Ref. Publications:

Airbus AOT A25L009-16 original issue dated 07 July 2016.

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The results of the safety assessment have indicated the need for immediate publication and notification, without the full consultation process.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – EIAL (Airworthiness Office), E-mail: airworthiness.A330-A340@airbus.com.

