



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD Number	CAA-2016-07-014	發布日期 Date issued	2016/8/3
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Bombardier Inc. model BD-700-1A10 and BD-700-1A11 aeroplanes, serial numbers (S/Ns) 9002 through 9763, 9765, 9767 through 9770, and 9998.		
主旨摘要	Engine - Rear Mount Retaining Bolt Failure		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主關機構 Original Authorities <input type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input type="checkbox"/> UK CAA <input checked="" type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國AD編號 Original AD number	CF-2016-23	
	1. 直接採用原AD之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) ____ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將AD執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	Bombardier Service Bulletins (SBs) 700-71-002, 700-71-6002, 700-71-5002 and 700-1A11-71-002.		
註：1. AD內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw Note：1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw			



AIRWORTHINESS DIRECTIVE

This Airworthiness Directive (AD) is issued pursuant to Canadian Aviation Regulation (CAR) 521.427. No person shall conduct a take-off or permit a take-off to be conducted in an aircraft that is in their legal custody and control, unless the requirements of CAR 605.84 pertaining to ADs are met. Standard 625 - Aircraft Equipment and Maintenance Standards Appendix H provides information concerning alternative means of compliance (AMOC) to ADs.

Number:

CF-2016-23

Effective Date:

8 August 2016

ATA:

72

Type Certificate:

A-177

Subject:

Engine - Rear Mount Retaining Bolt Failure

Applicability:

Bombardier Inc. model BD-700-1A10 and BD-700-1A11 aeroplanes, serial numbers (S/Ns) 9002 through 9763, 9765, 9767 through 9770, and 9998.

Compliance:

Within 500 hours air time or 4 months, whichever occurs first, from the effective date of this AD, unless already accomplished.

Background:

Bombardier reported that during maintenance of a BD-700 aeroplane, the engine mount pin, part number (P/N) BRR15838, was found backed out of the rear mount link. The retaining bolt, P/N AS54020, which passes through the engine mount pin was also found fractured at the groove which holds the locking spring. An investigation revealed the most probable root cause of failure to be a single axial tension static overload, with no evidence of fatigue contributing to the failure.

The above condition if not detected, may result in the loss of engine attachment to the airframe.

Bombardier has issued Service Bulletins (SBs) 700-71-002, 700-71-6002, 700-71-5002 and 700-1A11-71-002 to inspect the attachment points of the links between the engine rear mount assemblies, and installation of replacement hardware if required.

This AD mandates incorporation of the above Bombardier SBs to inspect and maintain integrity of the affected engine rear mount assembly. Bombardier is developing design changes for the parts in question. Further mandatory action may be required when the new parts become available.

Corrective Actions:

Inspect the engine rear mount assemblies and rectify if required, in accordance with the Accomplishment Instructions of the applicable SBs, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada, as shown in the table below:

Aeroplane Model	Bombardier SB	Date
BD-700-1A10	700-71-002, Revision 01	30 June 2016
	700-71-6002, Revision 01	30 June 2016
BD-700-1A11	700-71-5002, Revision 01	30 June 2016
	700-1A11-71-002, Revision 01	30 June 2016

Compliance with the original issue of the above Bombardier SBs, prior to the effective date of this AD, also satisfies the requirements of this AD.

Authorization:

For the Minister of Transport,

ORIGINAL SIGNED BY

Robin Lau
Acting Chief, Continuing Airworthiness
Issued on 28 July 2016

Contact:

Robin Lau, Continuing Airworthiness, Ottawa, telephone 1-888-663-3639, facsimile 613-996-9178 or e-mail AD-CN@tc.gc.ca or any Transport Canada Centre.