

 適航指令發布單 Airworthiness Directive Issuance Form			
民航局 AD 編號 AD number	CAA-2016-09-010	發布日期 Date issued	2016/9/22
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A320-211, A320-212 and A320-231 aeroplanes, manufacturer serial numbers (MSN) up to 0104 inclusive.		
主旨摘要	Wings - Centre Section / Pressurized Floor Fittings at Frame 36 Junction - Inspection / Modification		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%;"> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 50%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	2016-0181	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 57. This AD supersedes EASA AD 2013-0226(CAA-2013-09-011) dated 23 September 2013. Ref. Publications: Airbus SB A320-57-1028 original issue dated 12 August 1991, or Revision 01 dated 19 April 1996, or Revision 02 dated 03 June 2013. and Airbus SB A320-57-1029 original issue dated 12 August 1991, or Revision 01 dated 10 November 1992, or Revision 02 dated 16 June 1999.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2016-0181

Issued: 13 September 2016

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A320 aeroplanes

Effective Date: 27 September 2016

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2013-0226 dated 23 September 2013.

ATA 57 – Wings – Centre Section / Pressurized Floor Fittings at Frame 36 Junction – Inspection / Modification

Manufacturer(s):

Airbus (formerly Airbus Industrie)

Applicability:

Airbus A320-211, A320-212 and A320-231 aeroplanes, manufacturer serial numbers (MSN) up to 0104 inclusive.

Reason:

During centre fuselage certification full scale fatigue testing, damage was found on the pressurized floor fittings at Frame (FR) 36, below the lower surface panel.

This condition, if not detected and corrected, could affect the structural integrity of the aeroplane.

To prevent such damage, Airbus developed modification 21282, which was introduced in production from MSN 0105, to reinforce the pressurized floor fitting lower surface by changing material. For affected in-service aeroplanes, Airbus issued Service Bulletin (SB) A320-57-1028, introducing repetitive inspections, and SB A320-57-1029, which provides modification instructions.



DGAC France issued AD 95-099-067 to require these repetitive inspections and, depending on findings, corrective action(s), while the modification was specified in that AD as optional terminating action for these inspections.

Following new analysis in the frame of Extended Service Goal exercise, the inspection thresholds and intervals were revised to meet the original Design Service Goal. Consequently, EASA issued AD 2013-0226 to retain the requirements of DGAC France AD 95-099-067, which was superseded, but required those actions within reduced compliance times.

Since that AD was issued, in the frame of Widespread Fatigue Damages analysis, the situation has been reassessed and it has been decided to reclassify the modification, still stated as 'optional' terminating action in EASA AD 2013-0226, to the status 'mandatory'.

For the reasons described above, this AD retains the requirements of EASA AD 2013-0226, which is superseded, but requires embodiment of the modification as specified in Airbus SB A320-57-1029.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

- (1) Initially, within the compliance time defined in Table 1 of this AD, as applicable, and, thereafter, at intervals not to exceed 9 300 flight cycles (FC) or 18 600 flight hours (FH), whichever occurs first, accomplish a detailed inspection (DET) of the 6 fittings of the pressurized floor at FR 36, under lower surface panel in accordance with the instructions of Airbus SB A320-57-1028.

Table 1 – Initial Inspection

Compliance Time (whichever occurs later, A , B or C)	
A	Before exceeding 20 900 FC or 41 800 FH, whichever occurs first since aeroplane first flight
B	Within 9 300 FC or 18 600 FH, whichever occurs first since last inspection per Airbus SB A320-57-1028 instructions
C	Within 1 250 FC or 2 500 FH, whichever occurs first after 07 October 2013 [the effective date of EASA AD 2013-0226], without exceeding 12 000 FC since last inspection per Airbus SB A320-57-1028 instructions

- (2) If, during any DET as required by paragraph (1) of this AD, damage is found, before next flight, contact Airbus for approved repair instructions and, within the compliance time specified in these instructions, accomplish the repair accordingly, including any specified follow-on actions, as applicable.
- (3) Before exceeding 48 000 FC or 96 000 FH, whichever occurs first since aeroplane first flight, modify the aeroplane in accordance with the instructions of Airbus SB A320-57-1029.
- (4) Modification of an aeroplane as required by paragraph (3) of this AD constitutes terminating action for the repetitive DET as required by paragraph (1) of this AD for that aeroplane.



Ref. Publications:

Airbus SB A320-57-1028 original issue dated 12 August 1991, or Revision 01 dated 19 April 1996, or Revision 02 dated 03 June 2013.

Airbus SB A320-57-1029 original issue dated 12 August 1991, or Revision 01 dated 10 November 1992, or Revision 02 dated 16 June 1999.

The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 05 July 2016 as PAD 16-099 for consultation until 02 August 2016. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51; E-mail: account.airworth-eas@airbus.com.

