



**適航指令發布單**  
**Airworthiness Directive Issuance Form**

民航局 AD 編號 AD number	CAA-2018-03-003	發布日期 Date issued	2018/3/21
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A350-941 aeroplanes, all manufacturer serial numbers.		
主旨摘要	Flight Controls - Periodic Station Position Pick-Off Unit - Calibration Procedure		
民航局 CAA  <input type="checkbox"/> 本國產品 Native products  <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2018-0058	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 27. Ref. Publications: Airbus SB A350-27-P021 original issue dated 13 February 2018.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： <a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a> Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel:(02)2349-6331~3, Fax:(02)2545-8464, e-mail： <a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a>			



## Airworthiness Directive

**AD No.:** 2018-0058

**Issued:** 14 March 2018

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

### Design Approval Holder's Name:

AIRBUS

### Type/Model designation(s):

A350 aeroplanes

**Effective Date:** 16 March 2018

**TCDS Number(s):** EASA.A.151

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 27 – Flight Controls – Periodic Station Position Pick-Off Unit – Calibration Procedure

### Manufacturer(s):

Airbus

### Applicability:

Airbus A350-941 aeroplanes, all manufacturer serial numbers.

### Definitions:

For the purpose of this AD, the following definitions apply:

**The SB:** Airbus Service Bulletin (SB) A350-27-P021.

### Reason:

Occurrences have been reported by Airbus A350 operators of malfunctions of Station Position Pick-Off Units (SPPU). Investigations indicated that internal wiring failures occurred due to water ingress via certain electrical connectors, inducing subsequent icing during flight.

This condition, if not detected and corrected, could lead to hidden sensor signal drift (at flap station 3) which, in combination with an independent failure of a flap down drive disconnect, might lead to in-flight detachment of the outer flap surface, possibly resulting in damage to the aeroplane, and/or injury to persons on the ground.



Airbus determined that the SPPU calibration test can highlight all hidden faults, but this test is only scheduled after removal/installation of the equipment. Consequently, to address this potential unsafe condition, Airbus issued the SB, providing instructions to accomplish the SPPU calibration test at regular intervals.

For the reason described above, this AD requires repetitive SPPU calibration test and, depending on findings, accomplishment of applicable corrective action(s).

Pending the results of the on-going investigation, this AD is still considered to be an interim measure and further AD action may follow.

#### **Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

#### **Repetitive SPPU calibration test:**

- (1) Within 200 flight cycles (FC) or 30 days, whichever occurs first after the effective date of this AD, and, thereafter, at intervals not to exceed 200 FC, accomplish an SPPU calibration test in accordance with the instructions of the SB.

#### **Corrective Action(s):**

- (2) If, during any test as required by paragraph (1) of this AD, discrepancies are detected, before next flight, accomplish the applicable corrective action(s) in accordance with the instructions of the SB.

#### **Terminating Action:**

- (3) None.

#### **Ref. Publications:**

Airbus SB A350-27-P021 original issue dated 13 February 2018.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

#### **Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. For any question concerning the technical content of the requirements in this AD, please contact AIRBUS XWB – E-mail: [continued-airworthiness.a350@airbus.com](mailto:continued-airworthiness.a350@airbus.com).

