



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2018-06-006	發布日期 Date issued	2018/6/25
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers.		
主旨摘要	Electric and Electronic Common Installation - Cockpit Panel Bracket - Inspection		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <div style="display: flex; justify-content: space-between;"> <div style="width: 48%;"> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 48%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other_____ </div> </div>		
	設計國 AD 編號 Original AD number	2018-0131	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 92. This AD supersedes EASA AD 2015-0170(CAA-2015-08-005) dated 18 August 2015.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2018-0131

Issued: 19 June 2018

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: 03 July 2018

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2015-0170 dated 18 August 2015.

ATA 92 – Electric and Electronic Common Installation – Cockpit Panel Bracket – Inspection

Manufacturer(s):

Airbus (formerly Airbus Industrie)

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

Groups: Group 1 aeroplanes are those in pre modification (mod) 35869 configuration. Group 2 aeroplanes are those in post mod 35869 configuration.

The applicable SB: Airbus Service Bulletin (SB) A320-92-1087 for Group 1 aeroplanes and SB A320-92-1119 for Group 2 aeroplanes.



Reason:

During an unscheduled maintenance operation on an A330 aeroplane, the 10VU rack was removed for access and cracks were discovered on 10VU rack side fittings on lugs 1, 3 and 4. As a similar design is installed on A320 family aeroplanes, a sampling review was done to determine the possible fleet impact. The result showed that several aeroplanes had cracked or broken 10VU rack side fittings.

This condition, if not detected and corrected, could lead to a high vibration level on the primary flight and navigation displays during critical flight phases (take-off and landing), possibly creating reading difficulties for the crew.

Prompted by these findings, Airbus developed mod 35869 to reinforce the affected rack fitting lugs. For in-service aeroplanes, Airbus published SB A320-92-1087 to provide detailed inspection (DET) and repair instructions. Consequently, EASA AD 2015-0170 was issued to require, for all pre mod 35869 aeroplanes, repetitive DET of the affected 10VU rack fitting lugs and, depending on findings, accomplishment of a repair.

Since that AD was issued, analysis confirmed the need to extend the inspection to post mod 35869 aeroplanes. Airbus issued SB A320-92-1119 providing instructions for DET and repair of those aeroplanes accordingly. Airbus developed mod 157335 to further reinforce and adjust the affected rack fitting lugs. Analysis is still ongoing to confirm mod 157335 as terminating action for the requirements of this AD, and further AD action may follow.

For the reason described above, this AD retains the requirements of EASA AD 2015-0170, which is superseded, expanding the Applicability to include post mod 35869 aeroplanes, and requiring, for all aeroplanes, repetitive DET of the affected 10VU rack fitting lugs and, depending on findings, accomplishment of a repair.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspection(s):

- (1) For Group 1 aeroplanes: Within the compliance time defined in Table 1 of this AD, and, thereafter, at intervals not to exceed 20 000 flight cycles (FC) or 40 000 flight hours (FH), whichever occurs first, accomplish a DET of the 10VU lugs 1, 2, 3 and 4 in accordance with the instructions of Airbus SB A320-92-1087.

Table 1 – Initial Inspection

Compliance Time (whichever occurs later, A or B)	
A	Before exceeding 30 000 FC or 60 000 FH, whichever occurs first since aeroplane first flight
B	Within 24 months after 01 September 2015 [the effective date of EASA AD 2015-0170]

- (2) For Group 2 aeroplanes: Before exceeding 30 000 FC or 60 000 FH, whichever occurs first since aeroplane first flight, and, thereafter, at intervals not to exceed 20 000 FC or 40 000 FH,



whichever occurs first, accomplish a DET of the 10VU lugs 1, 2, 3 and 4 in accordance with the instructions of Airbus SB A320-92-1119.

Corrective Action(s):

- (3) If, during any DET as required by paragraph (1) or (2) of this AD, any crack is found on only one 10VU lug, before exceeding 5 000 FC or 10 000 FH, or within 24 months, whichever occurs first, repair the damaged lug in accordance with the instructions of the applicable SB (see Note 1 of this AD).
- (4) If, during any DET as required by paragraph (1) or (2) of this AD, any crack is found on two or more lugs, before next flight, repair the damaged lugs in accordance with the instructions of the applicable SB (see Note 1 of this AD).

Note 1: Depending on aeroplane configuration, removal, installation and testing of some equipment is not required to accomplish the repair as required by paragraph (3) or (4) of this AD, as applicable, for that aeroplane.

Terminating Action:

- (5) Accomplishment of corrective action(s) on an aeroplane, as required by paragraph (3) or (4) of this AD, as applicable, does not constitute terminating action for the repetitive inspections as required by paragraphs (1) or (2) of this AD, as applicable, for that aeroplane.

Reporting:

- (6) Within 90 days after each DET as required by paragraph (1) or (2) of this AD, as applicable, report the results (including no findings) to Airbus.

Ref. Publications:

Airbus SB A320-92-1087 original issue dated 28 March 2011, or Revision 01 dated 17 May 2011, or Revision 02 dated 25 November 2014, or Revision 03 dated 31 July 2017.

Airbus SB A320-92-1119 original issue dated 28 July 2017.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

- 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
- 2. This AD was posted on 04 April 2018 as PAD 18-048 for consultation until 02 May 2018. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
- 3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.



4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51;
E-mail: account.airworth-eas@airbus.com.

