



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2018-07-003	發布日期 Date issued	2018/7/12
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	To The Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017.		
主旨摘要	Boeing Material Specification (BMS) 8-39 flexible urethane foam/Inspection		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input checked="" type="checkbox"/> FAA <input type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2018-14-02	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 25. Reference: Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017.		

註：
 1. AD 內容後附。
 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw

Note：
 1. The AD text is enclosed.
 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw

[Federal Register Volume 83, Number 131 (Monday, July 9, 2018)]

[Rules and Regulations]

[Pages 31650-31653]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2018-14499]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0115; Product Identifier 2017-NM-110-AD; Amendment 39-19322; AD 2018-14-02]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes. This AD was prompted by reports that additional areas of Boeing Material Specification (BMS) 8-39 flexible urethane foam were found during a routine inspection. This AD requires an inspection for foam insulation on the dripshield above the overhead panel support structure and replacement if necessary. For certain airplanes, this AD also requires replacement of foam insulation on the overhead panel support structure. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 13, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 13, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0115.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0115; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the

regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Scott Craig, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3566; email: Michael.S.Craig@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes. The NPRM published in the Federal Register on February 26, 2018 (83 FR 8199). The NPRM was prompted by reports that additional areas of BMS 8-39 flexible urethane foam were found during a routine inspection. The NPRM proposed to require an inspection for foam insulation on the dripshield above the overhead panel support structure and replacement if necessary. For certain airplanes, the NPRM also proposed to require replacement of foam insulation on the overhead panel support structure.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment. Boeing and United Airlines stated that they supported the NPRM.

Request To Correct a Typo in the Service Information

Delta Airlines (DAL) requested that we correct a typo in Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017. DAL stated that during its review of Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017, it found a typo in the instructions in step 4 of figures 1 and 3 in the "More Data" column. DAL stated that the instructions refer to Aircraft Maintenance Manual (AMM) chapter "777 AMM 23-92-02," but the correct chapter should be "777 AMM 23-93-02."

We agree with the commenter that there is a typo in Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017. The correct reference should be "777 AMM 23-93-02." However, the typo is not in an "RC" (required for compliance) step in Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017, and the AMM is provided only as a reference in Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017. Therefore, we have not changed this AD in this regard.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017. This service information describes procedures for a general visual inspection for foam insulation on the dripshield above the overhead panel support structure and replacement if necessary. This service information also describes procedures for replacement of foam insulation on the overhead panel support structure. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

We estimate that this AD affects 132 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

Estimated Costs				
Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection and replacement of foam insulation	Up to 32 work-hours × \$85 per hour = \$2,720	\$5,611	Up to \$8,331	Up to \$1,099,692

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):



2018-14-02 The Boeing Company: Amendment 39-19322; Docket No. FAA-2018-0115; Product Identifier 2017-NM-110-AD.

(a) Effective Date

This AD is effective August 13, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by reports that additional areas of Boeing Material Specification (BMS) 8-39 flexible urethane foam were found during a routine inspection pursuant to a previously issued AD. The degradation of the foam over time increases the potential for an uncontrolled fire below the passenger compartment floor and other locations outside the areas covered by smoke detection and fire protection systems. We are issuing this AD to address BMS 8-39 flexible urethane foam found in certain areas of an airplane, which, if exposed to an ignition source, could cause loss of control of the airplane during a fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Replacement of Foam Installation

Except as required by paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017.

(h) Exception to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD.”

(i) Credit for Previous Actions

This paragraph provides credit for the corresponding actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 777-25-0621, dated December 10, 2014.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as RC, the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Scott Craig, Aerospace Engineer, Cabin Safety and Environmental Systems Section, Seattle ACO Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3566; email: Michael.S.Craig@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 777-25-0621, Revision 1, dated August 4, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 27, 2018.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.