



**適航指令發布單**  
**Airworthiness Directive Issuance Form**

民航局 AD 編號 AD number	CAA-2018-11-005A	發布日期 Date issued	2018/12/9												
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Applicability: Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers.														
主旨摘要	Oxygen – Crew Oxygen Cylinder Assembly – Operational Check / Replacement														
民航局 CAA <input type="checkbox"/> 本國產品 Native products  <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <table border="0" style="width: 100%;"><tr><td><input type="checkbox"/> FAA</td><td><input type="checkbox"/> Germany LBA</td></tr><tr><td><input checked="" type="checkbox"/> EASA</td><td><input type="checkbox"/> CAA-NL</td></tr><tr><td><input type="checkbox"/> Brazil</td><td><input type="checkbox"/> UK CAA</td></tr><tr><td><input type="checkbox"/> Transport Canada Civil Aviation</td><td><input type="checkbox"/> Japan CAB</td></tr><tr><td><input type="checkbox"/> DGAC</td><td><input type="checkbox"/> CAA of Israel</td></tr><tr><td></td><td><input type="checkbox"/> Other _____</td></tr></table>			<input type="checkbox"/> FAA	<input type="checkbox"/> Germany LBA	<input checked="" type="checkbox"/> EASA	<input type="checkbox"/> CAA-NL	<input type="checkbox"/> Brazil	<input type="checkbox"/> UK CAA	<input type="checkbox"/> Transport Canada Civil Aviation	<input type="checkbox"/> Japan CAB	<input type="checkbox"/> DGAC	<input type="checkbox"/> CAA of Israel		<input type="checkbox"/> Other _____
<input type="checkbox"/> FAA	<input type="checkbox"/> Germany LBA														
<input checked="" type="checkbox"/> EASA	<input type="checkbox"/> CAA-NL														
<input type="checkbox"/> Brazil	<input type="checkbox"/> UK CAA														
<input type="checkbox"/> Transport Canada Civil Aviation	<input type="checkbox"/> Japan CAB														
<input type="checkbox"/> DGAC	<input type="checkbox"/> CAA of Israel														
	<input type="checkbox"/> Other _____														
	設計國 AD 編號 Original AD number	2018-0245R1													
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____														
	2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)														
備註 Note	ATA 35. This AD revises EASA AD 2018-0245(CAA-2018-11-005) dated 13 November 2018. Ref. Publications: Airbus AOT A35P010-17 original issue dated 20 December 2017. and Airbus SB A350-35-P012 original issue dated 12 July 2018.														
<p>註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：<a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a></p> <p>Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail：<a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a></p>															



## Airworthiness Directive

**AD No.:** 2018-0245R1

**Issued:** 05 December 2018

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

**Design Approval Holder's Name:**

AIRBUS

**Type/Model designation(s):**

A350 aeroplanes

**Effective Date:** Revision 1: 12 December 2018  
Original Issue: 27 November 2018

**TCDS Number(s):** EASA.A.151

**Foreign AD:** Not applicable

**Revision:** This AD revises EASA AD 2018-0245 dated 13 November 2018.

### ATA 35 – Oxygen – Crew Oxygen Cylinder Assembly – Operational Check / Replacement

**Manufacturer(s):**

Airbus

**Applicability:**

Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers.

**Definitions:**

For the purpose of this AD, the following definitions apply:

**The AOT:** Airbus Alert Operators Transmission (AOT) A35P010-17.

**The SB:** Airbus Service Bulletin (SB) A350-35-P012.

**Affected assembly:** Oxygen cylinder assemblies, having Part Number (P/N) 4441227-058-000.

**Serviceable assembly:** Oxygen cylinder assemblies, having P/N 4441227-058-001.

**Groups:** Group 1 aeroplanes are those that have an affected assembly installed. Group 2 aeroplanes are those that do not have an affected assembly installed.



**Reason:**

Several occurrences were reported of loss of retention of the regulator inlet filter retainer on affected assemblies. The filter retainer detached from the regulator and dropped within the cylinder internal volume. The technical investigation identified a design defect which was the cause of these events.

This condition, if not detected and corrected, could lead to particle ingestion into the regulator during ground handling, possibly resulting in ignition / fire during system ground operational testing following cylinder (re)installation on an aeroplane.

To address this potential unsafe condition, Airbus issued the AOT to provide instructions for an operational check (OPC). Airbus also developed an improved oxygen cylinder assembly and issued the SB accordingly, to provide replacement instructions.

For the reasons described above, EASA issued AD 2018-0245 to require a one-time OPC of each affected assembly and, depending on findings, replacement. This AD also requires replacement of all affected assemblies with improved serviceable assemblies.

Prompted by operator requests for clarification after that AD was issued, this AD is revised to introduce a new definition for 'Groups' of aeroplanes affected by this AD, amending the AD accordingly to reflect the intended requirements for each Group.

**Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

**Inspection(s):**

- (1) For Group 1 aeroplanes: Within 6 months after 27 November 2018 [the effective date of the original issue of this AD], accomplish an OPC of each affected assembly in accordance with the instructions of the AOT.

**Corrective Action(s):**

- (2) If, during the OPC as required by paragraph (1) of this AD, any discrepancy is detected on an affected assembly, before next flight, replace that affected assembly in accordance with the instructions of the AOT.

**Replacement:**

- (3) For Group 1 aeroplanes: Unless already accomplished as required by paragraph (2) of this AD, within 18 months after 27 November 2018 [the effective date of the original issue of this AD], replace each affected assembly with a serviceable assembly in accordance with the instructions of the SB.

**Part(s) Installation:**

- (4) From 27 November 2018 [the effective date of the original issue of this AD], until aeroplane modification as required by paragraph (3) of this AD, installation on a Group 1 aeroplane of an affected assembly is allowed, provided that, prior to installation, it has passed (no discrepancies found) an OPC in accordance with the instructions of the AOT.



- (5) Do not install an affected assembly on any aeroplane, as required by paragraph (5.1) or (5.2) of this AD, as applicable.
- (5.1) For Group 1 aeroplanes: After modification of the aeroplane as required by paragraph (3) of this AD.
- (5.2) For Group 2 aeroplanes: From 27 November 2018 [the effective date of the original issue of this AD].

#### Ref. Publications:

Airbus AOT A35P010-17 original issue dated 20 December 2017.

Airbus SB A350-35-P012 original issue dated 12 July 2018.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

#### Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The original issue of this AD was posted on 02 October 2018 as PAD 18-134 for consultation until 30 October 2018. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS XWB, E-mail: [continued-airworthiness.a350@airbus.com](mailto:continued-airworthiness.a350@airbus.com).

