# 適航指令發布單

# **Airworthiness Directive Issuance Form**

	THE WOLLHINGS DI	- Issuance			
民航局 AD 編號 AD number	CAA-2019-04-009	發布日期 Date issued	2019/4/30		
適用之航空產品 Applied to (models numbers or part nu as applicable)	A330-343 aeroplane 01761 to 01768 inc 01778, 01780, 01781 mbers, 01794 inclusive, 0179	01794 inclusive, 01796 to 01798 inclusive, 01800, 01802, 01803, 01812, 01815, 01817, 01820, 01821, 01823, 01825, 01826, 01828, 01829,			
主旨摘要	Flight Controls – Replacement	Slat Geared Rotary	Actuators - Repair /		
民航局 設計國民航主管機構			· 機構		
CAA		Original Authorities			
□本國產品	□FAA	□Ge	ermany LBA		
Native products	EASA	$\Box$ CA	AA-NL		
_	□Brazil	□UF	K CAA		
□其他個案	Transport Canada Ci	ivil Aviation	pan CAB		
Other	DGAC		AA of Israel		
		<del></del>	her		
	設計國 AD 編號 Original AD numbe	2019-	-0093		
	■是(Yes) □ 否 a	<ol> <li>直接採用原 AD 之內容?(Is the original AD directly adopted?)         ■是(Yes) □否(No) _</li></ol>			
time or period as):					
	2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do				
Users need to report the status of compliance to the CAA?  □是(Yes) ■否(No)					
	ATA 27. Ref. Publi	cations: Airbus SB	A330-27-3233 original		
備註	issue dated 07 Marc	issue dated 07 March 2019. and Airbus RIL G27M18007640			
Note					
	original issue dated	18 December 2018			
3. 如有任何 adcaa@ma	品使用人得向民航局提出豁免、替代問題,請聯絡交通部民用航空局初始 ail.caa.gov.tw				
<ol> <li>Exemption approval.</li> </ol>	_		nce time may be proposed to the CAA for		
3. For further information, please contact Civil Aeronautics Administration on Tel: (02)2349-6331~3, Fax: (02)2545-8464					

e-mail: adcaa@mail.caa.gov.tw
CAA Form ACS-P08-02

第一頁/共一頁

EASA AD No.: 2019-0093



# **Airworthiness Directive**

AD No.: 2019-0093

**Issued: 26 April 2019** 

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

# Design Approval Holder's Name: Type/Model designation(s):

AIRBUS A330 aeroplanes

Effective Date: 10 May 2019

TCDS Number(s): EASA.A.004

Foreign AD: Not applicable

Supersedure: None

ATA 27 - Flight Controls - Slat Geared Rotary Actuators - Repair / Replacement

### Manufacturer(s):

Airbus

#### **Applicability:**

Airbus A330-202, A330-243, A330-243F, A330-302, A330-323 and A330-343 aeroplanes, manufacturer serial numbers (MSN) 01758, 01761 to 01768 inclusive, 01770 to 01773 inclusive, 01775, 01777, 01778, 01780, 01781, 01783, 01784, 01786 to 01789 inclusive, 01791 to 01794 inclusive, 01796 to 01798 inclusive, 01800, 01802, 01803, 01812, 01815, 01817, 01820, 01821, 01823, 01825, 01826, 01828, 01829, 01831 and 01834.

#### **Definitions:**

For the purpose of this AD, the following definitions apply:

The SB: Airbus Service Bulletin (SB) A330-27-3233.

**The RIL:** Airbus Retrofit Information Letter (RIL) G27M18007640.

The Liebherr SB: Liebherr-Aerospace Lindenberg GmbH (Liebherr) SB 926C-27-01.



EASA AD No.: 2019-0093

**Affected part**: Slat geared rotary actuators (SGRA), having Part Number (P/N) 926C0000-01 and serial number (s/n) as identified in the SB, except those that have passed an inspection, or have been repaired, as applicable, in accordance with the instructions of the Liebherr SB.

**Serviceable part:** An SGRA that is not an affected part.

#### Reason:

Cracks have been found within the ring gears of an SGRA. Investigation identified that this is due to a change in the manufacturing process of the 300M steel raw material in conjunction with inadequate post-production non-destructive testing for potential cracks. A batch of SGRA has been identified as having been subject to this manufacturing process.

This condition, if not detected and corrected, could, in combination with an independent failure on the second SGRA of the same slat surface, lead to an uncontrolled movement of the affected slat surface in flight, or detachment of the slat surface, possibly resulting in damage to the stabilizers, or reduced control of the aeroplane.

To address this potential unsafe condition, Airbus issued the SB to provide instructions to replace the affected parts, referencing the Liebherr SB for in-shop correction.

For the reasons described above, this AD requires replacement of each affected part with a serviceable part.

### Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

#### **Identification/Reporting:**

(1) Within 6 months after the effective date of this AD, for each aeroplane MSN, identify the associated affected parts as specified in the SB and report any mismatch to Airbus. The P/N and s/n identification of each affected part on an aeroplane is sufficient. The Functional Item Number (FIN) as specified in Appendix 01 of the SB is for information only as it cannot be excluded that an affected part may have finally been installed in production at another location on the same aeroplane.

This action can be accomplished on the aeroplane by checking the P/N and s/n of the SGRA installed, or by reviewing aeroplane maintenance records to make this determination, provided those records can be relied upon for that purpose and the P/N and s/n of the suspected parts can be positively identified from that review.

#### Replacement:

(2) Following the actions as required by paragraph (1) of this AD, within 20 000 flight hours after the effective date of this AD, replace each affected part with a serviceable part in accordance with the instructions of the SB.



EASA AD No.: 2019-0093

## Reporting:

(3) Within 30 days after replacement of all affected parts on an aeroplane, as required by paragraph (2) of this AD, report that action to Airbus. That action can be accomplished by using the instructions and reporting forms of the SB or the RIL.

#### **Ref. Publications:**

Airbus SB A330-27-3233 original issue dated 07 March 2019.

Airbus RIL G27M18007640 original issue dated 15 March 2019.

Liebherr SB 926C-27-01 original issue dated 18 December 2018.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

#### **Remarks:**

- If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
- 2. This AD was posted on 04 April 2019 as PAD 19-058 for consultation until 18 April 2019. No comments were received during the consultation period.
- 3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: <a href="mailto:ADs@easa.europa.eu">ADs@easa.europa.eu</a>.
- 4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the <a href="EU aviation safety">EU aviation safety reporting system</a>.
- 5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS EIAL (Airworthiness Office), E-mail: airworthiness.A330-A340@airbus.com.

