



適航指令發布單
Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2019-06-006	發布日期 Date issued	2019/6/17
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A330-941 aeroplanes, all manufacturer serial numbers.		
主旨摘要	Oxygen - Chemical Oxygen Generators - Replacement		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2019-0140	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 35. Ref. Publications: Airbus A330 MRBR Revision 17 dated August 2018.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2019-0140

Issued: 12 June 2019

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A330 aeroplanes

Effective Date: 26 June 2019

TCDS Numbers: EASA.A.004

Foreign AD: Not applicable

Supersedure: None

ATA 35 – Oxygen – Chemical Oxygen Generators – Replacement

Manufacturer(s):

Airbus

Applicability:

Airbus A330-941 aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The MRBR task: Airbus Maintenance Review Board Report (MRBR) task 35.20.01/05.

Affected Part: Collins Aerospace (formerly B/E Aerospace) chemical oxygen generators, having Part Number (P/N) 117042-XX, where XX represents any numerical value.

Serviceable Part: An affected part that has accumulated less than 10 years since its date of manufacture.

Reason:

Reports have been received indicating premature ageing of affected parts.

This condition, if not corrected, could lead to failure of the generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to aeroplane occupants.



To address this unsafe condition, Airbus issued the MRBR tasks to provide the necessary replacement instructions.

For the reasons described above, this AD requires removal from service of each affected part before exceeding 10 years since its date of manufacture.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Removal from service:

- (1) Before an affected part exceeds 10 years since its date of manufacture, remove that affected part from service, and replace it with a serviceable part. This can be accomplished by using the instructions of the MRBR task.

Part Installation:

- (2) From the effective date of this AD, it is allowed to install on any aeroplane an affected part, provided it is determined, prior to installation, that it is a serviceable part, as defined in this AD, and that, following installation, it is replaced as required by paragraph (1) of this AD.

Ref. Publications:

Airbus A330 MRBR Revision 17 dated August 2018.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 07 March 2019 as PAD 19-035 for consultation until 04 April 2019. The Comment Response Documents can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EIAL, E-mail: airworthiness.A330-A340@airbus.com.

