



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2020-07-011	發布日期 Date issued	2020/7/31
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A350-941 aeroplanes, all manufacturer serial numbers, except aeroplanes that have embodied Airbus modification (mod) 113749 and mod 112250 in production.		
主旨摘要	Flight Control and Guidance System - Ram Air Turbine Performance - Modification (Software Update) and Air Conditioning - Electrical Power Supply to Air Generation System Ram Air Actuators - Modification		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <div style="display: flex; justify-content: space-between;"> <div style="width: 48%;"> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 48%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	2020-0167	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	This AD supersedes EASA AD 2019-0203(CAA-2019-08-007) dated 20 August 2019.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2020-0167

Issued: 27 July 2020

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A350 aeroplanes

Effective Date: 10 August 2020

TCDS Number(s): EASA.A.151

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2019-0203 dated 20 August 2019.

ATA 42 – Flight Control and Guidance System – Ram Air Turbine Performance – Modification (Software Update)

ATA 21 – Air Conditioning – Electrical Power Supply to Air Generation System Ram Air Actuators – Modification

Manufacturer(s):

Airbus

Applicability:

Airbus A350-941 aeroplanes, all manufacturer serial numbers, except aeroplanes that have embodied Airbus modification (mod) 113749 and mod 112250 in production.

Definitions:

For the purpose of this AD, the following definitions apply:

The ATA 42 SB: Airbus Service Bulletin (SB) A350-42-P012.

The ATA 21 SB: Airbus SB A350-21-P038.

Airbus date of manufacture: The date of transfer of title (ownership) which is referenced in Airbus documentation at the time of first delivery to an operator.



Groups:

Group 1 aeroplanes are those that do not have Airbus mod 113749 embodied in production, except those that have embodied the ATA 42 SB in service.

Group 2 aeroplanes are those that do not have Airbus mod 112250 embodied in production, except those that have embodied the ATA 21 SB in service.

Reason:

It has been determined through testing that ram air turbine (RAT) performance may be below the expected (certified) level, when the landing gear is extended.

This condition, if not corrected, could lead to partial or total loss of RAT electrical power generation, when RAT is deployed in an emergency condition, possibly resulting in reduced control of the aeroplane.

To initially address this potential unsafe condition, Airbus issued the ATA 42 SB, providing instructions to install flight control and guidance system (FCGS) software (SW) X11 Standard (STD) to limit aeroplane side slip and guarantee RAT electrical power generation performance in case of total engine flame out, or during a total loss of normal electrical power generation. Consequently, EASA issued AD 2019-0203 to require installation of FCGS SW X11 STD.

Since that AD was issued, in order to force the Air Generation System (AGS) ram air outlet doors #2 to be flush in case of total engine flame out or loss of main electrical supply, Airbus developed mod 112250 to modify the electrical power supply of AGS ram air outlet actuator, and published the ATA 21 SB to provide in-service modification instructions.

For the reasons described above, this AD retains the requirements of EASA AD AD 2019-0203, which is superseded, and additionally requires modification of the electrical power supply of the AGS ram air outlet door actuators.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Modification:

- (1) For Group 1 aeroplanes: Within 10 months after 03 September 2019 [the effective date of EASA AD 2019-0203], modify the aeroplane by installing FCGS SW X11 STD in accordance with the instructions of the ATA 42 SB.
- (2) For Group 2 aeroplanes: Before exceeding 6 years since aeroplane date of manufacture, modify the electrical power supply of AGS ram air outlet door actuators from Electrical Power Distribution Center (EPDC) norm bus 24VDC to Circuit Breaker Panel (CBP) emergency bus 24VDC in accordance with the instructions of the ATA 21 SB.

Ref. Publications:

Airbus SB A350-42-P012 original issue dated 26 June 2019.

Airbus SB A350-21-P038 original issue dated 24 April 2020.



The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 30 June 2020 as PAD 20-101 for consultation until 14 July 2020. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS XWB, E-mail: continued-airworthiness.a350@airbus.com.

