COURS.
0.664
100000

適航指令發布單

Airworthiness Directive Issuance Form

	Airwortilliess Dire	ective issuance Fo	r III
民航局 AD 編號 AD number	CAA-2021-07-004	發布日期 Date issued	2021/7/22
適用之航空產品 Applied to (models, seria numbers or part numbers as applicable)		ent 7000-72C engines	, all serial numbers.
主旨摘要	Engine - High Pressure Turbine Blades - Inspection		
民航局 CAA □本國產品 Native products □其他個案 Other	■是(Yes) □否(a. b. □ 2. 使用人是否需要	□CAA-] □UK CA □UK CA □UK CA □I Aviation □Japan □CAA (□Other_ 2021-016 ≥內容?(Is the original (No) _ 生效日期另訂為(Rodate as): 執行時限另訂為(Rotime or period as): 將 AD 執行結果向民; ort the status of comp	suny LBA NL AA CAB of Israel 69 I AD directly adopted?) e-specify the effective □ e-specify the compliance fi 局提出報告?(Do □
備註 Note			lert NMSB TRENT mber 2019, or Revision
3. 如有任何問題, adcaa@mail.caa. Note: 1. The AD text is en 2. Exemption, an all approval.	iclosed. ternative method of compliance or nation, please contact Civil Aerona	蔥航科。Tel:(02)2349-6331~3 adjustment of the compliance tir	

CAA Form ACS-P08-02

第一頁/共一頁



Airworthiness Directive

AD No.: 2021-0169

Issued: 19 July 2021

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

Type/Model designation(s):

ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG

Trent 7000 engines

Effective Date: 02 August 2021

TCDS Number(s): EASA.E.036

Foreign AD: Not applicable

Supersedure: None

ATA 72 - Engine - High Pressure Turbine Blades - Inspection

Manufacturer(s):

Rolls-Royce plc

Applicability:

Trent 7000-72 and Trent 7000-72C engines, all serial numbers.

These engines are known to be installed on, but not limited to, Airbus A330 (NEO) aeroplanes.

Definitions:

For the purpose of this AD, the following definitions apply:

The NMSB: Rolls-Royce Alert Non-Modification Service Bulletin (NMSB) TRENT 1000 72-AK449 Revision 2. The NMSB has an 'A' (Alert) in the number, but an earlier or later revision may not have that 'A'. This kind of change does not effectively alter the publication references.

Affected part: High pressure turbine (HPT) blades, having Part Number (P/N) KH64485.

Serviceable part: An affected part which is new (not previously installed).



Reason:

In-service experience has shown that the affected parts may deteriorate, despite being subject to piece-part level inspections as specified in the current Rolls-Royce Trent 7000 Time Limits Manual, TLM T-T7000-1RR, Revision 9, Chapter 05-20.

This condition, if not detected and corrected, could lead to HPT blade failure, possibly resulting in engine in-flight shut-down (IFSD) and consequent reduced control of the aeroplane.

To address this potential unsafe condition, Rolls-Royce determined a flight cycle (FC) threshold and an on-wing borescope inspection method, and issued the NMSB accordingly.

For the reasons described above, this AD requires initial and repetitive inspections of the affected parts to detect axial cracking and, depending on findings, removal from service of the engine for in-shop replacement of the affected parts. This AD also requires implementation of a reduced life limit for the affected parts.

This AD is considered to be an interim action and further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspection(s):

(1) Before exceeding the compliance time as specified in Table 1 of this AD, as applicable, accomplish an on-wing borescope inspection of all affected parts in accordance with the instructions of Section 3.A of the NMSB.

Table 1 – Inspection Threshold(s) (see Note 1 of this AD)

FC Accumulated	Compliance Time
Less than 475 FC	Before exceeding 500 FC
475 FC or more	Within 25 FC the effective date of this AD

Note 1: Unless indicated otherwise, the FC specified in Table 1 and Table 2 of this AD are those accumulated by the engine since first flight, or since last in-service HPT blade set replacement, as applicable.

(2) Within the compliance time as specified in Table 2 of this AD, as applicable, and, thereafter, at intervals not to exceed 50 FC, accomplish an on-wing borescope inspection of all affected parts in accordance with the instructions of Section 3.A of the NMSB.

Table 2 – First Repeat Inspection Threshold(s) (see Note 1 of this AD)

FC Accumulated	Compliance Time
Less than 725 FC	Before exceeding 750 FC
725 FC or more	Within 25 FC the effective date of this AD



(3) From the effective date of this AD, before next flight after IFSD of an engine on an aeroplane, if the accumulated life of the affected parts installed on the not-affected (no IFSD) engine of that aeroplane have exceeded 450 FC, accomplish an on-wing borescope inspection of all affected parts on that not-affected (no IFSD) engine in accordance with the instructions of Section 3.A of the NMSB.

Corrective Action(s):

(4) If, during any inspection as required by paragraph (1), (2) or (3) of this AD, as applicable, any crack indication (as specified in the NMSB) is found, within the compliance time specified in Table 3 of this AD, as applicable, remove the engine from service and, before release to service of that engine, replace the affected parts with a full set of serviceable parts, as defined in this AD.

Affected Part Finding(s)

Cracks exceeding 4 mm (0.16 inch) in length

Before next flight

Within 10 FC or 60 flight hours, whichever occurs first after the inspection detecting crack(s)

Table 3 - Engine Removal from Service

Life Limitation:

(5) Before the affected parts on an engine exceed 1 000 FC since new (first installation on an engine), remove the engine from service and, before release to service of that engine, replace the affected parts with a full set of serviceable parts, as defined in this AD.

Note 2: The HPT blade life limit as required by paragraph (5) of this AD cancels the inspection intervals as currently defined in the TLM.

Credit:

(6) Inspection(s) and corrective action(s) on an engine, accomplished before the effective date of this AD in accordance with the instructions of Rolls-Royce Alert NMSB TRENT 1000 72-AK449 at Revision 1, are acceptable to comply with the initial requirements of paragraphs (1), (2) and (3) of this AD, as applicable, for that engine.

Terminating Action:

(7) None.

Ref. Publications:

Rolls-Royce Alert NMSB TRENT 1000 72-AK449 Revision 1 dated 12 December 2019, or Revision 2 dated 05 July 2021.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.



Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.

- 2. This AD was posted on 14 June 2021 as PAD 21-085 for consultation until 12 July 2021. The Comment Response Document can be found in the <u>EASA Safety Publications Tool</u>, in the compressed (zipped) file attached to the record for this AD.
- 3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
- 4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the <u>EU aviation safety reporting system</u>. This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
- 5. For any question concerning the technical content of the requirements in this AD, please contact your designated Rolls-Royce representative, or download the publication from your Rolls Royce Care account at https://customers.rolls-royce.com.

If you do not have a designated representative or Rolls Royce Care account, please contact **Corporate Communications** at **Rolls-Royce plc**, P.O. Box 31, Derby, DE24 8BJ, United Kingdom Telephone +44 (0)1332 242424,

or send an email through https://www.rolls-royce.com/contact-us/civil-aerospace.aspx identifying the correspondence as being related to **Airworthiness Directives**.

