



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2022-02-004	發布日期 Date issued	2022/2/11
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	IAE V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2531-E5, and V2533-A5 model turbofan engines with an installed: (1) High-pressure turbine 1st-stage disk, part number 2A5001, with a serial number listed in Appendix A, Table 1, of IAE Non-Modification Service Bulletin No. V2500-ENG-72-0713, Revision 1, dated January 26, 2021 (IAE NMSB V2500-ENG-72-0713, Revision 1) or IAE NMSB No. V2500-E5-72-0015, Revision 1, dated August 10, 2021 (IAE NMSB V2500-E5-72-0015, Revision 1); or (2) HPT 2nd-stage disk, P/N 2A4802, with an S/N listed in Appendix A, Table 2, of IAE NMSB V2500-ENG-72-0713, Revision 1, or IAE NMSB V2500-E5-72-0015, Revision 1.		
主旨摘要 Subject	This AD requires performance of a USI of the HPT 1st-stage disk and HPT 2nd-stage disk and, depending on the results of the inspections, replacement of the HPT 1st-stage disk or HPT 2nd-stage disk.		
民航局 CAA <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authority		
	<input checked="" type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input type="checkbox"/> UK CAA <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2022-02-09	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	This AD replaces AD 2021-11-15(CAA-2021-06-004) Ref. IAE Non-Modification Service Bulletin No. V2500-E5-72-0015, Revision 1, dated August 10, 2021. and IAE No. V2500-ENG-72-0713, Revision 1, dated January 26, 2021.		
註： <ol style="list-style-type: none"> 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail：adcaa@mail.caa.gov.tw 			

Note : 1. The AD text is enclosed.
2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aeronautics Administration on Tel : (02)2349-6330 / 6332, Fax : (02)2545-8464, e-mail : adcaa@mail.caa.gov.tw

CAA Form ACS-P08-02

第一頁/共一頁

[Federal Register Volume 87, Number 26 (Tuesday, February 8, 2022)]

[Rules and Regulations]

[Pages 7029-7033]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2022-02574]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0835; Project Identifier AD-2021-00971-E; Amendment 39-21906; AD 2022-02-09]

RIN 2120-AA64

Airworthiness Directives; International Aero Engines AG Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2021-11-15 for certain International Aero Engines AG (IAE) V2500 model turbofan engines. AD 2021-11-15 required performance of an ultrasonic inspection (USI) of the high-pressure turbine (HPT) 1st-stage disk and HPT 2nd-stage disk and, depending on the results of the inspections, replacement of the HPT 1st-stage disk or HPT 2nd-stage disk. Since the FAA issued AD 2021-11-15, the FAA determined the need to clarify the compliance time for inspection of any HPT 1st-stage disk or HPT 2nd-stage disk that is installed on a low-thrust model engine but had been previously operated on a high-thrust model engine. This AD requires performance of a USI of the HPT 1st-stage disk and HPT 2nd-stage disk and, depending on the results of the inspections, replacement of the HPT 1st-stage disk or HPT 2nd-stage disk. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 15, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 15, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of July 13, 2021 (86 FR 30380, June 8, 2021).

ADDRESSES: For service information identified in this final rule, contact International Aero Engines AG, 400 Main Street, East Hartford, CT 06118; phone: (800) 565-0140; email: help24@prattwhitney.com; website: <https://connect.p PrattWhitney.com>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0835.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0835; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Alberto Hernandez, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7329; fax: (781) 238-7199; email: Alberto.J.Hernandez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2021-11-15, Amendment 39-21577 (86 FR 30380, June 8, 2021), (AD 2021-11-15). AD 2021-11-15 applied to all IAE V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2531-E5, and V2533-A5 model turbofan engines with a certain HPT 1st-stage disk or HPT 2nd stage disk installed. The NPRM published in the Federal Register on October 28, 2021 (86 FR 59658). The NPRM was prompted by the FAA determining the need to clarify the compliance time for inspection of any HPT 1st-stage disk or HPT 2nd-stage disk that is installed on a V2500 low-thrust model engine but that had been previously operated on a V2500 high-thrust model engine. The manufacturer categorizes V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines as high-thrust model engines and V2522-A5, V2524-A5, V2525-D5, and V2527-A model turbofan engines as low-thrust model engines. The FAA determined that any HPT 1st-stage disk and HPT 2nd-stage disk that was operated on a high-thrust model engine must follow shortened compliance thresholds. In the NPRM, the FAA proposed to require the performance of a USI of the HPT 1st-stage disk and HPT 2nd-stage disk and, depending on the results of the inspections, replacement of the HPT 1st-stage disk or HPT 2nd-stage disk.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from two commenters. Commenters included Air Line Pilots Association, International and United Airlines Engineering. All commenters supported the NPRM without change.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting the AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

The FAA reviewed IAE Non-Modification Service Bulletin (NMSB) No. V2500-ENG-72-0713, Revision 1, dated January 26, 2021. This NMSB identifies the affected HPT 1st-stage disks and HPT

2nd-stage disks on IAE V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines and specifies procedures for a USI of the HPT 1st-stage disk and HPT 2nd-stage disk. The Director of the Federal Register approved IAE NMSB V2500-ENG-72-0713, Revision 1, dated January 26, 2021 for incorporation by reference as of July 13, 2021 (86 FR 30380, June 8, 2021).

The FAA also reviewed IAE NMSB No. V2500-E5-72-0015, Revision 1, dated August 10, 2021. This NMSB identifies the affected HPT 1st-stage disks and HPT 2nd-stage disks on IAE V2531-E5 model turbofan engines and specifies procedures for a USI of the HPT 1st-stage disk and HPT 2nd-stage disk.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in ADDRESSES.

Costs of Compliance

The FAA estimates that this AD affects 1,100 engines installed on airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
USI the HPT 1st-stage disk and HPT 2nd-stage disk	20 work-hours × \$85 per hour = \$1,700	\$0	\$1,700	\$1,870,000

The FAA estimates the following costs to do any necessary replacement that is required based on the results of the inspection. The agency has no way of determining the number of aircraft that might need this replacement:

On-Condition Costs

Action	Labor cost	Parts cost	Cost per product
Replace the HPT 1st-stage disk or HPT 2nd-stage disk	0 work-hours × \$85 per hour = \$0	\$300,000	\$300,000

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by:

- a. Removing Airworthiness Directive 2021-11-15, Amendment 39-21577 (86 FR 30380, June 8, 2021); and
- b. Adding the following new airworthiness directive:



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2022-02-09 International Aero Engines AG: Amendment 39-21906; Docket No. FAA-2021-0835; Project Identifier AD-2021-00971-E.

(a) Effective Date

This airworthiness directive (AD) is effective March 15, 2022.

(b) Affected ADs

This AD replaces AD 2021-11-15, Amendment 39-21577 (86 FR 30380, June 8, 2021) (AD 2021-11-15).

(c) Applicability

This AD applies to International Aero Engines AG (IAE) V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2531-E5, and V2533-A5 model turbofan engines with an installed:

(1) High-pressure turbine (HPT) 1st-stage disk, part number (P/N) 2A5001, with a serial number (S/N) listed in Appendix A, Table 1, of IAE Non-Modification Service Bulletin (NMSB) No. V2500-ENG-72-0713, Revision 1, dated January 26, 2021 (IAE NMSB V2500-ENG-72-0713, Revision 1) or IAE NMSB No. V2500-E5-72-0015, Revision 1, dated August 10, 2021 (IAE NMSB V2500-E5-72-0015, Revision 1); or

(2) HPT 2nd-stage disk, P/N 2A4802, with an S/N listed in Appendix A, Table 2, of IAE NMSB V2500-ENG-72-0713, Revision 1, or IAE NMSB V2500-E5-72-0015, Revision 1.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by an analysis performed by the manufacturer after an event involving an uncontained failure of a HPT 1st-stage disk that resulted in high-energy debris penetrating the engine cowling. The FAA is issuing this AD to prevent failure of the HPT 1st-stage disk and HPT 2nd-stage disk. The unsafe condition, if not addressed, could result in uncontained HPT disk failure, damage to the engine, damage to the airplane, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For IAE V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines with an HPT 1st-stage disk, P/N 2A5001, with an S/N listed in Appendix A, Table 1, of IAE NMSB V2500-ENG-72-0713, Revision 1, within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, or within 10 flight cycles (FCs) after the effective date of this AD, whichever occurs later, perform an ultrasonic inspection (USI) of the HPT 1st-stage disk using the Accomplishment Instructions, paragraph 6, of IAE NMSB V2500-ENG-72-0713, Revision 1.

Figure 1 to Paragraph (g)(1) – Inspection threshold

Compliance time: Whichever occurs first, Row A or B	
A	At the next engine shop visit after July 13, 2021 (the effective date of AD 2021-11-15)
B	Before the HPT 1st-stage disk or HPT 2nd-stage disk has accumulated 3,200 FCs since July 13, 2021

Note 1 to paragraph (g)(1): The USI required by paragraphs (g)(1) through (6) of this AD requires the HPT 1st-stage disk and HPT 2nd-stage disks to be removed from the engine allowing piece-part opportunity inspections. Per the Airworthiness Limitations Section of the manufacturer's Instructions for Continued Airworthiness, the additional inspections are not required unless the part has more than 100 FCs since the last piece-part opportunity inspection, is damaged, or is the cause for the removal of the engine. Engine removal for the purposes of complying with this AD is not “cause” for removal as stated in the Airworthiness Limitations Section.

(2) For IAE V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines with an HPT 2nd-stage disk, P/N 2A4802, with an S/N listed in Appendix A, Table 2, of IAE NMSB V2500-ENG-72-0713, Revision 1, within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later, perform a USI of the HPT 2nd-stage disk using the Accomplishment Instructions, paragraph 7, of IAE NMSB V2500-ENG-72-0713, Revision 1.

(3) For IAE V2522-A5, V2524-A5, V2525-D5, and V2527-A5 model turbofan engines with an HPT 1st-stage disk, P/N 2A5001, with an S/N listed in Appendix A, Table 1, of IAE NMSB V2500-ENG-72-0713, Revision 1, within the following compliance times, perform a USI of the HPT 1st-stage disk using the Accomplishment Instructions, paragraph 6, of IAE NMSB V2500-ENG-72-0713, Revision 1:

(i) If the affected HPT 1st-stage disk has not operated at any time in an IAE V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, or V2533-A5 model turbofan engine, perform the inspection within the compliance time specified in Figure 2 to paragraph (g)(3)(i) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later; or

Figure 2 to Paragraph (g)(3)(i) – Inspection threshold

Compliance time: Whichever occurs first, Row A or B	
A	At the next HPT rotor and stator assembly (HPT module) removal after July 13, 2021 (the effective date of AD 2021-11-15)
B	Before the HPT 1st-stage disk or HPT 2nd-stage disk has accumulated 6,700 FCs since July 13, 2021

(ii) If the affected HPT 1st-stage disk has operated at any time in an IAE V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, or V2533-A5 model turbofan engine, perform the inspection within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later.

(4) For IAE V2522-A5, V2524-A5, V2525-D5, and V2527-A5 model turbofan engines with an HPT 2nd-stage disk, P/N 2A4802, with an S/N listed in Appendix A, Table 2, of IAE NMSB V2500-ENG-72-0713, Revision 1, within the following compliance times, perform a USI of the HPT 2nd-stage disk using the Accomplishment Instructions, paragraph 7, of IAE NMSB V2500-ENG-72-0713, Revision 1:

(i) If the affected HPT 2nd-stage disk has not operated at any time in an IAE V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, or V2533-A5 model turbofan engine, perform the inspection within the compliance time specified in Figure 2 to paragraph (g)(3)(i) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later; or

(ii) If the affected HPT 2nd-stage disk has operated at any time in an IAE V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, or V2533-A5 model turbofan engine, perform the inspection within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later.

(5) For IAE V2531-E5 model turbofan engines with an HPT 1st-stage disk, P/N 2A5001, with an S/N listed in Appendix A, Table 1, of IAE NMSB V2500-E5-72-0015, Revision 1, within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later, perform a USI of the HPT 1st-stage disk using the Accomplishment Instructions, paragraph 6, of IAE NMSB V2500-E5-72-0015, Revision 1.

(6) For IAE V2531-E5 model turbofan engines with an HPT 2nd-stage disk, P/N 2A4802, with an S/N listed in Appendix A, Table 2, of IAE NMSB V2500-E5-72-0015, Revision 1, within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD, or within 10 FCs after the effective date of this AD, whichever occurs later, perform a USI of the HPT 2nd-stage disk using the Accomplishment Instructions, paragraph 7, of IAE NMSB V2500-E5-72-0015, Revision 1.

(7) If, during the USI required by paragraphs (g)(1) through (6) of this AD, an HPT 1st-stage disk or HPT 2nd-stage disk does not pass the inspection as specified in the Accomplishment Instructions, paragraph 8, of IAE NMSB V2500-ENG-72-0713, Revision 1, or IAE NMSB V2500-E5-72-0015, Revision 1, as applicable, before further flight, remove the HPT 1st-stage disk or HPT 2nd-stage disk, as applicable, from service and replace with a part eligible for installation.

(h) Definitions

(1) For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, H-P, except for the following situations, which do not constitute an engine shop visit.

(i) Separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance.

(ii) Engine removal for the purpose of performing field maintenance activities at a maintenance facility in lieu of performing them on-wing.

(2) For the purpose of this AD, a “part eligible for installation” is:

(i) An HPT 1st-stage disk or HPT 2nd-stage disk listed in Appendix A, Tables 1 and 2, of IAE NMSB V2500-ENG-72-0713, Revision 1, or Appendix A, Tables 1 and 2, of IAE NMSB V2500-E5-72-0015, Revision 1, that passed the USI required by paragraphs (g)(1) through (6) of this AD; or

(ii) An HPT 1st-stage disk or HPT 2nd-stage disk that is not listed in Appendix A, Tables 1 and 2, of IAE NMSB V2500-ENG-72-0713, Revision 1, or Appendix A, Tables 1 and 2, of IAE NMSB V2500-E5-72-0015, Revision 1.

(i) Credit for Previous Actions

You may take credit for the USI of the HPT 1st-stage disk and HPT 2nd-stage disk required by paragraphs (g)(5) and (6) of this AD and the replacement of the HPT 1st-stage disk and HPT 2nd-stage disk required by paragraph (g)(7) of this AD, if you performed these actions before the effective date of this AD in accordance with IAE NMSB No. V2500-E5-72-0015, original issue, dated December 15, 2020.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Alberto Hernandez, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7329; fax: (781) 238-7199; email: Alberto.J.Hernandez@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on March 15, 2022.

(i) International Aero Engines AG (IAE) Non-Modification Service Bulletin (NMSB) No. V2500-E5-72-0015, Revision 1, dated August 10, 2021.

(ii) [Reserved]

(4) The following service information was approved for IBR on July 13, 2021 (86 FR 30380, June 8, 2021).

(i) IAE NMSB No. V2500-ENG-72-0713, Revision 1, dated January 26, 2021.

(ii) [Reserved]

(5) For service information identified in this AD, contact International Aero Engines AG, 400 Main Street, East Hartford, CT 06118; phone: (800) 565-0140; email: help24@prattwhitney.com; website: <https://connect.p PrattWhitney.com>.

(6) You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 10, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-02574 Filed 2-7-22; 8:45 am]