



適航指令發布單 Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2022-03-001	發布日期 Date issued	2022/3/8
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers, except: - A319 aeroplanes on which Airbus modification (mod) 28238, mod 28162 and mod 28342 have been embodied in production; and - A318 aeroplanes on which mod 39195 has been embodied in production, or Airbus Service Bulletin (SB) A320-00-1219 has been embodied in service.		
主旨摘要 Subject	Fuselage - Inner Cap and Frame Flange at Frame 68 Stringer 22 - Inspection		
民航局 CAA <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authority <div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	2022-0030	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 53. Ref. Publications: Airbus SB A320-53-1491 original issue dated 14 August 2020.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax： (02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			

Airworthiness Directive

AD No.: 2022-0030

Issued: 25 February 2022

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: 11 March 2022

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: None

ATA 53 – Fuselage – Inner Cap and Frame Flange at Frame 68 Stringer 22 – Inspection

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers, except:

- A319 aeroplanes on which Airbus modification (mod) 28238, mod 28162 and mod 28342 have been embodied in production; and
- A318 aeroplanes on which mod 39195 has been embodied in production, or Airbus Service Bulletin (SB) A320-00-1219 has been embodied in service.

Definitions:

For the purpose of this AD, the following definitions apply:

Affected area: Inner cap and web horizontal flange at frame 68 (left-hand and right-hand side) at level of stringer 22.

The SB: Airbus SB A320-53-1491.

Reason:

Cracks have been reported in the affected area during accomplishment of inspections required by EASA AD 2016-0238.

This condition, if not detected and corrected, could reduce the structural integrity of the fuselage.

To address this potential unsafe condition, Airbus issued the SB to provide instructions for inspection of the affected area.

For the reasons described above, this AD requires repetitive special detailed inspection (SDI) of the affected area.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspection(s):

- (1) Before exceeding the compliance time(s) defined in Table 1 of this AD, as applicable, and, thereafter, at intervals not to exceed 19 700 flight cycles (FC), accomplish SDI of each affected area, in accordance with the instructions of the SB.

Table 1 – Initial SDI

Aeroplane accumulated FC (on the effective date of this AD)	Compliance Time
33 700 FC or less	Before exceeding 20 000 FC since aeroplane first flight or within 24 months after the effective date of this AD, whichever occurs later
More than 33 700 FC	Within 12 months after the effective date of this AD

Alternative Method:

- (2) Accomplishment on an aeroplane of (repetitive) maintenance instructions, issued and approved by Airbus before the effective date of this AD, which supplement or supersede the instructions of the SB, is an acceptable alternative method to comply with the requirements of paragraphs (1) of this AD for that aeroplane.

Corrective Action(s):

- (3) If, during any inspection as required by paragraph (1) or (2) of this AD, as applicable, discrepancies and/or cracks are detected, before next flight, contact Airbus for approved corrective action(s) instructions and, within the compliance time specified therein, accomplish those instructions accordingly.

Terminating Action:

- (4) Accomplishment of corrective action(s) on an aeroplane as required by paragraph (3) of this AD does not constitute terminating action for the repetitive SDI as required by paragraph (1) of this AD for that aeroplane, unless specified otherwise in the instructions provided by Airbus.



Ref. Publications:

Airbus SB A320-53-1491 original issue dated 14 August 2020.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 21 June 2021 as PAD 21-090 for consultation until 19 July 2021. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – IIASA; E-mail: account.airworth-eas@airbus.com.

