



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2022-05-008	發布日期 Date issued	2022/5/19
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N and A321-253NX aeroplanes, all manufacturer serial numbers.		
主旨摘要 Subject	Power Plant - Aft Engine Mount Secondary Load Path - Inspection		
<div style="text-align: center;">民航局 CAA</div> <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	<div style="text-align: center;">設計國民航主管機構 Original Authority</div> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%;"> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 50%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	2022-0089	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 71. Ref. Publications: Airbus SB A320-71-1090 original issue dated 30 July 2021.		

註： 1. AD 內容後附。
 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail：
adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：
 (02)2545-8464, e-mail：adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2022-0089

Issued: 17 May 2022

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301 or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303 or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A321 aeroplanes

Effective Date: 31 May 2022

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: None

ATA 71 – Power Plant – Aft Engine Mount Secondary Load Path – Inspection

Manufacturer(s):

Airbus

Applicability:

Airbus A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N and A321-253NX aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The SB: Airbus Service Bulletin (SB) A320-71-1090.

DET: Detailed inspection (DET) of aft engine mount left-hand and right-hand side secondary load path clearance and fail safe pin, in accordance with the instructions of the SB.

Reason:

Design review determined that the engine fail safe lug may not be able to sustain, during one inspection interval as currently specified in the Airworthiness Limitations Section, the loads deriving from the engagement of the secondary load path.



This condition, if not detected and corrected, could lead to engine mount rupture, possibly resulting in engine loss during flight and loss of control of the aeroplane.

To address this potential unsafe condition, Airbus issued the SB, as defined in this AD, providing instructions for repetitive DET, in addition to the inspections per airworthiness limitation item (ALI) task 712232-01-1.

For the reasons described above, this AD requires repetitive DET and, depending on findings, accomplishment of corrective actions.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspection(s):

- (1) Within 11 000 flight cycles (FC) since last installation of an engine on an aeroplane, or since last engine mount inspection as per ALI task 712232-01-1, or since aeroplane first flight, whichever occurs later, and, thereafter, at intervals not exceeding 11 000 FC, accomplish a DET of that engine.
- (2) After replacing an engine on an aeroplane, the next repeat inspection as required by paragraph (1) of this AD for that engine can be postponed until 11 000 FC since that engine installation.

Corrective Action(s):

- (3) If, during any inspection as required by paragraph (1) of this AD, discrepancies are detected, as defined in the SB, or aft engine mount parts are found broken, before next flight, replace the engine in accordance with the instructions of the SB, and contact Airbus for approved instructions and, within the compliance time specified therein, accomplish those instructions accordingly.

Terminating Action:

- (4) None.

Ref. Publications:

Airbus SB A320-71-1090 original issue dated 30 July 2021.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 16 February 2022 as PAD 22-013 for consultation until 16 March 2022. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.



4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – IIASA; E-mail: account.airworth-eas@airbus.com.

