



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2022-08-014	發布日期 Date issued	2022/8/29
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Bombardier Inc. model BD-700-2A12 aeroplanes, serial numbers 70006 through 70129.		
主旨摘要 Subject	Flight Controls - Multi-Function Spoiler - Replacement of MFS 1, MFS 2, and MFS 3 Anti-Rotation Plates		
<div style="text-align: center;">民航局 CAA</div> <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	<div style="text-align: center;">設計國民航主管機構 Original Authority</div> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <input type="checkbox"/> FAA <input type="checkbox"/> EASA <input type="checkbox"/> Brazil <input checked="" type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 45%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	CF-2022-47	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 27. Ref. Bombardier SB 700-27-7504 Revision 1, dated 11 July 2022 or later revisions.		

註： 1. AD 內容後附。
 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail：
adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail：
adcaa@mail.caa.gov.tw



AIRWORTHINESS DIRECTIVE

This Airworthiness Directive (AD) is issued pursuant to Canadian Aviation Regulation (CAR) 521.427. No person shall conduct a take-off or permit a take-off to be conducted in an aircraft that is in their legal custody and control, unless the requirements of CAR 605.84 pertaining to ADs are met. Standard 625 - Aircraft Equipment and Maintenance Standards Appendix H provides information concerning alternative means of compliance (AMOC) with ADs.

Number:

CF-2022-47

Effective Date:

30 August 2022

ATA:

27

Type Certificate:

A-177

Subject:

Flight Controls – Multi-Function Spoiler (MFS) – Replacement of MFS 1, MFS 2, and MFS 3 Anti-Rotation Plates

Applicability:

Bombardier Inc. model BD-700-2A12 aeroplanes, serial numbers 70006 through 70129.

Compliance:

Within 36 months from the effective date of this AD, unless already accomplished.

Background:

It has been reported that some of the MFS anti-rotation plates failed in-service due to a thin wall design. The MFS anti-rotation plates were designed with overlapping tolerances on the inside and outside diameters, allowing for an extremely thin wall thickness once machined. Failed MFS anti-rotation plates can result in wear and failure of the inboard and outboard hinge pins. Significant wear and fracture of the pins could result in that particular hinge no longer supporting the load.

This AD mandates the inspection of all MFS anti-rotation plates for cracks and hinge bolts for any possible evidence of rotation, and the replacement of all MFS anti-rotation plates with redesigned parts.

Corrective Actions:

In accordance with the Accomplishment Instructions of Bombardier SB 700-27-7504 Revision 1, dated 11 July 2022 or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada:

- A. Remove MFS anti-rotation plates part number (P/N) G05770140-103 and P/N G05770160-101, inspect the MFS anti-rotation plates for cracks and the hinge bolts for any possible evidence of rotation. If cracks or evidence of rotation is found, contact Bombardier for an approved disposition and incorporate that disposition before further flight.
- B. Install MFS anti-rotation plates P/N G05770140-105.

Authorization:

For the Minister of Transport,

ORIGINAL SIGNED BY

Philippe Ngassam
Director, National Aircraft Certification
Issued on 16 August 2022

Contact:

Scott Wales, Continuing Airworthiness, Ottawa, telephone 888-663-3639, facsimile 613-996-9178 or e-mail TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca or any Transport Canada Centre.