



適航指令發布單
Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2023-02-002	發布日期 Date issued	2023/2/6
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Embraer S.A. airplanes model EMB-505		
主旨摘要 Subject	aileron autopilot servo mount clutch retaining bolt and washer - inspection / Replacement.		
民航局 CAA <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="checkbox"/> FAA <input type="checkbox"/> EASA <input checked="" type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2023-02-01	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 22. Ref. (SB) N.505-22-0004, Revision 04, dated January 06, 2023, or further revisions approved by ANAC.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL - BRAZIL

BRAZILIAN AIRWORTHINESS DIRECTIVE

AD No.: 2023-02-01

Effective Date: 06 Fev. 2023

The following Brazilian Airworthiness Directive (AD), issued by the Agência Nacional de Aviação Civil (ANAC) in accordance with provisions of Chapter IV, Title III of Código Brasileiro de Aeronáutica - Law No. 7,565 dated 19 December 1986 - and Regulamento Brasileiro da Aviação Civil (RBAC) 39, applies to all aircraft registered in the Registro Aeronáutico Brasileiro. No person may operate an aircraft to which this AD applies, unless it has previously complied with the requirements established herein.

AD No. 2023-02-01 - EMBRAER / 39-1507.

APPLICABILITY:

This Airworthiness Directive (AD) applies to Embraer S.A. airplanes model EMB-505, as specified in Embraer Service Bulletin (SB) N.505-22-0004, Revision 04, dated January 06, 2023, or further revisions approved by ANAC.

CANCELLATION / REVISION:

Not applicable.

REASON:

It has been found the occurrence of corrosion in the clutch retaining bolt of aileron autopilot servo mount of the airplane. A clutch retaining bolt failure can disengage the clutch from the drive pin and jam the aileron controls, which may affect the airplane controllability.

Since this condition may occur in other airplanes of the same type and affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD in the indicated time limit.

REQUIRED ACTION:

Replacement of the aileron autopilot servo mount clutch retaining bolt and washer.

COMPLIANCE:

Required as indicated below, unless already accomplished.

(a) Replacement of the aileron autopilot servo mount clutch retaining bolt and washer.

Within the applicable intervals established in the "Table 01 - Compliance

intervals and limitations" of this AD, replace the aileron autopilot servo mount clutch retaining bolt with Part Number (P/N) 211-00090-03 by a new one bearing the same P/N 211-00090-03 or by a new one bearing a new P/N AN3-10A, and washer with P/N 212-00035-10 by a new one bearing a new P/N 212-00203-04 or a new P/N MS35338-43.

Table 01 - Compliance intervals and limitations.

Applicable airplane Flight Hours Since New (FHSN) and Time Since New (TSN), in months (MO), intervals.	Accomplishment interval.	Limitations (whichever occurs first).
(1) More than 144 TSN, or; More than 3,800 FHSN and more than 84 TSN, or; More than 5,500 FHSN.	(a) Within the next 3 MO or 50 FH, whichever occurs first, after the effective date of this AD.	(i) Not applicable.
(2) More than 3,800 FHSN up to 5,500 FHSN and less than 84 TSN.	(a) Within the next 6 MO or 200 FH, whichever occurs first, after the effective date of this AD.	(i) Limited to 87 TSN or 5,550 FHSN, whichever occurs first, or; (ii) Before accumulating 50 FH after 84 TSN, or; (iii) Before accumulating 3 MO after 5,500 FHSN.
(3) More than 1,200 FHSN up to 3,800 FHSN and more than 48 TSN up to 144 TSN.	(a) Within the next 6 MO or 200 FH, whichever occurs first, after the effective date of this AD.	(i) Limited to 147 TSN, or; (ii) Before accumulating 3,850 FHSN after 84 TSN, or; (iii) Before accumulating 3 MO after 3,800 FHSN and 84 TSN.
(4) Less than 3,800 FHSN and more than 36 TSN up to 48 TSN.	(a) Within the next 9 MO or 600 FH, whichever occurs first, after the effective date of this	(i) Limited to 54 TSN or 4,000 FHSN, whichever occurs first, or; (ii) Before accumulating 6 MO after 1,200 FHSN and 48 TSN, or; (iii) Before

	AD.	accumulating 200 FH after 1,200 FHSN and 48 TSN, or; (iv) Before accumulating 6 MO after 3,800 FHSN.
(5) Less than 1,200 FHSN and more than 48 TSN up to 144 TSN.	(a) Within the next 9 MO or 600 FH, whichever occurs first, after the effective date of this AD.	(i) Limited to 147 TSN or 1,400 FHSN, whichever occurs first, or; (ii) Before accumulating 50 FH after 144 TSN; or; (iii) Before accumulating 6 MO after 1,200 FHSN, or; (iv) Before accumulating 200 FH after 1,200 FHSN.

NOTE: If the airplane operation age and/or the flight hours criteria change before the SB accomplishment, the most restrictive criteria must be obeyed.

(b) Repetitive replacement.

Replace the aileron autopilot servo mount clutch retaining bolt with P/N 211-00090-03 or with P/N AN3-10A by a new one with P/N 211-00090-03 or with P/N AN3-10A, and the washer with P/N 212-00203-04 or with P/N MS35338-43 by a new one with P/N 212-00203-04 or with P/N MS35338-43, at intervals that do not exceed 36 months after the first replacement according to the paragraph **(a)** of this AD.

(c) Alternative methods of compliance (AMOCs).

A different method or a different compliance time, with the requirements of this AD, may be used if approved by the Manager of the Continuing Airworthiness Technical Branch (GTAC) of ANAC.

(d) Material incorporated by reference.

You must use the Embraer SB N.505-22-0004, Revision 04, dated January 06, 2023, or further revisions approved by ANAC, to do the actions required by this AD, unless this AD specifies otherwise.

Record compliance with this AD in the applicable maintenance log book.

CONTACT:

For additional technical information, contact:

National Civil Aviation Agency (ANAC)
Continuing Airworthiness Technical Branch (GTAC)

Rua Doutor Orlando Feirabend Filho, nº 230
Centro Empresarial Aquárius - Torre B - 14º ao 18º andares
Parque Residencial Aquárius
CEP 12246-190 - São José dos Campos - SP, BRAZIL.
Tel: (12) 3203-6600; E-mail: pac@anac.gov.br

APPROVAL:

ROBERTO JOSÉ SILVEIRA HONORATO
Head of Department
Department of Airworthiness (SAR)
ANAC

NOTA: Original in Portuguese language signed and available in the files of the Continuing Airworthiness Technical Branch (GTAC) of the National Civil Aviation Agency (ANAC).

Referência: Processo nº 00066.014634/2022-07

SEI nº 8127278