



## 適航指令發布單

## Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2023-05-002A	發布日期 Date issued	2023/5/18
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A319-151N, A319-153N, A319-171N, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N, A321-272NX aeroplanes, all manufacturer serial numbers (MSN).		
主旨摘要 Subject	Landing Gear - Braking and Steering Control Unit - Replacement / Master Minimum Equipment List - Amendment / Electric and Electronic Common Installation - Relays - Replacement		
民航局 CAA <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input type="checkbox"/> UK CAA <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2023-0093R1	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	This AD revises EASA AD 2023-0093(CAA-2023-05-002) dated 05 May 2023, which superseded EASA AD 2022-0032R1 dated 29 July 2022.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： <a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a> Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax： (02)2545-8464, e-mail： <a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a>			



## Airworthiness Directive

**AD No.:** 2023-0093R1

**Issued:** 15 May 2023

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

### Design Approval Holder's Name:

AIRBUS S.A.S.

### Type/Model designation(s):

A319, A320 and A321 aeroplanes

**Effective Date:** Revision 1: 19 May 2023  
Original Issue: 19 May 2023

**TCDS Number(s):** EASA.A.064

**Foreign AD:** Not applicable

**Supersedure:** This AD revises EASA AD 2023-0093 dated 05 May 2023, which superseded EASA AD 2022-0032R1 dated 29 July 2022.

### ATA 32 – Landing Gear – Braking and Steering Control Unit – Replacement / Master Minimum Equipment List – Amendment

### ATA 92 – Electric and Electronic Common Installation – Relays – Replacement

### Manufacturer(s):

Airbus S.A.S.

### Applicability:

Airbus A319-151N, A319-153N, A319-171N, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N, A321-272NX aeroplanes, all manufacturer serial numbers (MSN).

### Definitions:

For the purpose of this AD, the following definitions apply:

**Affected BSCU:** Braking and Steering Control Units (BSCU) having Part Number (P/N) E21327307.

**Non-affected BSCU:** Any BSCU having a P/N other than E21327307.



**Serviceable BSCU:** Any BSCU, eligible for installation, which is a non-affected BSCU; or an affected BSCU that has never triggered any fault signature on an aeroplane as defined in Appendix 1 of the AOT 1.

**Type 1 relay:** Relays having P/N E0244-28A0, installed at Functional Item Number (FIN) positions 24GG and 25GG.

**Type 2 relay:** A relay having P/N E0669D28A0.

**The AOT 1:** Airbus Alert Operators Transmission (AOT) A32N025-22.

**The AOT 2:** Airbus AOT A32N030-23.

**The SB:** Airbus Service Bulletin (SB) A320-92-1149.

**The MMEL update:** Airbus A318/A319/A320/A321 Master Minimum Equipment List (MMEL) items listed in the Appendix 2 of this AD or in the MMEL Revision dated 05 April 2023.

**The FOT:** Airbus Flight Operations Transmission (FOT) 999.0010/22.

**Aeroplane date of manufacture:** The date of transfer of title (ownership) which is referenced in Airbus documentation at the time of first delivery to an operator.

#### **Groups:**

Group 1a aeroplanes are those that have an affected BSCU and a type 1 relay installed.

Group 1b aeroplanes are those that have a non-affected BSCU and a type 1 relay installed.

Group 2 aeroplanes are those that are not Group 1a nor 1b (see Note 1 of this AD).

An aeroplane having an MSN listed in Table 1 of Appendix 1 of this AD is considered to be a Group 1a or Group 1b aeroplane, depending on the BSCU installed, until the accomplishment of the inspection, as required by paragraph (1) of this AD, has taken place and determined which relay is installed on that aeroplane.

**Note 1:** An aeroplane on which Airbus modification (mod) 171984 (installation of relay P/N E0669D28A0) has been embodied in production and having an MSN not listed in Table 1 of Appendix 1 of this AD is a Group 2, provided the aeroplane remains in that configuration.

#### **Reason:**

A new BSCU standard P/N E21327307 was developed and introduced through Airbus mod 165148 to answer to the obsolescence of some components fitted in the old BSCU standard P/N E21327107 and P/N E21327007. Since this new BSCU standard was introduced on aeroplanes, several BSCU channel failures were detected, inducing, in case of dual channel failures, loss of anti-skid function together with the reversion to the alternate braking mode, and loss of nose wheel steering.

This condition, if not corrected, could lead to loss of braking performance with significant increase in aeroplane stopping distance, possibly resulting in runway excursion.



To address this potential unsafe condition, Airbus issued the AOT 1 and the FOT (together with Quick Reference Handbook and Flight Crew Operating Manual updates) to provide guidance to the flight crew in the event of specific fault signatures (Electronic Centralized Aircraft Monitoring (ECAM) warning + Maintenance Message). Airbus also updated the MMEL accordingly. Consequently, EASA issued AD 2022-0032 (later revised) to require, for aeroplanes with an affected BSCU installed, the accomplishment of the AOT 1, and the amendment of the operator MEL.

Further investigation identified that a type 1 relay was embodied in a position where a type 2 relay should have been installed. The combination of a type 1 relay with an affected BSCU could induce BSCU freezing. Consequently, Airbus developed mod 171984, which was introduced on the production line, and issued the SB to provide instructions for replacement of type 1 relays. It was also determined that the type 1 relay is no longer installed on A320 family CEO aeroplanes since its mandated replacement, required through DGAC France AD F-1993-163-043 (grandfathered by EASA). CEO aeroplanes are therefore not included in the applicability of this AD.

EASA was informed that the troubleshooting of a BSCU fault triggered on a post-production aeroplane revealed that the relays installed on aircraft at 24GG / 25GG FIN locations were not in conformity with the Aeroplane Inspection Report. Further investigation identified that certain MSNs are potentially affected by this issue. For this reason, the AOT 2 was issued for a dedicated inspection.

For the reasons described above, EASA issued AD 2023-0093, superseding EASA AD 2022-0032R1 and requiring replacement of affected BSCU with serviceable BSCU in case of fault signatures, MEL amendment instating dispatch limitation, and replacement of affected type 1 relays with type 2 relays.

Since that AD was published, it was determined that certain aeroplanes having an MSN as listed in Table 1 of Appendix 1 of this AD, have been delivered with a BSCU P/N E21327107. This AD is revised accordingly.

#### **Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

#### **Inspection:**

- (1) For aeroplanes having an MSN listed in Table 1 of Appendix 1 of this AD, within the compliance time defined in Table 1 of this AD, as applicable, visually inspect the FIN 24GG and 25GG to determine whether a relay type 1 is installed (see Note 2 of this AD).

Table 1 – Relay Inspection

<b>BSCU Installed</b>	<b>Compliance Time</b> (after the effective date of this AD)
Affected BSCU	Within 12 months
Non-affected BSCU	Within 24 months



Note 2: If during the visual inspection a relay type 1 is found, the aeroplane is either a Group 1a or Group 1b aeroplane, depending on the BSCU installed. If a type 2 relay is found, the aeroplane is a Group 2 aeroplane.

#### **BSCU Replacement:**

- (2) For Group 1a aeroplanes having an MSN not listed in Table 1 of Appendix 1 of this AD: If, during any flight after 10 March 2022 [the effective date of EASA AD 2022-0032 at original issue], a BSCU fault signature is triggered on an aeroplane as defined in the AOT 1 Appendix 1, before next flight, replace the affected BSCU with a serviceable BSCU in accordance with the instructions of the AOT 1.
- (3) For Group 1a aeroplanes having an MSN as listed in Table 1 of Appendix 1 of this AD: If, during any flight after the effective date of this AD, a BSCU fault signature is triggered on an aeroplane as defined in the AOT 1 Appendix 1, before next flight, replace the affected BSCU with a serviceable BSCU in accordance with the instructions of the AOT 1.

#### **MMEL Amendment:**

- (4) Before next flight after the effective date of this AD, implement the instructions of the MMEL update, as defined in this AD, on the basis of which the operator's MEL must be amended, inform all flight crews, and, thereafter, operate the aeroplane accordingly.

#### **Modification:**

- (5) For Group 1a and 1b aeroplanes: Within the compliance time as specified in Table 2 of this AD, as applicable, replace each type 1 relay with a type 2 relay in accordance with the instructions of the SB (for the MSN not listed in Table 1 of the Appendix 1 of this AD), or in accordance with the instructions of the AOT 2 (for the MSN listed in Table 1 of the Appendix 1 of this AD), as applicable (see Note 3 of this AD).

Table 2 – Relay Replacement

<b>Group</b>	<b>Compliance Time</b> (after the effective date of this AD)
1a	Within 12 months
1b	Within 24 months

Note 3: Following the modification, the aeroplane is considered to be a Group 2 aeroplane.

#### **Part(s) Installation:**

- (6) Do not install a relay P/N E0244-28A0 at FIN positions 24GG and 25GG on any aeroplane, as required by paragraph (6.1) or (6.2) of this AD, as applicable:
  - (6.1) For Group 1a and 1b aeroplanes: After modification of the aeroplane as required by paragraph (5) of this AD.
  - (6.2) For Group 2 aeroplanes: From the effective date of this AD.



- (7) For Group 1a: From the effective date of this AD, it is allowed to install a BSCU on an aeroplane, provided it is a serviceable BSCU, as defined in this AD.
- (8) For Group 1b aeroplanes: From the effective date of this AD, do not install an affected BSCU on an aeroplane.

#### Ref. Publications:

Airbus AOT A32N025-22 original issue dated 24 February 2022, or Revision 01 dated 10 May 2023.

Airbus AOT A32N030-23 original issue dated 27 February 2023.

Airbus A318/A319/A320/A321 MMEL Revision dated 05 April 2023.

Airbus FOT 999.0010/22 original issue dated 22 February 2022, or Revision 01 dated 25 February 2022.

Airbus SB A320-92-1149 original issue dated 11 October 2022, or Revision 01 dated 20 January 2023.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

#### Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The original issue of this AD was posted on 06 December 2022 as PAD 22-166, re-published on 22 December 2022 as PAD 22-166R1 and re-published on 14 April 2023 as PAD 22-166R2 for consultation until 28 April 2023. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – 1IASA; E-mail: [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com).



## Appendix 1

Table 1 – Affected MSN

MSN							
9540	10127	10128	10142	10146	10161	10188	10272
10275	10284	10331	10353	10400	10420	10434	10448
10486	10546	10620	10637	10644	10655	10658	10674
10701	10703	10714	10724	10729	10737	10741	10756
10776	10779	10780	10788	10789	10795	10797	10798
10803	10809	10814	10816	10819	10828	10831	10832
10833	10837	10839	10842	10848	10850	10853	10854
10855	10861	10862	10866	10873	10875	10878	10881
10882	10884	10885	10886	10887	10888	10890	10893
10896	10898	10900	10901	10902	10903	10904	10907
10908	10909	10911	10912	10914	10916	10917	10918
10919	10921	10922	10923	10924	10925	10927	10932
10933	10934	10935	10937	10938	10939	10940	10941
10942	10947	10949	10950	10951	10952	10954	10957
10958	10960	10961	10962	10963	10964	10965	10966
10967	10969	10970	10972	10973	10975	10976	10977
10979	10980	10981	10982	10983	10984	10985	10986
10987	10988	10989	10990	10992	10993	10995	10996
10997	10998	11002	11003	11004	11005	11006	11007
11008	11010	11011	11012	11013	11014	11015	11016
11017	11018	11019	11020	11021	11022	11023	11024
11025	11026	11027	11028	11030	11031	11032	11033
11034	11035	11036	11037	11038	11039	11040	11041
11042	11043	11044	11045	11047	11048	11049	11050
11051	11052	11053	11054	11055	11056	11057	11059
11060	11061	11062	11064	11065	11066	11067	11068
11069	11070	11071	11073	11074	11075	11076	11077
11078	11079	11081	11082	11083	11085	11086	11087
11088	11090	11091	11092	11094	11097	11099	11100
11102	11103	11105	11108	11109	11111	11112	11114
11116	11117	11118	11120	11121	11122	11123	11124
11126	11127	11128	11130	11133	11135	11137	11138
11139	11140	11141	11142	11143	11145	11146	11148
11149	11150	11151	11152	11153	11154	11155	11157
11159	11160	11161	11162	11166	11169	11173	11174
11175	11178	11180	11181	11182	11188	11189	11190
11193	11194	11195	11197	11199	11201	11205	11211
11213	11216	11222	11224	11228	11232	11234	11235
11244	11245	11247	11252	11254	11258	11261	11265
11270	11271	11282	11287	11288	11293	11295	



## Appendix 2

Table 2 – Affected MMEL Items

ITEM	Title	Ident MI	Date	Effectivity
32-31-01	Landing Gear Control and Interface Unit (LGCIU)	MI-32-31-00007688.0006001	22 FEB 22	A320neo with BSCU P/N E21327307, without ACT
		MI-32-31-00007688.0007001	22 FEB 22	A320neo with BSCU P/N E21327307, with ACT
32-32-02	LGCIU 2 RH L/G Shock Absorber Proximity Detector	MI-32-32-00007694.0002001	22 FEB 22	A320neo with BSCU P/N E21327307
32-32-03	LGCIU 2 LH L/G Shock Absorber Proximity Detector	MI-32-32-00007695.0002001	22 FEB 22	A320neo with BSCU P/N E21327307
32-42-03	BSCU System 1	MI-32-42-00007739.0003001	24 FEB 22	A319/A320/A321neo, with BSCU P/N E21327307
32-42-04	BSCU System 2	MI-32-42-00007740.0003001	22 FEB 22	A319/A320/A321neo, with BSCU P/N E21327307
32-44-01	Yellow System Brake	MI-32-44-00007746.0002001	22 FEB 22	A319/A320/A321neo, with BSCU P/N E21327307
32-44-03	Brakes Pressure Indicator	MI-32-44-00007748.0003001	22 FEB 22	A319/A320/A321neo, with BSCU P/N E21327307
78-09-01	ENG 1(2) REVERSER CTL FAULT Alert	MI-78-09-00016199.0002001	22 FEB 22	A319/A320/A321neo, with BSCU P/N E21327307
78-30-01	Thrust Reverser	MI-78-30-00008603.0005001	22 FEB 22	A319/A320/A321neo with PW1100 engines and with BSCU P/N E21327307
		MI-78-30-00008603.0006001	22 FEB 22	A319/A320/A321neo with LEAP engines and with BSCU P/N E21327307

