



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2023-05-008	發布日期 Date issued	2023/5/30
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N and A321-272NX aeroplanes, all manufacturer serial numbers.		
主旨摘要 Subject	Fuel - Fuel Pump - Inspection / Replacement		
<div style="text-align: center;">民航局 CAA</div> <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	<div style="text-align: center;">設計國民航主管機構 Original Authority</div> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 45%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	2023-0106	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	This AD supersedes EASA AD 2007-0218R2(CAA-2006-05-003D) dated 10 October 2014.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2023-0106

Issued: 25 May 2023

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: 08 June 2023

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2007-0218R2 dated 10 October 2014.

ATA 28 – Fuel – Fuel Pump – Inspection / Replacement

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N and A321-272NX aeroplanes, all manufacturer serial numbers.

Note 1: The applicability of the AD and the applicability of service documents issued by the type certificate holder may vary, while the applicability of the AD is the binding one.

Definitions:

For the purpose of this AD, the following definitions apply:

Pump A: Fuel pumps having part number (P/N) 568-1-27202-001, P/N 568-1-27202-002 or P/N 568-1-27202-005.

Pump B: Fuel pumps having P/N 568-1-27202-02R.



The AOT: Airbus Alert Operator Transmission (AOT) A28N010-22-00R1.

The SB: Airbus Service Bulletin (SB) A320-28-1159.

Groups:

Group 1 aeroplanes are A319/A320 aeroplanes not having modification (MOD) 154327 (introduction of the A321 centre fuel transfer system onto A319 and A320 variants) embodied and all A318 aeroplanes.

Group 2 aeroplanes are A319/A320 aeroplanes having MOD 154327 embodied and all A321 aeroplanes.

Aeroplane date of manufacture: The date of transfer of title (ownership) at the time of first delivery to an operator, which is referenced in Airbus documentation.

Reason:

Failures of type 8410 fuel pump P/N 568-1-27202-005 have been reported in service. Subsequent investigation revealed that the cause of the pump failure was due to one of the two screws and nuts holding the gas return connector to the top of the motor housing becoming unscrewed. Prompted by these reports, EASA published AD 2006-0106-E, AD 2006-0222 and AD 2007-0218, each one superseding the other, requiring modification or replacement of fuel pumps A, as defined in this AD.

After EASA AD 2007-0218R2 was issued, it has been determined that aeroplanes fitted with fuel pumps B can be subject to cavitation erosion on the wiring conduit.

This condition, if not detected and mitigated, could lead to be the source of an in-tank ignition, affecting the integrity of the aeroplane structure and systems. To address this possible unsafe condition, Airbus issued the AOT, providing applicable instructions.

For the reasons described above, this AD is based on the requirements of EASA AD 2007-0218R2, which is superseded, and requires inspection and replacement of pumps B.

This AD is considered an interim action and further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Note 2: An aeroplane on which Airbus MOD 39067 (installation of fuel pump P/N 568-1-27202-006) and/or MOD 151512 (installation of fuel pump P/N 568-1-27202-007) have been embodied in production is not affected by the requirement of paragraphs (1) to (6) of this AD, provided neither a pump A nor a pump B has been installed on that aeroplane after its date of manufacture.

- (1) From the effective date of this AD, do not operate any aeroplane having a pump A installed.



Inspection(s):

- (2) For Group 1 aeroplanes: Within 30 days after the effective date of this AD, inspect each pump B in the centre fuel tank at locations FIN 37QA and 38QA in accordance with the instructions of the AOT.
- (3) For Group 2 aeroplanes: Within 90 days after the effective date of this AD, inspect each pump B located in wing fuel tank at locations FIN 21QA, 22QA, 25QA and 26QA in accordance with the instructions of the AOT.

Corrective Action(s):

- (4) For Group 1 and Group 2 aeroplanes: If, during any inspection as required by paragraph (2) or (3) of this AD, as applicable, discrepancies, as defined in the AOT, are detected on a fuel pump, before next flight, replace that fuel pump in accordance with the instructions of the AOT.
- (5) For Group 1 and Group 2 aeroplanes: Unless already accomplished as required by paragraph (4) of this AD, within 4 000 flight hours after the inspection as required by paragraph (2) and (3) of this AD, as applicable, replace each pump B at locations FIN 21QA, 22QA, 25QA and 26QA, 37QA, 38QA, as applicable, in accordance with the instructions of the AOT.

Credit:

- (6) Inspections and corrective actions, accomplished on an aeroplane before the effective date of this AD in accordance with the instructions of the AOT at original issue are acceptable to comply with the requirements of paragraphs (2) to (5) of this AD, as applicable, for that aeroplane.

Part(s) Installation:

- (7) For Group 1 aeroplanes: From the effective date of this AD, do not install a fuel pump B at location FIN 37QA and 38QA (see Note 3 of this AD).
- (8) For Group 2 aeroplanes: From the effective date of this AD, do not install a fuel pump B at location FIN 21QA, 22QA, 25QA and 26QA (see Note 3 of this AD).

Note 3: Removal of an affected fuel pump from an aeroplane and subsequent reinstallation of that fuel pump on the same aeroplane, accomplished during a single maintenance visit, is not considered as 'install' as specified in paragraph (7) and (8) of this AD.

Ref. Publications:

Airbus SB A320-28-1159 original issue dated 08 January 2007.

Airbus AOT A28N010-22-00, at original issue, dated 09 February 2023 or revision 1 dated 06 March 2023.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.



Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – 1IASA; E-mail: account.airworth-eas@airbus.com

