



適航指令發布單 Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2023-11-001	發布日期 Date issued	2023/11/07
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers. Note: While the applicability of the SB, as defined in this AD, is limited to aeroplanes installing Trent XWB-84 and Trent XWB-97 engines, this AD is also applicable to aeroplanes installing Trent XWB-75 engines.		
主旨摘要 Subject	Pneumatic - TRENT XWB Engine Bleed Air Supply System T-Duct - Replacement		
民航局 CAA	設計國民航主管機構 Original Authority		
<input type="radio"/> 本國產品 Native product	<input type="radio"/> FAA	<input type="radio"/> Germany LBA	
<input type="radio"/> 其他個案 Other	<input checked="" type="radio"/> EASA	<input type="radio"/> CAA-NL	
	<input type="radio"/> Brazil	<input type="radio"/> UK CAA	
	<input type="radio"/> Transport Canada Civil Aviation	<input type="radio"/> Japan CAB	
	<input type="radio"/> DGAC	<input type="radio"/> CAA of Israel	
		<input type="radio"/> Other_____	
	設計國AD編號 Original AD number	2023-0189	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as):		
	2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	ATA 36. Ref. Publications: Airbus Service Bulletin A350-36-P033 original issue dated 27 October 2023. Rolls-Royce Alert NMSB TRENT XWB 36-AK870 original issue dated 29 September 2023.		

註： 1. AD內容後附。

2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。

3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464,

adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.

2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.

3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332,

Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2023-0189

Issued: 31 October 2023

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A350 aeroplanes

Effective Date: 07 November 2023

TCDS Number(s): EASA.A.151

Foreign AD: Not applicable

Supersedure: None

ATA 36 – Pneumatic – TRENT XWB Engine Bleed Air Supply System T-Duct – Replacement

Manufacturer(s):

Airbus

Applicability:

Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers (MSN).

Note: While the applicability of the SB, as defined in this AD, is limited to aeroplanes installing Trent XWB-84 and Trent XWB-97 engines, this AD is also applicable to aeroplanes installing Trent XWB-75 engines.

Definitions:

For the purpose of this AD, the following definitions apply:

The SB: Airbus Service Bulletin (SB) A350-36-P033.

The NMSB: Rolls-Royce Alert Non-Modification Service Bulletin (NMSB) TRENT XWB-36-AK870.

The NMSB has an 'A' (Alert) in the number, but a later revision may not have that 'A'. This kind of change does not effectively alter the publication references.



Affected part: Engine Bleed Air System (EBAS) T-Duct having Part Number RR03-11011-001 and a serial number as listed in the APPENDIX 1 of the NMSB.

Serviceable part: EBAS T-Duct, eligible for installation, which is not an affected part; or an affected part, for which the flight cycles (FC) since new (first installation on an engine of an aeroplane) are known or can be determined (see Note 2 of this AD), and that has not exceeded the compliance time as defined in Table 1 of this AD.

Groups: Group 1 aeroplanes are those that have an affected part installed. Group 2 aeroplanes are those that do not have an affected part installed.

Reason:

The affected part manufacturer, a sub-supplier to Rolls-Royce (RR) for engines Trent XWB-75, Trent XWB-84 and Trent XWB-97 bleed ducts, reported that certain EBAS T-Duct may have a non-conformance due to a quality escape not detected during the manufacturing process.

This condition, if not corrected, could cause cracking of the affected part with consequent air leakage, which could result in high energy debris release (uncontained engine rotor failure), and/or in an engine uncontrolled fire, and thus subsequent loss of control of the aeroplane.

To address this potential unsafe condition, Airbus issued the SB, which refers to the NMSB, to provide instructions for the replacement of the affected parts, and a list of aeroplanes known to be close to the replacement Compliance Time, in order to prioritize logistic support.

For the reasons described above, this AD requires replacement of affected parts with serviceable parts, and provides criteria for installation of affected parts.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Replacement:

- (1) For Group 1 aeroplanes: Within the compliance time as defined in Table 1 of this AD, as applicable depending on EBAS T-Duct criteria, replace each affected part with a serviceable part, as defined in this AD, in accordance, with the instructions of the SB.



Table 1 – Affected EBAS T-Duct Criteria

EBAS T-Duct Criteria	Compliance Time (see Notes 1 and 2 of this AD)
The affected part has only been installed on A350-900 aeroplanes, and the FC are known or can be determined	Before exceeding 5 700 FC
The affected part has been installed on A350-900 and A350-1000 aeroplanes, or it cannot be determined on which aeroplanes it has been installed; and the FC are known or can be determined	Before exceeding 5 700 FC
The affected part has only been installed on A350-1000 aeroplanes and the FC are known or can be determined	Before exceeding 8 200 FC
The FC accumulated by the affected part cannot be determined	Within 20 months after the effective date of this AD

Note 1: The FC referred to in Table 1 of this AD are those accumulated by the affected part since new (first installation on an engine of an aeroplane).

Note 2: The NMSB provides instructions to determine the FC accumulated since new (first installation on an engine of an aeroplane) by an affected part.

Part Installation:

(2) For Group 1 and Group 2 aeroplanes: From the effective date of this AD, it is allowed to install an affected part on an engine of an aeroplane, provided that the affected part is a serviceable part. Following that installation, the aeroplane is effectively a Group 1, and that affected part must be replaced as required by paragraph (1) of this AD.

Ref. Publications:

Airbus Service Bulletin A350-36-P033 original issue dated 27 October 2023.

Rolls-Royce Alert NMSB TRENT XWB 36-AK870 original issue dated 29 September 2023.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on



a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.

5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS S.A.S. A350 XWB (1IAK), E-mail: continued-airworthiness.a350@airbus.com.

