



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2024-01-008	發布日期 Date issued	2024/01/26
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	A330-243, A330-302, A330-343 and A330-941 aeroplanes, manufacturer serial numbers (MSN) 1627, 1628, 1637, 1679, 1691, 1692, 1701, 1716, 1720, 1721, 1745, 1754, 1757, 1769, 1779, 1783, 1792, 1872, 1878, 1915, 1920, 1931, 1935, 1949, 1953, 1957, 1962, 1983, 1990, 1991, 1994, 1999, 2000 and 2010.		
主旨摘要 Subject	Equipment/Furnishings - Galley 4 Aft Bulkhead Cover Panel - Replacement		
民航局 CAA <input type="radio"/> 本國產品 Native product <input type="radio"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="radio"/> FAA <input type="radio"/> Germany LBA <input checked="" type="radio"/> EASA <input type="radio"/> CAA-NL <input type="radio"/> Brazil <input type="radio"/> UK CAA <input type="radio"/> Transport Canada Civil Aviation <input type="radio"/> Japan CAB <input type="radio"/> DGAC <input type="radio"/> CAA of Israel <input type="radio"/> Other____		
	設計國AD編號 Original AD number	2024-0023	
備註 Note	ATA 25. Ref. Publications: Airbus SB A330-25-3836 original issue dates 23 June 2023.		

註： 1. AD內容後附。

2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。

3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.

2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.

3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2024-0023

Issued: 23 January 2024

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A330 aeroplanes

Effective Date: 06 February 2024

TCDS Number(s): EASA.A.004

Foreign AD: Not applicable

Supersedure: None

ATA 25 – Equipment/Furnishings – Galley 4 Aft Bulkhead Cover Panel – Replacement

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

A330-243, A330-302, A330-343 and A330-941 aeroplanes, manufacturer serial numbers (MSN) 1627, 1628, 1637, 1679, 1691, 1692, 1701, 1716, 1720, 1721, 1745, 1754, 1757, 1769, 1779, 1783, 1792, 1872, 1878, 1915, 1920, 1931, 1935, 1949, 1953, 1957, 1962, 1983, 1990, 1991, 1994, 1999, 2000 and 2010.

Definitions:

For the purpose of this AD, the following definitions apply:

The SB: Airbus Service Bulletin (SB) A330-25-3836.

Affected part: Aft bulkhead cover panel, installed in galley G4, identified as 'affected part' and having a Part Number (P/N) as listed in Table 1 of this AD.

Serviceable part: Aft bulkhead cover panel, eligible for installation in galley G4, identified as 'serviceable part' and having a P/N as listed in Table 1 of this AD.



Reason:

It has been determined that certain aft bulkhead cover panels, installed in galley G4, have been manufactured from a material not in conformity with approved design data, and for which no demonstration of compliance against the heat release requirements (JAR 25.853 / Appendix F part IV) is available.

This condition, if not corrected, represents a non-compliance with certification requirements which could lead to injury to cabin crew and/or passengers, and reduced evacuation capacity from the aeroplane in case of an emergency.

To address this potential unsafe condition, Airbus issued the SB providing instructions to replace those parts with new parts, in conformity with the approved design data.

For the reason described above, this AD requires to replace affected parts with serviceable parts, and prohibits reinstallation of affected parts.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the actions required by this AD have been already accomplished:

Modification:

- (1) Within 12 months after the effective date of this AD, replace each affected part, as identified in Table 1 of this AD, with the correspondent serviceable part, as applicable, in accordance with the instructions of the SB.

Table 1 – Affected Parts and Serviceable Parts – P/N

Affected Part	Serviceable Part
G33DLAKGA000-01	G33DLAKGA000-02
G335KAKGA000-01	G335KAKGA000-02
3303DLBHGB00	3303DLBHGC00
330EVEBHGA00	330EVEBHGB00
3303FJBHGA00	3303FJBHGB00
330SAABHGB00	330SAABHGC00

Part(s) Installation:

- (2) After the modification of an aeroplane as required by paragraph (1) of this AD, do not (re)install an affected part on that aeroplane.

Ref. Publications:

Airbus SB A330-25-3836 original issue dates 23 June 2023.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.



Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 14 December 2023 as PAD 23-147 for consultation until 11 January 2024. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – 1IAL (Airworthiness Office), E-mail: airworthiness.A330-A340@airbus.com.

