



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2024-03-002B	發布日期 Date issued	2024/10/08
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers.		
主旨摘要 Subject	Pneumatic - Precooler Exchanger - Inspection		
民航局 CAA <input type="radio"/> 本國產品 Native product <input type="radio"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="radio"/> FAA <input type="radio"/> Germany LBA <input checked="" type="radio"/> EASA <input type="radio"/> CAA-NL <input type="radio"/> Brazil <input type="radio"/> UK CAA <input type="radio"/> Transport Canada Civil Aviation <input type="radio"/> Japan CAB <input type="radio"/> DGAC <input type="radio"/> CAA of Israel <input type="radio"/> Other_____		
	設計國AD編號 Original AD number	2024-0058R2	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as): 2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	This AD revises EASA AD 2024-0058R1(CAA-2024-03-002A) dated 16 April 2024, which revised EASA AD 2024-0058 dated 04 March 2024.		

註： 1. AD內容後附。
2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464,
adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332,
Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2024-0058R2

Issued: 04 October 2024

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A350 aeroplanes

Effective Date:

Revision 2: 11 October 2024

Revision 1: 23 April 2024

Original issue: 11 March 2024

TCDS Number(s):

EASA.A.151

Foreign AD:

Not applicable

Revision:

This AD revises EASA AD 2024-0058R1 dated 16 April 2024, which revised EASA AD 2024-0058 dated 04 March 2024.

ATA 36 – Pneumatic – Precooler Exchanger – Inspection

Manufacturer(s):

Airbus

Applicability:

Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The AOT: Airbus Alert Operators Transmission (AOT) A36P010-23.

Affected part: Pre-cooler exchanger (PCE) Part Number (P/N) 67200000-02.

Reason:

An occurrence was reported where, during a maintenance inspection, thrust reverser and pylon thermal blankets have been found damaged due to air leak coming from the PCE directly in the thermal blanket direction. Investigation is still on-going to understand the premature failure of the PCE.



This condition, if not detected and corrected, could result in blanket damage that, if combined with an independent event of engine fire, could lead to a temporary uncontrolled fire.

To address this potential unsafe condition, Airbus issued the AOT to provide test and inspection instructions for the affected parts.

For the reason described above, EASA issued AD 2024-0058 requiring repetitive leak test of the affected parts, and, depending on findings, accomplishment of additional inspection(s) and applicable corrective action(s). That AD required also reporting of leak test results.

After that AD was issued, it was determined that the accomplishment in shop of the Honeywell Component Maintenance Publication leak test task 36-11-36, paragraph 6 on a PCE is an acceptable method of compliance. Consequently, the EASA AD 2024-0058 was revised to add the Alternative Method of Compliance.

Since EASA AD 2024-0058R1 was issued Airbus published the AOT revision 02, updating the visual inspection procedure at step 5.6.B. iv. by adding instructions to accomplish additional inspections before contacting Airbus. This AD is revised accordingly.

This AD is still considered to be an interim action and further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the actions required by this AD have been already accomplished:

Repetitive Test(s):

- (1) Within the compliance time as defined in Table 1 of this AD, as applicable and, thereafter, at intervals not to exceed 100 flight cycles (FC), accomplish a leak test of each affected part in accordance with the instructions of the AOT.

Table 1 – Initial Inspection

Compliance Time (A or B, whichever occurs later)	
A	Before the PCE exceeds 5 500 FC since new (first installation on an aeroplane)
B	Before exceeding 100 FC or within 3 months, whichever occurs first after 11 March 2024 [the effective date of the original issue of this AD]

Inspection(s):

- (2) If, during any test as required by paragraph (1) of this AD, a leak is detected, perform visual inspection of the thermal blankets, in accordance with the instructions of the AOT.

Corrective Action(s):

- (3) If, during any test as required by paragraph (1) of this AD, a leak is detected, before next flight, replace that affected part in accordance with the instructions of the AOT.



- (4) If, during any inspection as required by paragraph (2) of this AD, any discrepancy, as defined in the AOT, is identified, before next flight, contact Airbus for approved repair instructions and accomplish those instructions accordingly (see Note 1 of this AD). Replacement of a damaged blanket can be accomplished in accordance with the instructions of the applicable Aircraft maintenance manual.

Note 1: AOT A36P010-23 revision 02 Step 5.6.B.iv. provides additional inspections instructions which can be accomplished before contacting Airbus.

Terminating Action(s):

- (5) None.

Reporting:

- (6) Within 30 days or 5 FC, whichever occurs later after the accomplishment of any leak test as required by paragraph (1) of this AD, report the leak test results, including no findings, to Airbus. This can be accomplished in accordance with the instructions of the AOT.

Part(s) Installation:

- (7) From 11 March 2024 [the effective date of the original issue of this AD], it is allowed to install a PCE on an aeroplane, provided, after that installation, leak tests of that PCE are accomplished as required by paragraph (1) of this AD. Following installation, the first leak test can be deferred until 5 500 FC since new (first installation) of that PCE on an aeroplane, or until 100 FC since last accomplishment of a leak test (no leak detected) of that PCE in accordance with the instructions of the AOT, as applicable. If no information is available to determine when next leak test must be accomplished, accomplish the leak test before next flight after installation.

Alternative Method of Compliance:

- (8) Accomplishment of leak test of an affected part in accordance with Honeywell Component Maintenance Publication 36-11-36, paragraph 6, is an acceptable alternative method to comply with the requirements of paragraphs (1) and (7) of this AD, as applicable, for that affected part.

Ref. Publications:

Airbus AOT A36P010-23 original issue dated 13 February 2024, or revision 01 dated 14 April 2024, or revision 02 dated 19 September 2024.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, the original issue of this AD was posted on 04 March 2024 as Final AD with Request for Comments, postponing the public consultation process until 01 April 2024. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed ('zipped') file, attached to the record for this AD.



3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS S.A.S. A350 XWB (1IAK), E-mail: continued-airworthiness.a350@airbus.com.

