



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2024-10-007	發布日期 Date issued	2024/10/18
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	This AD applies to The Boeing Company Model 737-300, -400, and -800 series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023; or Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023; as applicable.		
主旨摘要 Subject	This AD requires inspecting certain galleys to determine part numbers, inspecting for an existing galley modification placard and marking on galleys with affected part numbers, and replacing wire bundle spiral wrap sleeving as applicable.		
民航局 CAA	設計國民航主管機構 Original Authority		
<input type="radio"/> 本國產品 Native product	<input checked="" type="radio"/> FAA <input type="radio"/> Germany LBA <input type="radio"/> EASA <input type="radio"/> CAA-NL <input type="radio"/> Brazil <input type="radio"/> UK CAA <input type="radio"/> Transport Canada Civil Aviation <input type="radio"/> Japan CAB <input type="radio"/> DGAC <input type="radio"/> CAA of Israel <input type="radio"/> Other_____		
<input type="radio"/> 其他個案 Other			
	設計國AD編號 Original AD number	2024-18-08	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as): 2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	ATA 25. Ref. Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023. and Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023.		

註： 1. AD內容後附。
2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-1693; Project Identifier AD-2023-01229-T; Amendment 39-22842; AD 2024-18-08]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY:

Federal Aviation Administration (FAA), DOT.

ACTION:

Final rule.

SUMMARY:

The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-300, -400, and -800 series airplanes. This AD was prompted by a report that the protective spiral wrap used on certain galley wire bundles does not have the correct flammability properties. This AD requires inspecting certain galleys to determine part numbers, inspecting for an existing galley modification placard and marking on galleys with affected part numbers, and replacing wire bundle spiral wrap sleeving as applicable. This AD also prohibits the installation of affected parts. The FAA is issuing this AD to address the unsafe condition on these products.

DATES:

This AD is effective November 15, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 15, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2024-1693; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; [websitemyboeingfleet.com](http://www.boeingfleet.com).
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](http://www.regulations.gov) under Docket No. FAA-2024-1693.

FOR FURTHER INFORMATION CONTACT:

Julie Linn, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3584; email: julie.linn@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend [14 CFR part 39](#) by adding an AD that would apply to certain The Boeing Company Model 737-300, -400, and -800 series airplanes. The NPRM published in the **Federal Register** on June 24, 2024 ([89 FR 52408](#)). The NPRM was prompted by a report that the protective spiral wrap used on certain galley wire bundles does not have the correct flammability properties and may not self-extinguish. In the NPRM, the FAA proposed to require inspecting certain galleys to determine part numbers, inspecting for an existing galley modification placard and marking on galleys with affected part numbers, and replacing wire bundle spiral wrap sleeving as applicable; and to prohibit the installation of affected parts. The FAA is issuing this AD to address the incorrect flammability properties, which, if not addressed, could result in electrical arcing or sparking, ignition of the spiral wire wrapping, and smoke and/or fire in the flight compartment, leading to loss of continued safe flight and landing.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from the Air Line Pilots Association, who supported the NPRM without change.

The FAA received additional comments from Aviation Partners Boeing. The following presents the comments received on the NPRM and the FAA's response to each comment.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that the installation of winglets per Supplemental Type Certificate (STC) ST00830SE and STC ST01219SE does not affect the accomplishment of the manufacturer's service instructions.

The FAA agrees with the commenter that STC ST00830SE and STC ST01219SE do not affect the accomplishment of the manufacturer's service instructions. Therefore, the installation of STC ST00830SE and STC ST01219SE does not affect the ability to accomplish the actions required by this AD. The FAA has not changed this AD in this regard.

Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under [1 CFR Part 51](#)

The FAA reviewed Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023; and Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023. This material specifies procedures for an inspection or records check to determine the part number of certain galleys; and for any galley with an affected part number found, an inspection for an existing galley modification placard and any marking indicating the galley was modified using certain service information; and, if applicable, replacement of wire bundle polyethylene protective spiral wrap protective sleeving with Boeing Material Specification (BMS) 13-81 wire protective sleeving. These documents are distinct since they apply to different airplane models.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 4 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection for galley part number	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$340

The FAA estimates the following costs to do any necessary inspections or replacements that would be required based on the results of the inspection. The agency has no way of determining the number of aircraft that might need these inspections or replacements:

On-Condition Costs

Action	Labor cost	Parts cost	Cost per product
Inspection for modification placard	1 work-hour × \$85 per hour = \$85	\$0	\$85.
Replacement	Up to 218 work-hours × \$85 per hour = \$18,530	Up to \$1,185	Up to \$19,715.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under [Executive Order 13132](#). This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under [Executive Order 12866](#),
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in [14 CFR Part 39](#)

- Air transportation
- Aircraft
- Aviation safety
- Incorporation by reference
- Safety

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends [14 CFR part 39](#) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: [49 U.S.C. 106\(g\)](#), [40113](#), [44701](#).

[§.39.13](#) [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-18-08 The Boeing Company: Amendment 39-22842; Docket No. FAA-2024-1693; Project Identifier AD-2023-01229-T.

(a) Effective Date

This airworthiness directive (AD) is effective November 15, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-300, -400, and -800 series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023; or Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023; as applicable.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by a report that the protective spiral wrap used on certain galley wire bundles does not have the correct flammability properties and may not self-extinguish. The unsafe condition, if not addressed, could result in electrical arcing or sparking, ignition of the spiral wire wrapping, and smoke and/or fire in the flight compartment, leading to loss of continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For Model 737-300 and -400 series airplanes: Except as specified by paragraph (h)(1) of this AD, at the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023.

Note 1 to paragraph (g)(1): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-25A1873, dated August 25, 2023, which is referred to in Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023.

(2) For Model 737-800 series airplanes: Except as specified by paragraph (h)(2) of this AD, at the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023.

Note 2 to paragraph (g)(2): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-25A1876, dated September 1, 2023, which is referred to in Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023, refer to the original issue date of Requirements Bulletin 737-25A1873 RB, this AD requires using the effective date of this AD.

(2) Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023, refer to the original issue date of Requirements Bulletin 737-25A1876 RB, this AD requires using the effective date of this AD.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install a galley wire bundle spiral wrap made of polyethylene with self-wrapping sleeve on any airplane.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in [14 CFR 39.19](#). In accordance with [14 CFR 39.19](#), send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal

inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Julie Linn, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3584; email: julie.linn@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the address specified in paragraph (l)(3) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under [5 U.S.C. 552\(a\)](#) and [1 CFR part 51](#).

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-25A1873 RB, dated August 25, 2023.

(ii) Boeing Alert Requirements Bulletin 737-25A1876 RB, dated September 1, 2023.

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 6, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[[FR Doc. 2024-23541](#) Filed 10-10-24; 8:45 am]

BILLING CODE 4910-13-P