



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2025-03-004	發布日期 Date issued	2025/03/07
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes identified in Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024.		
主旨摘要 Subject	This AD requires an inspection or maintenance records check to determine if the primary exhaust nozzle has an affected part number and, for affected primary exhaust nozzles, an installation of bridge brackets onto the primary exhaust nozzle, or as an option, an installation of a serviceable primary exhaust nozzle, and also requires revising the existing maintenance or inspection program, as applicable, to incorporate new airworthiness limitations.		
民航局 CAA <input type="radio"/> 本國產品 Native product <input type="radio"/> 其他個案 Other	<div>設計國民航主管機構 Original Authority</div> <div><div><input checked="" type="radio"/> FAA <input type="radio"/> EASA <input type="radio"/> Brazil <input type="radio"/> Transport Canada Civil Aviation <input type="radio"/> DGAC</div><div><input type="radio"/> Germany LBA <input type="radio"/> CAA-NL <input type="radio"/> UK CAA <input type="radio"/> Japan CAB <input type="radio"/> CAA of Israel <input type="radio"/> Other_____</div></div>		
	設計國AD編號 Original AD number	2025-04-03	
	<div>1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as):</div> <div>2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)</div>		
備註 Note	ATA 78. Ref. Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024.		

- 註：
1. AD內容後附。
 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw

Note：1. The AD text is enclosed.

2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw

[Federal Register, Volume 90 Number 41 (Tuesday, March 4, 2025)]

[Rules and Regulations]

[Pages 11124-11129]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2025-03396]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-2235; Project Identifier AD-2023-01009-T; Amendment 39-22961; AD 2025-04-03]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY:

Federal Aviation Administration (FAA), DOT.

ACTION:

Final rule.

SUMMARY:

The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. This AD was prompted by two engine fan blade-out (FBO) events that resulted in the separation of engine inlet cowl and fan cowl parts from the airplane damaging the fuselage, which caused loss of pressurization and subsequent emergency descent. The FBO events also resulted in cracks in the primary exhaust nozzle, potentially resulting in the departure of the primary exhaust nozzle and damaging a stabilizer or striking the fuselage and window. This AD requires an inspection or maintenance records check to determine if the primary exhaust nozzle has an affected part number and, for affected primary exhaust nozzles, an installation of bridge brackets onto the primary exhaust nozzle, or as an option, an installation of a serviceable primary exhaust nozzle. This AD also requires revising the existing maintenance or inspection program, as applicable, to incorporate new airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES:

This AD is effective April 8, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 8, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-2235; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.
- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-2235.

FOR FURTHER INFORMATION CONTACT:

Luis Cortez-Muniz, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone: 206-231-3958; email: luis.a.cortez-muniz@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend [14 CFR part 39](#) by adding an AD that would apply to certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. The NPRM published in the **Federal Register** on December 12, 2023 ([88 FR 86080](#)). The NPRM was prompted by two engine FBO events that resulted in the separation of engine inlet cowl and fan cowl parts from the airplane damaging the fuselage, which caused loss of pressurization and subsequent emergency descent. The FBO events also resulted in cracks in the primary exhaust nozzle, potentially resulting in the departure of the primary exhaust nozzle and damaging a stabilizer or striking the fuselage and window. In the NPRM, the FAA proposed to require an inspection or maintenance records check to determine if the primary exhaust nozzle has an affected part number and, for affected primary exhaust nozzles, an installation of bridge brackets onto the primary exhaust nozzle, or as an option, an installation of a serviceable primary exhaust nozzle. The FAA also proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new airworthiness limitations. The FAA is issuing this AD to address the unsafe condition related to the primary exhaust nozzle that was also a result of the FBO events. During an FBO event, primary exhaust nozzles that are not strengthened could depart the engine, potentially damaging a stabilizer or striking the fuselage and window. This condition, if not addressed, could result in loss of control of the airplane, or in a rapid decompression and hazard to window-seated passengers aft of the wing.

Other Related Rulemaking

The FAA issued three NPRM ADs related to Exemption No. 19212A, dated September 7, 2023 (Docket No. FAA-2021-0681) (Exemption No. 19212A), which requires Boeing to develop modifications to the inlet cowl, fan cowl, and exhaust nozzle for operators to incorporate by July 31, 2028. Exemption No. 19212A further requires Boeing to provide solutions to address maintenance errors. Exemption No. 19212A also requires Boeing to develop airworthiness limitations for the modifications and solutions to address maintenance errors.

The NPRM for this AD, Docket No. FAA-2023-2235, refers to Boeing Special Attention Requirements Bulletin 737-78-1106, dated September 1, 2023, as the appropriate source of service information for

accomplishing the proposed modifications to the exhaust nozzle.

The NPRM for Docket No. FAA-2023-2234 ([88 FR 86069](#), December 12, 2023) refers to Boeing Special Attention Requirements Bulletin 737-71-1937, dated July 27, 2023, as the appropriate source of service information for accomplishing the proposed modifications to the fan cowl.

The NPRM for Docket No. FAA-2023-2236 ([88 FR 86084](#), December 12, 2023) refers to Boeing Special Attention Requirements Bulletin 737-71-1938, dated July 27, 2023, as the appropriate source of service information for accomplishing the proposed modifications to the inlet cowl.

All three NPRMs also proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new airworthiness limitations (System Airworthiness Limitations No. 2, No. 3, and No. 4).

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from Air Line Pilots Association, International (ALPA) who supported the NPRM without change.

The FAA received additional comments from 10 commenters, including AIRDO, All Nippon Airways, American Airlines, Aviation Partners Boeing, Boeing, Delta Airlines, Qantas, Southwest Airlines, Sun Country Airlines, and Virgin Australia Airlines. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request for Clarifying Part Interchangeability

Sun Country Airlines stated there is a possibility of an aircraft becoming out of compliance due to replacement of a modified exhaust nozzle with an unmodified exhaust nozzle. Sun Country Airlines stated that other rulemaking that has affected components has had wording identifying or limiting pre- and post-modification installation/interchangeability. The FAA infers Sun Country Airlines is requesting that the FAA add a note to the proposed AD to specify a modified exhaust nozzle cannot be replaced with an unmodified exhaust nozzle.

The FAA agrees to clarify. [14 CFR 39.7](#) specifies that once an AD is issued, no person may operate a product to which the AD applies except in accordance with the requirements of that AD. Further, [14 CFR 39.9](#) imposes a continuing obligation to maintain compliance with an AD by establishing a separate violation for each time an aircraft is operated that fails to meet AD requirements. Thus, operators have an ongoing obligation to ensure that the AD-mandated configuration is maintained. Additionally, it is not possible to install an affected primary exhaust nozzle on airplanes not identified in the applicability of this AD. Therefore, adding the part restriction note would not be necessary since all affected Boeing Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes are required to accomplish Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024. The FAA has not changed this AD in this regard.

Request To Refer to Later Revisions of the Service Information

Southwest Airlines requested that the FAA change paragraphs (g) and (h) of the proposed AD to reference Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, which is pending publication. Southwest Airlines asked that the FAA not publish the AD until the release of Revision 1 and allow credit for previous accomplishment of the original issue of the requirements bulletin.

The FAA has reviewed Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024. This revision adds airplane line numbers 1245, 1614, 1810, 1839, 1885, 1934, 1979, 1991, 2080, 2157, 2232, 2531, 2822, 3071, 3189, and 3319 to the effectivity (which were listed in paragraph (c)(2) of the proposed AD). This revision also adds “System Airworthiness Limitation No. 4—Engine Nacelle Maintenance Errors” to the actions to incorporate airworthiness limitations. The AWLs are now incorporated into Revision 1 of Boeing Special Attention Requirements Bulletin 737-78-1106 RB. This information can now be required via Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, instead of as an exception to the service information.

In addition to incorporating the AWL information that was specified in figure 1 to the introductory text of paragraph (h) of the proposed AD, the only other changes to the “Compliance” paragraph and Accomplishment Instructions of Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, were to reference the NPRM, clarify Note 1 that describes the “Enhanced Required for Compliance” document, clarify a certain part nomenclature and clarify the location of a certain pin. None of these changes substantively affect the required actions on operators but instead are clarifying.

Therefore, the FAA has revised this AD to refer to Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, including revising the applicability of this AD to only refer to Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, since the line numbers identified in paragraph (c)(2) of the proposed AD are included in the service information. The FAA also added paragraph (j) of this AD to provide credit for previous work performed prior to the effective date of this AD.

Request for AWL Compliance Time Extension

AIRDO, All Nippon Airways, American Airlines, Delta Air Lines, Sun Country Airlines, Qantas, and Virgin Australia Airlines requested the compliance time for revising the existing maintenance or inspection program be extended from before further flight as specified in the proposed AD to a longer compliance time. Compliance time requests varied from 30 days to 12 months. Some commenters stated that the “before further flight” requirement should be removed altogether. Several commenters noted that incorporating the AWLs before further flight after modification was not possible since the AWLs were not published at the same time as the modification bulletins. Qantas requested that for airplanes on which the modification specified in Boeing Special Attention Requirements Bulletin 737-78-1106 RB has already been done, the FAA allow figure 1 to the introductory text of paragraph (h) of the proposed AD to be incorporated within 30 days after the effective date of the AD instead of before further flight after accomplishing actions specified in Boeing Special Attention Requirements Bulletin 737-78-1106 RB. Virgin Australian Airlines requested credit for completing the modification of the exhaust nozzle prior to the AD's effective date. Sun Country Airlines also expressed concern that the AWL revision and updated requirements have not been approved or released via normal distribution channels.

The FAA disagrees with changing the compliance time but acknowledges the concern regarding the compliance time for airplanes on which the modification was done prior to adoption of this AD and availability of the updated AWL. However, the requirement to incorporate the AWLs before further flight is in accordance with Exemption No. 19212A, Docket No. FAA-2021-0681 and is part of the change to type design. The FAA provided a time-limited exemption (TLE) to Boeing, Exemption No. 19212A. The TLE includes a limitation to require the AWLs to be incorporated as part of the type design for each of the modifications which include engine inlet, fan cowl and fan cowl support beam, and exhaust nozzle. As the modification plus the AWL is required to maintain a compliant design, the AD will maintain the “before further flight” requirement.

The FAA also notes that paragraph (f) of this AD states to accomplish the required actions within the compliance times specified, “unless already done.” Therefore, if operators have accomplished the modification and incorporation of the AWLs required for compliance with this AD before the effective date of this AD, no further action is necessary.

Request the Removal of AWL Incorporation

American Airlines, Delta Air Lines, Sun Country Airlines, Southwest Airlines, and Qantas requested removing the requirements to incorporate some or all of the AWLs specified in the proposed AD (System Airworthiness Limitations No. 2, No. 3, and No. 4). The commenters pointed out that paragraph (h) of the proposed AD specifies incorporating certain AWLs included in Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01. The commenters noted that the current Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01 does not include the AWLs specified in figure 1 to the introductory text to paragraph (h) of the proposed AD, which are vague and do not provide a definitive action to address the unsafe condition identified in the proposed AD. Qantas stated that operators do not have instructions to modify the inlet cowls and fan cowls in Boeing Special Attention Requirements Bulletin 737-78-1106 RB, and suggested that System Airworthiness Limitation No. 2 be removed from the proposed AD and only be located in the NPRM for Docket No. FAA-2023-2234 and the NPRM for Docket No. FAA-2023-2236 where it is more suited.

Sun Country Airlines stated System Airworthiness Limitation No. 4 does not appear to be related to the events that prompted the NPRM and is not related to the intent of this ruling. Southwest stated that incorporating System Airworthiness Limitation No. 4 places responsibility on the operator, rather than the manufacturer, to be compliant and produce solutions. Southwest added that Boeing has a responsibility to define “potential maintenance errors” and to provide specific modification or inspection procedures to mitigate those errors. Some commenters also raised concerns that an immediate change to the maintenance program would not provide additional safety measures. American Airlines expressed further concern that the new proposed requirements may result in airplanes being out of revenue service while waiting on an operator's Certificate Management Office (CMO) to process the maintenance program change. Delta recommended that the FAA transfer the AWL requirements into a separate AD.

The FAA disagrees with removing some or all of the AWLs specified in this AD. The FAA requirement to incorporate the AWLs before further flight is in accordance with the modifications required by Exemption No. 19212A to address the unsafe condition. Furthermore, the TLE includes a limitation to require that the AWLs be incorporated as part of the type design for modifications to the engine inlet, fan cowl and fan cowl support beam, and exhaust nozzle. Therefore, once one of the modification bulletins (Boeing Special Attention Requirements Bulletins 737-71-1937 RB, 737-71-1938 RB, and 737-78-1106 RB) is accomplished, all the AWLs specified in this AD need to be incorporated into the operators' maintenance program so the operator can maintain a compliant design and address the unsafe condition. System Airworthiness Limitations No. 2, No. 3, and No. 4 were created to address the TLE requirements and the unsafe condition.

A new version of the AWLs has been released, Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01, dated January 2024, that includes the AWLs identified in figure 1 to the introductory text of paragraph (h) of the proposed AD. Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, includes procedures to incorporate those new AWLs. Therefore, the FAA has determined that incorporating the new AWLs must be done as part of the requirements of this AD and not in a separate AD.

Request To Change AWL Compliance Time

Southwest Airlines suggested either a service data due date of December 31, 2024 to align with the time-limited exemption, Exemption No. 19212A be added to the proposed AD or that the FAA remove the AWL requirements from the proposed AD. Southwest Airlines stated System Airworthiness Limitations No. 2, No. 3, and No. 4 do not provide a defined date for Boeing to release all service data to operators. Therefore, without a defined date for Boeing to release all service data, there is concern that operators may not be given sufficient time to perform the required modifications prior to the AD's completion due date.

The FAA disagrees with the commenter's request. As previously mentioned, a new AWL revision has been released that includes the System Airworthiness Limitations No. 2 and No. 3, and No. 4. The service information for System Airworthiness Limitations No. 2 and No. 3 has been released, *i.e.*, Boeing Special Attention Requirements Bulletin 737-71-1938, dated July 27, 2023, and Revision 1, dated June 27, 2024; Boeing Special Attention Requirements Bulletin 737-71-1937, dated July 27, 2023, and Revision 1, dated June 27, 2024; and Boeing Special Attention Requirements Bulletin 737-78-1106, dated September 1, 2023, and Revision 1, dated May 23, 2024. Although service information to address System Airworthiness Limitation No. 4 has not yet been released, the FAA has coordinated with Boeing to better understand the requirements of System Airworthiness Limitation No. 4, which requires the incorporation of solutions to address potential engine nacelle maintenance errors into operators' maintenance programs. The solutions are intended to prevent the unlatching of the fan cowl and fan cowl integrated drive generator (IDG) door in flight. The solutions will consist of a re-designed fan cowl latch and keeper and application of high visibility paint on the interior of the IDG door. The FAA has added an exception to paragraph (h)(2) of this AD to clarify solutions as required in AWL No. 4. Operators have until December 31, 2029, to incorporate solutions to address potential maintenance errors as specified in AWL No. 4 and clarified in this AD.

Request for Clarification Regarding AWL Requirement

Delta Air Lines, Qantas, and American Airlines asked for clarification on what would be required to meet System Airworthiness Limitations No. 2, No. 3, and No. 4. The commenters stated adequate instructions are not included in the AWLs. Therefore, additional details are needed to clarify these requirements and provide a clear path to comply with the AWLs specified in figure 1 to the introductory text of paragraph (h) of the proposed AD. Furthermore, certain operators do not believe this meets [14 CFR 43.16](#), and System Airworthiness Limitation No.4 is an unexpected demand.

The FAA agrees to clarify. Accomplishing the modification specified in Boeing Special Attention Requirements Bulletins 737-71-1938 RB, 737-71-1937 RB, and 737-78-1106 RB satisfies the requirements of System Airworthiness Limitations No. 2 and No. 3. This also satisfies the requirement of [14 CFR 43.16](#) to perform inspections or maintenance in accordance with the AWLs.

As denoted in paragraph 4., "Approval" of Boeing Special Attention Requirements Bulletin 737-71-1938, Revision 1, dated June 27, 2024, the accomplishment of that requirements bulletin meets the requirements of item (1) of Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01 "SYSTEM AIRWORTHINESS LIMITATION NO. 2."

As denoted in paragraph 4., "Approval" of Boeing Special Attention Requirements Bulletin 737-71-1937, Revision 1, dated June 27, 2024, the accomplishment of that requirements bulletin meets the requirements of items (2) and (3) of Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01 "SYSTEM AIRWORTHINESS LIMITATION NO. 2."

As denoted in paragraph 4., "Approval" of Boeing Special Attention Requirements Bulletin 737-78-1106, Revision 1, dated May 23, 2024, the accomplishment of that requirements bulletin meets the requirements of Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs)

As previously stated, the FAA coordinated with Boeing to determine potential maintenance errors that require solutions in accordance with System Airworthiness Limitation No. 4. To comply with this AD and the System Airworthiness Limitation No. 4, solutions will consist of a re-designed fan cowl latch and keeper and application of high visibility paint on the interior of the IDG door. If any specific service information is provided or further solutions are incorporated to address potential maintenance errors, the FAA may consider further rulemaking.

Request for Change to Exception (System Airworthiness Limitation No. 4)

Boeing requested appending the following statement to the end of System Airworthiness Limitation No. 4.: “Boeing will release all service data to enable full compliance for the CFM56-7B nacelle for addressing potential maintenance errors prior to that date.” Boeing stated that the statement would correspond to the systems included in AWL No. 2 and 3.

The FAA agrees to clarify. As previously mentioned, the recently released new Boeing AWL document includes System AWL No. 4. The new AWL includes the text as requested by Boeing. Therefore, no change to this AD is necessary.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing (APB) stated that the installation of winglets per supplemental type certificate (STC) ST00830SE on applicable Boeing models subject to the proposed rule does not affect compliance with the mandated actions in this AD.

The FAA agrees with the commenter that STC ST00830SE does not affect the ability to accomplish the actions required by this AD. The FAA has not changed this AD in this regard.

Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Material Incorporated by Reference Under [1 CFR Part 51](#)

The FAA reviewed Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024. This material specifies procedures for a maintenance records check, or an inspection of the engine to identify if the engine has a primary exhaust nozzle with an affected part number. For affected primary exhaust nozzles, the service information specifies procedures for installing bridge brackets onto the primary exhaust nozzle, or as an option, installing a serviceable exhaust nozzle onto the engine. This material also specifies the incorporation of Boeing 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01 “System Airworthiness Limitation NO. 2—Fan Blade Out Conditions,” “System Airworthiness Limitation NO. 3—Fan Blade Out Conditions”, and “System Airworthiness Limitation NO. 4—Engine Nacelle Maintenance errors” into the operator's maintenance or inspection program.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES** .

Costs of Compliance

The FAA estimates that this AD affects 1,215 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect for affected part numbers or maintenance records check	2 work-hours × \$85 per hour = \$170	\$0	\$170	\$206,550.
Bridge bracket installation.*	Up 23 work-hours × \$85 per hour = \$1,955	Up \$63,200	Up to \$65,155	Up to \$79,163,325.**

* The option to install a serviceable primary exhaust nozzle would cost up to \$65,155 per product.

** Not all airplanes will have an affected primary exhaust nozzle so the fleet cost will be significantly lower.

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the agency estimates the average total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under [Executive Order 13132](#). This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under [Executive Order 12866](#),

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in [14 CFR Part 39](#)

- Air transportation
- Aircraft
- Aviation safety
- Incorporation by reference
- Safety

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends [14 CFR part 39](#) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: [49 U.S.C. 106\(g\)](#), [40113](#), [44701](#).

[§ 39.13](#) [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025-04-03 The Boeing Company: Amendment 39-22961; Docket No. FAA-2023-2235; Project Identifier AD-2023-01009-T.

(a) Effective Date

This airworthiness directive (AD) is effective April 8, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes identified in Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024.

(d) Subject

Air Transport Association (ATA) of America Code 78, Exhaust.

(e) Unsafe Condition

This AD was prompted by two engine fan blade-out (FBO) events that resulted in the separation of engine inlet cowl and fan cowl parts from the airplane damaging the fuselage, which caused loss of pressurization and subsequent emergency descent. The FBO events also resulted in cracks in the primary exhaust nozzle, which could result in the departure of the primary exhaust nozzle. The FAA is

issuing this AD to address primary exhaust nozzles that are not strengthened, which during an FBO event, could depart the engine, potentially damaging a stabilizer or striking the fuselage and window. The unsafe condition, if not addressed, could result in loss of control of the airplane, or in a rapid decompression and hazard to window-seated passengers aft of the wing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Special Attention Service Bulletin 737-78-1106, Revision 1, dated May 23, 2024, which is referred to in Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024.

(h) Exceptions to Requirements Bulletin Specifications

(1) Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, refer to the original issue date of Requirements Bulletin 737-78-1106 RB, this AD requires using the effective date of this AD.

(2) Where System Airworthiness Limitation No. 4, as identified in Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024, requires incorporation of solutions to address potential engine nacelle maintenance errors, solutions consist of a re-designed fan cowl latch and keeper and application of high visibility paint on the interior of the integrated drive generator (IDG) door.

(i) No Alternative Actions

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions may be used unless the actions are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k) of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Requirements Bulletin 737-78-1106 RB, dated September 1, 2023, provided where Tables 1 and 2 of Boeing Special Attention Requirements Bulletin 737-78-1106 RB specify incorporating 737-600/700/700C/800/900/900ER Airworthiness Limitations (AWLs) Document D626A001-9-01 “System Airworthiness Limitation NO. 2—Fan Blade Out Conditions,” and “System Airworthiness Limitation NO. 3—Fan Blade Out Conditions” into the operators' maintenance program, the information specified in figure 1 to paragraph (j) of this AD has been incorporated into the airworthiness limitations.

Figure 1 to Paragraph (j)—System Airworthiness Limitations

SYSTEM AIRWORTHINESS LIMITATION No. 2
FAN BLADE OUT CONDITIONS
All aircraft must install the following modifications: (1) engines inlets with new spacer design and increased fastener capability (2) fan cowls with new radial restraint fitting hooks, new radial restraint clips, and an external doubler at the starter vent (3) fan cowl support beam fastener changes (except for 737-900ER aircraft, because the fan cowl support beam fastener changes are already incorporated). All aircraft that have not incorporated these modifications cannot operate past July 31, 2028 unless upgraded to new hardware that is fully compliant to §§ 25.901(c) and Appendix K25.1.1 to Part 25. Boeing will release all service data to allow retrofit of hardware updates to the CFM56-7B nacelle prior to that date.
SYSTEM AIRWORTHINESS LIMITATION No. 3
FAN BLADE OUT CONDITIONS
All aircraft delivered without the Performance Improvement Package (PIP) must install engine exhaust nozzle structural stiffening elements. All aircraft that have not incorporated these modifications cannot operate past July 31, 2028 unless upgraded to new hardware that is fully compliant to §§ 25.901(c) and Appendix K25.1.1 to Part 25. Boeing will release all service data to allow retrofit of hardware updates to CFM56-7B nacelle prior to that date.
SYSTEM AIRWORTHINESS LIMITATION No. 4
ENGINE NACELLE MAINTENANCE ERRORS
All aircraft must incorporate solutions to address potential maintenance errors, <i>e.g.</i> , the failure to completely latch the fan cowl or the can cowl integrated drive generator (IDG) door. All aircraft that have not incorporated changes to become fully compliance with §§ 25.901(c) and Appendix K25.1.1 to Part 25 cannot be operated past December 31, 2029.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in [14 CFR 39.19](#). In accordance with [14 CFR 39.19](#), send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact Luis Cortez-Muniz, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone: 206-231-3958; email: luis.a.cortez-muniz@faa.gov.

(2) Boeing material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (m)(3) this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under [5 U.S.C. 552\(a\)](#) and [1 CFR part 51](#).

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Requirements Bulletin 737-78-1106 RB, Revision 1, dated May 23, 2024.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on February 25, 2025.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[[FR Doc. 2025-03396](#) Filed 3-3-25; 8:45 am]

BILLING CODE 4910-13-P