



# 適航指令發布單

## Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2026-04-007	發布日期 Date issued	2026/05/08												
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	This AD applies to The Boeing Company Model 787-8, 787-9, and 787-10 airplanes, certificated in any category, as specified in Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022.														
主旨摘要 Subject	This AD retains the requirements of AD 2023-08-04(CAA-2023-05-007) and requires, for certain airplanes, a detailed inspection of all clam shell couplings for the presence and correct installation of safety straps at door 1 and door 3 lavatories and galleys with a potable water system and applicable on-condition actions, which would terminate the existing requirements. This AD also prohibits the installation of affected parts at inspection locations.														
民航局 CAA  <input type="radio"/> 本國產品 Native product  <input type="radio"/> 其他個案 Other	<div style="text-align: center;">設計國民航主管機構 Original Authority</div> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%; border: none;"><input checked="" type="radio"/> FAA</td> <td style="width: 50%; border: none;"><input type="radio"/> Germany LBA</td> </tr> <tr> <td style="border: none;"><input type="radio"/> EASA</td> <td style="border: none;"><input type="radio"/> CAA-NL</td> </tr> <tr> <td style="border: none;"><input type="radio"/> Brazil</td> <td style="border: none;"><input type="radio"/> UK CAA</td> </tr> <tr> <td style="border: none;"><input type="radio"/> Transport Canada Civil Aviation</td> <td style="border: none;"><input type="radio"/> Japan CAB</td> </tr> <tr> <td style="border: none;"><input type="radio"/> DGAC</td> <td style="border: none;"><input type="radio"/> CAA of Israel</td> </tr> <tr> <td style="border: none;"></td> <td style="border: none;"><input type="radio"/> Other_____</td> </tr> </table>			<input checked="" type="radio"/> FAA	<input type="radio"/> Germany LBA	<input type="radio"/> EASA	<input type="radio"/> CAA-NL	<input type="radio"/> Brazil	<input type="radio"/> UK CAA	<input type="radio"/> Transport Canada Civil Aviation	<input type="radio"/> Japan CAB	<input type="radio"/> DGAC	<input type="radio"/> CAA of Israel		<input type="radio"/> Other_____
<input checked="" type="radio"/> FAA	<input type="radio"/> Germany LBA														
<input type="radio"/> EASA	<input type="radio"/> CAA-NL														
<input type="radio"/> Brazil	<input type="radio"/> UK CAA														
<input type="radio"/> Transport Canada Civil Aviation	<input type="radio"/> Japan CAB														
<input type="radio"/> DGAC	<input type="radio"/> CAA of Israel														
	<input type="radio"/> Other_____														
	設計國AD編號 Original AD number	2026-09-01													
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as) : b. 執行時限另訂為(Re-specify the compliance time or period as) : 2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)														
備註 Note	This AD replaces AD 2023-08-04(CAA-2023-05-007)														

註： 1. AD內容後附。  
 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。  
 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, [adcaa@mail.caa.gov.tw](mailto:adcaa@mail.caa.gov.tw)

Note： 1. The AD text is enclosed.  
 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.  
 3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, [adcaa@mail.caa.gov.tw](mailto:adcaa@mail.caa.gov.tw)

[Federal Register, Volume 91 Number 82 (Wednesday, April 29, 2026)]

[Rules and Regulations]

[Pages 23005-23008]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2026-08306]

---

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. FAA-2025-1114; Project Identifier AD-2025-00314-T; Amendment 39-23321; AD 2026-09-01]**

**RIN 2120-AA64**

### **Airworthiness Directives; The Boeing Company Airplanes**

#### **AGENCY:**

Federal Aviation Administration (FAA), DOT.

#### **ACTION:**

Final rule.

#### **SUMMARY:**

The FAA is superseding Airworthiness Directive (AD) 2023-08-04, which applied to certain The Boeing Company Model 787-8, 787-9, and 787-10 airplanes. AD 2023-08-04 required a detailed visual inspection of all door 1 and door 3 lavatory and galley potable water systems for any missing or incorrectly installed clamshell couplings, and applicable on-condition actions. This AD was prompted by discoveries by Boeing that some couplings did not have the required safety strap and that they have developed a design solution that replaces the couplings with couplings that have safety straps. This AD retains the requirements of AD 2023-08-04 and requires, for certain airplanes, a detailed inspection of all clamshell couplings for the presence and correct installation of safety straps at door 1 and door 3 lavatories and galleys with a potable water system and applicable on-condition actions, which would terminate the existing requirements. This AD also prohibits the installation of affected parts at inspection locations. The FAA is issuing this AD to address the unsafe condition on these products.

#### **DATES:**

This AD is effective June 3, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 3, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain other

publication listed in this AD as of June 29, 2023 ([88 FR 33823](#), May 25, 2023).

## ADDRESSES:

*AD Docket:* You may examine the AD docket at *regulations.gov* under Docket No. FAA-2025-1114; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

### *Material Incorporated by Reference:*

- For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website *myboeingfleet.com*.
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at *regulations.gov* under Docket No. FAA-2025-1114.

## FOR FURTHER INFORMATION CONTACT:

Joshua Baek, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 562-627-6725; email: [joshua.y.baek@faa.gov](mailto:joshua.y.baek@faa.gov).

## SUPPLEMENTARY INFORMATION:

### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend [14 CFR part 39](#) to supersede AD 2023-08-04, Amendment 39-22419 ([88 FR 33823](#), May 25, 2023) (AD 2023-08-04). AD 2023-08-04 applied to certain The Boeing Company Model 787-8, 787-9, and 787-10 airplanes. The NPRM was published in the **Federal Register** on July 3, 2025 ([90 FR 29512](#)). The NPRM was prompted by reports of a loss of water pressure during flight and water leaks that affected multiple pieces of electronic equipment. In the NPRM, the FAA proposed to continue to retain the requirements of AD 2023-08-04 and require, for certain airplanes, a detailed inspection of all clamshell couplings for the presence and correct installation of safety straps at door 1 and door 3 lavatories and galleys with a potable water system and applicable on-condition actions, which would terminate the existing requirements. Additionally, Model 787-10 airplanes were included in the applicability of the NPRM to prevent the installation of affected parts on Model 787-10 airplanes as required by the Parts Installation Prohibition paragraph of this AD. The FAA is issuing this AD to prevent the unsafe condition, which, if not addressed, could lead to water leaks and water migration to critical flight equipment, which may affect the continued safe flight and landing of the airplane.

## Discussion of Final Airworthiness Directive

### Comments

The FAA received comments from the Air Line Pilots Association, International (ALPA), and United Airlines who supported the NPRM without change.

The FAA received additional comments from Boeing, Turkish Airlines (THY), Kenya Airlines, an individual commenter, and The Foundation for Aviation Safety. The following presents the comments received on the NPRM and the FAA's response to each comment.

### **Request for Clarification on Applicability**

Boeing requested clarification on why Model 787-10 airplanes were included in the applicability of the proposed AD. Boeing stated that the Background section of the proposed AD includes Model 787-10 airplanes, although the applicability of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025, is limited to the Model 787-8 and 787-9 airplanes. Boeing noted that revising the Background section to explain that Model 787-10 airplanes were included because of the Parts Installation Prohibition paragraph would avoid confusion.

The FAA agrees to clarify. This AD retains the requirements of paragraph (g) of AD 2023-08-04, which incorporates by reference (IBR) Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022, which applies to Boeing Model 787-8, 787-9, and 787-10 airplanes. In addition, some Model 787-10 airplanes may not have been inspected as required by AD 2023-08-04; therefore, the Parts Installation Prohibition paragraph in this AD also applies to Model 787-10 airplanes. For these reasons, the Background section of this AD has been revised to clarify that Model 787-10 airplanes are included because of the Parts Installation Prohibition requirement of this AD.

### **Request To Revise Listed Part Numbers**

Turkish Airlines requested the FAA revise the Parts Installation Prohibition paragraph in the proposed AD that prohibits installation of (P/N) 14C02-08C or P/N AS1655A08. Turkish Airlines explained that P/N AS1655A08 is listed in THY illustrated parts data (IPD) 38-10-01-10 as the specification number for P/N 14C02-08A, and therefore it would be applicable to all THY Model 787 airplanes.

The FAA agrees and has revised the Parts Installation Prohibition paragraph in this AD to identify these part numbers as “P/N 14C02-08C (AS1655C08)” and “P/N 14C02-08A (AS1655A08)”.

### **Request for Clarification on Applicability and Parts Installation Prohibition Requirements**

Turkish Airlines requested clarification on whether the replacement required by the Parts Installation Prohibition paragraph in the proposed AD would apply to its fleet, given that Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025, is not applicable to Turkish Airlines. Turkish Airlines also requested clarification on whether it would be required to perform any actions specified in the Parts Installation Prohibition paragraph for airplanes that are not included in the Effectivity of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025.

The FAA provides the following clarification. The Parts Installation Prohibition paragraph does not describe an action; rather, it prohibits installation of affected part numbers in locations where they have been replaced with approved part numbers. The Parts Installation Prohibition paragraph applies to all airplanes identified in the Applicability paragraph of this AD. Therefore, the Parts

Installation Prohibition paragraph of this AD applies to any Turkish Airlines airplanes included in the Applicability paragraph of this AD, even if those airplanes are not listed in the Effectivity of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025.

### **Request for Credit for Previous Actions**

Kenya Airways requested the FAA include an additional paragraph in the NPRM to provide credit for the actions required by the New Required Actions paragraph if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin B787-81205-SB250299-00 RB, Issue 001, dated July 31, 2023. Kenya stated that it has accomplished Boeing Alert Service Bulletin B787-81205-SB250299-00 RB, Issue 001, dated July 31, 2023, on some of its airplanes, and therefore requested credit for those completed actions.

The FAA disagrees with the request. Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 001, dated July 31, 2023, omits certain inspection locations. As a result, Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 001, dated July 31, 2023, does not fully address the unsafe condition, and therefore cannot be credited. No changes have been made to this AD in this regard.

### **Request To Clarify the Parts Installation Prohibition Paragraph**

An individual commenter requested the FAA confirm the correct part number referenced as “P/N 14C33-08” in paragraph (m) of the proposed AD. The commenter noted that the listed part number is inconsistent with Boeing documentation and industry parts catalogs, which list “P/N 14C34-08C”. The commenter also requested clarification that the parts installation prohibition applies only to new installations and that properly installed units may remain in service until the next scheduled replacement. The commenter stated that paragraph (m) prohibits installation of P/N 14C02-08C and P/N AS1655A08 at affected locations but does not distinguish between existing and new installations.

The FAA provides the following clarification. The Parts Installation Prohibition paragraph in this AD has been revised as described previously. Both P/N 14C34-08C and P/N 14C33-08 are valid replacement parts; therefore, P/N 14C02-08C (AS1655C08) or P/N 14C02-08A (AS1655A08) may be replaced with either P/N 14C34-08C or P/N 14C33-08. Additionally, paragraph (m) of this AD specifies that the prohibited part numbers cannot be installed in locations where they have been replaced with valid part numbers, indicating that the parts installation prohibition only applies to new installations where the affected parts have already been replaced with P/N 14C34-08C or P/N 14C33-08.

### **Request To Define Inspection Locations**

An individual commenter requested the FAA define the term “inspection locations” as the clamshell coupling points at door 1 and door 3 lavatories and galleys and include a note or diagram to that effect. The commenter stated that the term was not defined in the regulatory text of the proposed AD and could be misconstrued to include all potable-water system fittings.

The FAA disagrees with the request. The inspection locations are defined in Table 5 of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025. Table 5 instructs operators to “Do a Detailed Inspection (DET) of all clamshell couplings at Door 1 and Door 3 lavatories and galleys with potable water system for a safety strap and that clamshell

coupling with a safety strap is correctly installed.” Therefore, the inspection locations are already defined in the referenced service information. No changes have been made to this AD in this regard.

### **Request To Consolidate Cross-Referenced Documents**

An individual commenter requested the FAA provide a consolidated compliance table within the regulatory text or as a standalone matrix in the proposed AD. The commenter stated that the proposed AD incorporated six separate service documents with distinct information that could be technically misinterpreted.

The FAA disagrees that the quantity of service documents referenced in this AD will lead to technical misinterpretation. The issue dates of each referenced service document are identified in this AD. The FAA has determined that the current structure of this AD provides the most accurate and enforceable method for identifying the required actions. No changes have been made to this AD in this regard.

### **Request for Broader Action To Address Water Intrusion Issues**

The FAA received a comment from the Foundation for Aviation Safety asking how many additional water intrusion issues might occur as the airplane ages and what the FAA is doing to ensure that Boeing maintains manufacturing quality to prevent leaks. The Foundation for Aviation Safety also suggested that all affected airplanes be inspected and undergo leak detection testing rather than waiting for electrical or electronic failures.

The FAA acknowledges the commenter's concerns. However, the questions and suggestions provided are general in nature and are not specific to the unsafe condition addressed in this AD. Broader concerns regarding potential future water intrusion issues and fleetwide leak detection testing are outside the scope of this AD. Therefore, no changes have been made to this AD in this regard.

### **Conclusion**

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

### **Material Incorporated by Reference Under [1 CFR Part 51](#)**

The FAA reviewed Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025. This material specifies procedures for a detailed inspection for the presence and correct installation of safety straps at the clamshell couplings at door 1 and door 3 lavatories and galleys with a potable water system. The material also specifies applicable on-condition actions including correcting the installation of the safety strap, replacing any clamshell coupling that does not have a strap with a new clamshell coupling that has a safety strap, and performing a water leak test.

This AD also requires Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022, which the Director of the Federal Register approved for incorporation by reference as of June 29, 2023 ([88 FR 33823](#), May 25, 2023).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

### Costs of Compliance

The FAA estimates that this AD affects 165 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

#### Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Clamshell coupling inspection, per lavatory/galley (retained actions from AD 2023-08-04)	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$14,025.
Safety strap inspection, per lavatory/galley (new action) (For 787-8 and -9 airplanes)	27 work-hours × \$85 per hour = \$2,295, per lavatory/galley	0	\$2,295 per lavatory/galley	\$238,680 (104 airplanes).

The FAA estimates the following costs to do any on-condition actions that would be required based on the results of the inspections. The agency has no way of determining the number of aircraft that might need these actions:

#### On-Condition Costs

Action	Labor cost	Parts cost	Cost per product
Correct installation for clamshell coupling with safety strap that was installed incorrectly	1 work-hour × \$85 per hour = \$85 per lavatory/galley	\$0	\$85 per lavatory/galley.
Install clamshell coupling with strap and perform leak test	4 work-hours × \$85 per hour = \$340 per lavatory/galley	Up to \$267 per lavatory/galley	\$607 per lavatory/galley.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

This AD will not have federalism implications under [Executive Order 13132](#). This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under [Executive Order 12866](#),
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in [14 CFR Part 39](#)

- Air transportation
- Aircraft
- Aviation safety
- Incorporation by reference
- Safety

## The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends [14 CFR part 39](#) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** [49 U.S.C. 106\(g\)](#), [40113](#), [44701](#).

#### [§ 39.13](#) [Amended]

2. The FAA amends § 39.13 by:

a. Removing Airworthiness Directive (AD) 2023-08-04, Amendment 39-22419 ( [88 FR 33823](#), May 25, 2023); and

b. Adding the following new AD:

**2026-09-01 The Boeing Company:** Amendment 39-23321; Docket No. FAA-2025-1114; Project Identifier AD-2025-00314-T.

#### (a) Effective Date

This airworthiness directive (AD) is effective June 3, 2026.

**(b) Affected ADs**

This AD replaces AD 2023-08-04, Amendment 39-22419 ([88 FR 33823](#), May 25, 2023) (AD 2023-08-04).

**(c) Applicability**

This AD applies to The Boeing Company Model 787-8, 787-9, and 787-10 airplanes, certificated in any category, as specified in Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022.

**(d) Subject**

Air Transport Association (ATA) of America Code 38, Water/waste.

**(e) Unsafe Condition**

This AD was prompted by reports of a loss of water pressure during flight and water leaks that affected multiple pieces of electronic equipment, and by the determination that some clamshell couplings for certain lavatory and galley doors did not have a required safety strap. The FAA is issuing this AD to prevent the unsafe condition, which, if not addressed, could lead to water leaks and water migration to critical flight equipment, which may affect the continued safe flight and landing of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Clamshell Coupling Inspection, With No Changes**

This paragraph restates the requirements of paragraph (g) of AD 2023-08-04, with no changes. Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022.

*Note 1 to paragraph (g):* Guidance for accomplishing the actions required by paragraph (g) of this AD can be found in Boeing Alert Service Bulletin B787-81205-SB380021-00, Issue 001, dated August 12, 2022, which is referred to in Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022.

**(h) Retained Exception to Service Information Specifications, With No Changes**

This paragraph restates the exception of paragraph (h) of AD 2023-08-04, with no changes. Where the Compliance Time columns of the table in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022, refer to the Issue 001 date of Requirements Bulletin B787-81205-SB380021-00 RB, this AD requires using June 29, 2023 (the effective date of AD 2023-08-04).

**(i) Retained Credit for Previous Actions, With No Changes**

This paragraph restates the provisions of paragraph (i) of AD 2023-08-04, with no changes. This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before June 29, 2023 (the effective date of AD 2023-08-04), using Multi Operator Message MOM-MOM-21-0554-01B, dated December 14, 2021 (for lavatory inspections); and MOM-MOM-22-0229-01B, dated April 29, 2022 (for galley inspections).

#### **(j) New Required Actions**

For airplanes identified in Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025: Except as specified by paragraph (k) of this AD, at the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025.

*Note 2 to paragraph (j):* Guidance for accomplishing the actions required by paragraph (j) of this AD can be found in Boeing Alert Service Bulletin B787-81205-SB250299-00, Issue 002, dated February 28, 2025, which is referred to in Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025.

#### **(k) New Exception to Service Information Specifications**

Where the Compliance Time column of the table in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025, uses the phrase “the Issue 001 date of Requirements Bulletin B787-81205-SB250299-00 RB,” this AD requires using the effective date of this AD.

#### **(l) Terminating Action for Clamshell Coupling Inspection**

For the airplanes identified in Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025: Accomplishment of the actions required by paragraph (j) of this AD terminates the requirements of paragraph (g) of this AD.

#### **(m) Parts Installation Prohibition**

As of the effective date of this AD, no person may install a clamshell coupling, part number (P/N) 14C02-08C (AS1655C08) or P/N 14C02-08A (AS1655A08), at inspection locations where P/N 14C02-08C (AS1655C08) or P/N 14C02-08A (AS1655A08) was replaced with P/N 14C34-08C or P/N 14C33-08 on any airplane.

#### **(n) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in [14 CFR 39.19](#). In accordance with [14 CFR 39.19](#), send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (o)(1) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(o) Additional Information**

(1) For more information about this AD, contact Joshua Baek, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 562-627-6725; email: [joshua.y.baek@faa.gov](mailto:joshua.y.baek@faa.gov).

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (p)(5) of this AD.

**(p) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under [5 U.S.C. 552\(a\)](#) and [1 CFR part 51](#).

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following material was approved for IBR on June 3, 2026.

(i) Boeing Alert Requirements Bulletin B787-81205-SB250299-00 RB, Issue 002, dated February 28, 2025.

(ii) [Reserved]

(4) The following material was approved for IBR on June 29, 2023 ([88 FR 33823](#), May 25, 2023).

(i) Boeing Alert Requirements Bulletin B787-81205-SB380021-00 RB, Issue 001, dated August 12, 2022.

(ii) [Reserved]

(5) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

(6) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(7) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on April 21, 2026.

Victor Wicklund,

Acting Director, Integrated Certificate Management Division, Aircraft Certification Service.

[[FR Doc. 2026-08306](#) Filed 4-28-26; 8:45 am]

BILLING CODE 4910-13-P