



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2026-05-005	發布日期 Date issued	2026/05/21
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	MBB-BK117 D-3 and D-3m helicopters, all serial numbers (s/n).		
主旨摘要 Subject	Main Rotor Drive - Rotor Hub-Shaft - Inspection		
民航局 CAA	設計國民航主管機構 Original Authority		
<input type="radio"/> 本國產品 Native product	<input type="radio"/> FAA	<input type="radio"/> Germany LBA	
<input type="radio"/> 其他個案 Other	<input checked="" type="radio"/> EASA	<input type="radio"/> CAA-NL	
	<input type="radio"/> Brazil	<input type="radio"/> UK CAA	
	<input type="radio"/> Transport Canada Civil Aviation	<input type="radio"/> Japan CAB	
	<input type="radio"/> DGAC	<input type="radio"/> CAA of Israel	
		<input type="radio"/> Other_____	
	設計國AD編號 Original AD number	2026-0091	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as) : b. 執行時限另訂為(Re-specify the compliance time or period as) :		
	2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	This AD supersedes EASA AD 2026-0078-E(CAA-2026-05-004) dated 13 April 2026.		

註： 1. AD內容後附。

2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。

3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464,

adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.

2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.

3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332,

Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2026-0091

Issued: 08 May 2026

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS HELICOPTERS DEUTSCHLAND GmbH

Type/Model designation(s):

MBB-BK117 D-3 and D-3m helicopters

Effective Date: 15 May 2026

TCDS Number(s): EASA.R.010

Foreign AD: Not applicable

Supersedure: This AD supersedes EASA AD 2026-0078-E dated 13 April 2026.

ATA 63 – Main Rotor Drive – Rotor Hub-Shaft – Inspection

Manufacturer(s):

Airbus Helicopters (AH); Airbus Helicopters Deutschland GmbH; Kawasaki Heavy Industries Ltd.; and Airbus Helicopters Inc.

Applicability:

MBB-BK117 D-3 and D-3m helicopters, all serial numbers (s/n).

Definitions:

For the purpose of this AD, the following definitions apply:

The EASB: AH Emergency Alert Service Bulletin (EASB) MBB-BK117-63-21-0002 issue 002.

Affected Part: Rotor hub-shaft, manufacturer part number (MP/N) D623M1501203 and MP/N D623M1501204.

Reason:

An occurrence has been reported of a crack on the affected part of a helicopter, which was detected during the troubleshooting accomplished after that the crew reported increased vibration of the helicopter.



This condition, if not corrected, could lead to failure of the main rotor transmission, possibly resulting in loss of control of the helicopter.

To address this potential unsafe condition, AH issued the original issue of EASB MBB-BK117-63-21-0002, providing instructions for inspection of the affected part. Consequently, EASA published AD 2026-0078-E to require inspections of the affected parts, and, depending on findings, to contact AH for reporting and for applicable corrective action(s).

Since that AD was issued, AH issued the EASB, as defined in this AD, to update the compliance time inspection thresholds and add recurring inspections.

For the reasons described above, this AD retains the requirements of EASA AD 2026-0078-E, which is superseded, and additionally requires repetitive inspections of the affected parts.

This AD is still considered an interim action and further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Inspection(s):

- (1) Within the compliance time as identified in Table 1 of this AD, as applicable, accomplish an inspection of the affected part in accordance with the instructions of the EASB.

Table 1 – Initial Inspection (see Note 1 and 2 of this AD)

Inspection Threshold	Compliance Time
900 FH TSN or less and 1 year TSM or less	Within 15 FH or 7 days, whichever occurs first after the affected part accumulates 900 FH TSN or 1 year TSM
900 FH TSN or less and more than 1 year TSM	A or B, whichever occurs first: A) Within 15 FH or 7 days, whichever occurs first after the affected part accumulates 900 FH TSN or B) Within 15 FH or 7 days, whichever occurs first after the effective date of this AD
More than 900 FH TSN and less than 3 000 FH TSN	Within 15 FH or 7 days, whichever occurs first after 15 April 2026 [the effective date of EASA AD 2026-0078-E]
3 000 FH TSN or more	Before next flight after 15 April 2026 [the effective date of EASA AD 2026-0078-E]



Note 1: Unless otherwise specified, the flight hours (FH) time since new (TSN) specified in Table 1 of this AD are those accumulated on 15 April 2026 [the effective date of EASA AD 2026-0078-E] by the affected part since first installation on any helicopter.

Note 2: Unless otherwise specified, the time since manufacture (TSM) specified in Table 1 of this AD is that accumulated on the effective date of this AD by the affected part since manufacturing. If unknown, the date of release of the EASA Form 52 of the helicopter (or equivalent statement of conformity) applies instead.

- (2) From 15 April 2026 [the effective date of EASA AD 2026-0078-E], within 5 FH after each reporting of noticeable changes in vibrations, or balancing abnormalities of a helicopter, accomplish an inspection of the affected part in accordance with the instructions of the EASB (see Note 3 of this AD).

Note 3: The requirements of paragraph (2) of this AD are applicable for any affected part, disregarding the TSM and the number of FH TSN accumulated by that part.

Repetitive Inspection(s):

- (3) Within the compliance time as identified in Table 2 of this AD, as applicable, and, thereafter, at intervals not to exceed 100 FH or 1 year, whichever occurs first, accomplish an inspection of the affected part in accordance with the instructions of the EASB (see Note 4 of this AD).

Table 2 – Repetitive Inspection

FH accumulated on the effective date of this AD after the inspection as required by paragraph (1) of this AD	Compliance Time
More than 100 FH	Within 15 FH or 7 days, whichever occurs first after the effective date of this AD
100 FH or less	A or B, whichever occurs later: A) Within 100 FH or 1 year, whichever occurs first after the inspection as required by paragraph (1) of this AD or B) Within 15 FH or 7 days, whichever occurs first after the effective date of this AD

Note 4: A non-cumulative tolerance of 10 FH may be applied to the 100 FH interval specified in paragraph (3) to allow synchronization of the required inspections with other maintenance tasks, for which a tolerance is already granted in the applicable Maintenance Manual.

Corrective Action(s):

- (4) If, during any inspection as required by paragraph (1), (2) or (3) of this AD, as applicable, any discrepancy, as defined in the EASB, is detected on an affected part, before next flight, replace that affected part in accordance with the instructions of the EASB.



Reporting:

- (5) If, during any inspection as required by paragraph (1), (2) or (3) of this AD, as applicable, any discrepancy, as defined in the EASB, is detected on an affected part, within 7 days after that inspection, report the inspection result to AH. The EASB provides instructions which are acceptable for compliance with this reporting requirement.

Part(s) Installation:

- (6) From 15 April 2026 [the effective date of EASA AD 2026-0078-E], it is allowed to install an affected part on any helicopter provided that it is new (not previously installed on any helicopter), or that, concurrently with that installation, that part passes (no discrepancy, as defined in the EASB, is detected) an inspection in accordance with the instructions of the EASB and, thereafter, it is inspected as required by this AD.

Credit:

- (7) Inspection(s) and corrective action(s), as applicable, accomplished on a helicopter before the effective date of this AD in accordance with the instructions of AH EASB MBB-BK117-63-21-0002 at issue 001 (original issue) are acceptable for compliance with the requirements of paragraph (1) and (4) of this AD, as applicable, for that helicopter.

Terminating action:

- (8) None.

Ref. Publications:

AH EASB MBB-BK117-63-21-0002 issue 001 (original issue) dated 13 April 2026 and issue 002 dated 04 May 2026.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication. All interested persons may send their comments, referencing the AD Number, to the E-mail address specified in below Remark 3, prior to 05 June 2026. Only if any comment is received during the consultation period, a Comment Response Document will be published in the [EASA Safety Publications Tool](#), in a compressed ('zipped') file, attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than



those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.

5. For any question concerning the technical content of the requirements in this AD, please contact: Airbus Helicopters Deutschland GmbH, Industriestrasse 4, 86609 Donauwörth, Federal Republic of Germany, Telephone: + 33 (0)4 42 85 97 97;
Web portal: <https://airbusworld.helicopters.airbus.com/>
E-mail: customersupport.helicopters@airbus.com.

