



交通部民用航空局飛安公告

Aviation Safety Bulletin

ASB No: 111-067/O

February 14, 2022

Subject:

Enhance training on wet/slippery runways/taxiways maneuvering and enhance situational awareness under hazardous weather conditions to ensure flight safety.

Description:

An ROC-registered B744F veered off the taxiway before entering the ramp area after it landed in heavy snow. The flight crew applied differential thrust for an assisted turn, which led to a controllability problem and skidded the aircraft causing engines 1 and 2 to collide with bulk containers.

Recommendations:

1. Operators shall enhance crew training taxiing on wet/slippery runways/taxiways and include it within their recurrent training subjects for winter operations.
2. Before dispatch, if weather conditions at the destination airport may cause contamination of runways and taxiways, flight crew shall brief the relative countermeasures.
3. Awareness of directional controllability shall be raised while taxiing on wet/slippery runways/taxiways. Flight crew shall stop the aircraft and ask for tow service whenever hesitant about its controllability.