



Civil Aeronautics Administration

Aviation Safety Bulletin

ASB No: 93-002/CS

DEC, 2004

Subject :

After the periodical C-check, an aircraft was released to service and operated in non-compliance with required equipment (e.g. Passenger Safety Information Cards, Emergency Locator Transmitter) not installed for her first flight.

Background :

Investigation reveals that the pertinent operation personnel including cabin attendant, maintenance personnel, contracted airport ground handling service agent did not follow the SOPs to conduct Pre-flight checks.

The event may happen due to lack of coordination between associated sections and human errors, which are concluded to systemic deficiencies in operation control and management.

Recommendation :

The operators shall :

1. Review the subject such as dock-in and dock-out checklist and establish procedures to enhance operation control before the aircraft is returned to service.
2. Define duties and responsibilities of operation personnel concerned, and implement adequate pre-flight check procedures to meet the regulatory requirements.
3. Designate the adequate entity to follow up the corrective actions through self-audit system to preclude recurrence of similar case.