



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2019-01-007	發布日期 Date issued	2019/1/17
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	A320-214, A320-271N, A321-211 and A321-231 aeroplanes, manufacturer serial numbers (MSN) as listed in Appendix 1 of this AD.		
主旨摘要	25 - Equipment / Furnishings - Cabin Attendant Seat - Modification		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%;"> <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 50%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	2019-0005	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 25. Ref. Publications: Airbus SB A320-25-1BEK original issue dated 18 November 2016. and Airbus SB A320-25-1BEL original issue dated 18 November 2016. and Goodrich SB 2427-25-001 revision C dated 21 October 2016. and Goodrich SB 2428-25-001 revision D dated 09 November 2016. and Goodrich SB 2431-25-001 revision D dated 09 November 2016.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2019-0005

Issued: 14 January 2019

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A320 and A321 aeroplanes

Effective Date: 28 January 2019

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: None

ATA 25 – Equipment / Furnishings – Cabin Attendant Seat – Modification

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

A320-214, A320-271N, A321-211 and A321-231 aeroplanes, manufacturer serial numbers (MSN) as listed in Appendix 1 of this AD.

Definitions:

For the purpose of this AD, the following definitions apply:

The applicable SB: Airbus Service Bulletin (SB) A320-25-1BEK and SB A320-25-1BEL, as applicable.

Goodrich SB: Goodrich SB 2427-25-001, Goodrich SB 2428-25-001 and Goodrich SB 2431-25-001.

Affected part: Cabin attendant seat as identified in the effectivity of Goodrich SB.

Reason:

During a test of a new wall partition for cabin attendant seat model 2428, the backrest was found permanently deformed and did not allow the seat pan to return to a full-up position. Investigation results identified that a heat treatment had not been applied on certain backframes, which could lead to permanent deformation of the seat backrest.



This condition, if not corrected, could reduce the escape path through the adjacent exit door in case of evacuation, possibly resulting in injury to aeroplane occupants.

To address this potential unsafe condition, Airbus issued the applicable SB, which refer to Goodrich SB, providing instructions to modify affected parts by replacing the backframe, and to add a placard after modification.

For the reasons described above, this AD requires modification of the affected parts.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Modification(s):

- (1) Within 24 months after the effective date of this AD, modify each affected part in accordance with the instructions of the applicable SB.

Reporting:

- (2) Within 30 days after modification of an affected part as required by paragraph (1) of this AD, or within 30 days after the effective date of this AD, whichever occurs later, report that action to Airbus. This can be done using the address monitored.retrofit@airbus.com or in accordance with the instructions of the SB.

Ref. Publications:

Airbus SB A320-25-1BEK original issue dated 18 November 2016.

Airbus SB A320-25-1BEL original issue dated 18 November 2016.

Goodrich SB 2427-25-001 revision C dated 21 October 2016.

Goodrich SB 2428-25-001 revision D dated 09 November 2016.

Goodrich SB 2431-25-001 revision D dated 09 November 2016.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 14 December 2018 as PAD 18-177 for consultation until 11 January 2019. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.



4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51;
E-mail: account.airworth-eas@airbus.com.



Appendix 1

List of affected MSN:

Airbus SB	Aeroplane model	Affected MSN					
A320-25-1BEK	A320-214, A321-211, A321-231	6669	6672	6704	6736	6770	6773
		6787	6793	6804	6825	6835	6838
		6845	6848	6867	6889	6891	6897
		6910	6926	6939	6947	6953	6976
A320-25-1BEL	A320-271N	6801					

