

Aviation Safety Bulletin

ASB No: 89/010/ O

April,2000

Subject:

CVR (Cockpit Voice Recorder) Deactivation procedure.

Background:

In the recent MD-80s incident,the flight crew did not deactivate the CVR, thus resulting in continuous operation of the CVR and erasing the Pertinent CVR information.

Recommendation:

In accordance with CAA regulation, operators are required to deactivate CVR and DFDR immediately after an accident / incident so as to retain the data needed for investigation.

All operators are responsible for the establishment of pertinent S.O.P.in the management of above-mentioned situation.