



Civil Aeronautics Administration

Aviation Safety Bulletin

ASB No: 92-027/OPS

August 18, 2003

Subject :

Flight crew shall comply with the ATC radio procedure to READ BACK the ATC instructions and change frequency as advised.

Background :

During approach, a revenue flight of national airline's flight crew suspected not READ BACK the tower instructions 「hold short of runway XXR」, and arbitrarily change frequency from tower to ground. After got the permit from ground, this aircraft cross runway XXR that caused a taking off flight to abort take-off.

Recommendation :

1. Please notice all flight crew to comply with the ATC instruction and radio procedures to read back the 「mandatory READ BACK ATC instructions」, and change frequency by advised.
2. Due to the busy cockpit work loads after landing, PF and PNF both have to well cooperate and monitor the on going communicating channel to know the vicinity aircrafts movement.
3. The 121.5MHZ channel shall contiguously be guarded by crew, for reasons of safety.