

 適航指令發布單 Airworthiness Directive Issuance Form		
民航局 AD 編號 AD number	CAA-2007-05-002Cancellation 發布日期 Date issued	2018/1/30
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	ARRIEL 2B, 2B1, 2B1A, 2C, 2C1, 2C2, 2S1 and 2S2 engines, if previously used by an operator (e.g. military) who is not under the safety oversight of a civil aviation authority. These engines are known to be installed on, but not limited to, Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale) AS 350 B3, AS 365 N3, EC 130 B4 and EC 155 B1 helicopters; and Sikorsky S-76C helicopters.	
主旨摘要	CANCELLED: ATA 72 - Engines Formerly Used by Non-Civil Operators - Civil Use	
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____	
	設計國 AD 編號 Original AD number	2007-0117-CN
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)	
備註 Note	ATA 72. This Notice cancels EASA AD 2007-0117(CAA-2007-05-002) dated 02 May 2007. Ref. Publications: The related Safran Helicopter Engines or Turboméca SB is specified in the relevant TCDS EASA.E.001 (hyperlink provided above).	
註： Note：	1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel:(02)2349-6331~3, Fax:(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw	



Airworthiness Directive Cancellation Notice

AD No.: 2007-0117-CN

Issued: 24 January 2018

Note: This Airworthiness Directive (AD) Cancellation Notice (CN) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

Design Approval Holder's Name:

SAFRAN HELICOPTER ENGINES

Type/Model designation(s):

ARRIEL 2 engines

Effective Date: 24 January 2018

TCDS Number(s): [EASA.E.001](#)

Foreign AD: Not applicable

Cancellation: This Notice cancels EASA AD 2007-0117 dated 02 May 2007.

CANCELLED: ATA 72 – Engines Formerly Used by Non-Civil Operators – Civil Use

Manufacturer(s):

SAFRAN Helicopter Engines, formerly Turboméca, S.A.

Applicability:

ARRIEL 2B, 2B1, 2B1A, 2C, 2C1, 2C2, 2S1 and 2S2 engines, if previously used by an operator (e.g. military) who is not under the safety oversight of a civil aviation authority.

These engines are known to be installed on, but not limited to, Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale) AS 350 B3, AS 365 N3, EC 130 B4 and EC 155 B1 helicopters; and Sikorsky S-76C helicopters.

Reason:

Engines that have been operated and maintained outside the framework of a civil aviation regime may have a configuration that does not (or no longer) conform to the original approved type definition. This may concern the modification standard, the applied repair schemes, or the maintenance programme for critical parts. In addition, the operating limits approved during civil certification and, in particular, life limits based on normal civil operation cycles, may also have been exceeded on these engines. As a consequence, for the purposes of civil aviation, these engines are considered to be not airworthy.

EASA issued AD 2007-0117 to define the conditions for returning ARRIEL 2 engines to service in a civil regime, containing the instructions for restoring an engine to conformity.



Since that AD was issued, EASA considered that, because installation of a non-airworthy (e.g. ex-military use) engine is not legally permitted unless certain actions are taken, it is not necessary to address this kind of 'safety risk' by AD action. Consequently, a reference to a Service Bulletin (SB), containing the relevant instructions, has been incorporated in a Note in the applicable Type Certificate Data Sheet (TCDS).

For the reasons described above, this Notice cancels EASA AD 2007-0117.

Required Action(s) and Compliance Time(s):

None

Ref. Publications:

The related Safran Helicopter Engines or Turboméca SB is specified in the relevant TCDS EASA.E.001 (hyperlink provided above).

Remarks:

1. This AD-CN was posted on 13 December 2017 as PAD 17-171-CN for consultation until 10 January 2018. No comments were received during the consultation period.
2. Enquiries regarding this AD-CN should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. For any question concerning the technical content of this AD-CN, please contact: SAFRAN Helicopter Engines, Customer Support, 40220 Tarnos, France, Fax: +33 5 59 74 45 15, or contact [SAFRAN on-line for technical assistance](#).

