



## 適航指令發布單

### Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2020-04-010	發布日期 Date issued	2020/4/29
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers.		
主旨摘要	Time Limits / Maintenance Checks - Safe Life Airworthiness Limitations Items - ALS Part 1 - Amendment		
<div style="text-align: center;">民航局 CAA</div> <input type="checkbox"/> 本國產品 Native products  <input type="checkbox"/> 其他個案 Other	<div style="text-align: center;">設計國民航主管機構 Original Authorities</div> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%;"> <input type="checkbox"/> FAA  <input checked="" type="checkbox"/> EASA  <input type="checkbox"/> Brazil  <input type="checkbox"/> Transport Canada Civil Aviation  <input type="checkbox"/> DGAC         </div> <div style="width: 50%;"> <input type="checkbox"/> Germany LBA  <input type="checkbox"/> CAA-NL  <input type="checkbox"/> UK CAA  <input type="checkbox"/> Japan CAB  <input type="checkbox"/> CAA of Israel  <input type="checkbox"/> Other _____         </div> </div>		
	設計國 AD 編號 Original AD number	2020-0091	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 05. Ref. Publications: Airbus A350 ALS Part 1 Revision 04 dated 14 September 2018, and Variation 4.3 dated 07 June 2019.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： <a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a> Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： <a href="mailto:adcaa@mail.caa.gov.tw">adcaa@mail.caa.gov.tw</a>			



## Airworthiness Directive

**AD No.:** 2020-0091

**Issued:** 22 April 2020

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

### Design Approval Holder's Name:

AIRBUS

### Type/Model designation(s):

A350 aeroplanes

**Effective Date:** 06 May 2020

**TCDS Number(s):** EASA.A.151

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 05 – Time Limits / Maintenance Checks – Safe Life Airworthiness Limitations Items – ALS Part 1 – Amendment

### Manufacturer(s):

Airbus

### Applicability:

Airbus A350-941 and A350-1041 aeroplanes, all manufacturer serial numbers.

### Definitions:

For the purpose of this AD, the following definitions apply:

**The ALS:** Airbus A350 Airworthiness Limitations Section (ALS) Part 1, Revision 04, including Variation 4.3.

**The AMP:** The approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane. For affected A350 aeroplanes registered in Europe, compliance with the approved AMP is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph 3.



**New and/or more restrictive tasks:** This includes all tasks that are new and all tasks for which a threshold or interval was reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS Revision that is currently incorporated in the AMP.

**Reason:**

The airworthiness limitations for the Airbus A350 aeroplanes, which are approved by EASA, are currently defined and published in the A350 ALS document(s). The Safe Life Airworthiness Limitation Items are specified in ALS Part 1. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

Improvement of safe life component selection and life extension campaigns resulted in life limitation changes, among others new or more restrictive life limitations, which have been approved by EASA. Consequently, Airbus issued the ALS, compiling all previously approved changes to ALS Part 1.

For the reason described above, this AD requires accomplishment of the actions specified in the ALS.

**Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

**Maintenance Tasks and Replacement of Life Limited Parts:**

- (1) From the effective date of this AD, replace each component before exceeding the applicable life limit, as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration (see Note 1 of this AD).

Note 1: For the purpose of this AD, the thresholds as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks.

**AMP Revision:**

- (2) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

**Credit:**

- (3) If, before the effective date of this AD, the AMP has been revised to incorporate the tasks and limitations as specified in a previous revision of ALS Part 1, that action ensures the continued accomplishment of those tasks and limitations.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations, as applicable to aeroplane model and depending on aeroplane configuration, as defined in, and within the compliance times (see Note 1 of this AD) as specified in, the ALS, to comply with paragraph (1) of this AD.



For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations, as applicable to aeroplane model and depending on aeroplane configuration, as defined in the ALS, into the AMP to comply with paragraph (2) of this AD.

#### **Recording AD Compliance:**

- (4) When the AMP of an aeroplane has been revised as required by paragraph (2) or (3) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraph (1) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (2) or (3) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

#### **Ref. Publications:**

Airbus A350 ALS Part 1 Revision 04 dated 14 September 2018, and Variation 4.3 dated 07 June 2019.

The use of later approved revisions or variations of the above-mentioned document is acceptable for compliance with the requirements of this AD.

#### **Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 12 March 2020 as PAD 20-048 for consultation until 09 April 2020. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS A350 XWB, E-mail: [continued-airworthiness.a350@airbus.com](mailto:continued-airworthiness.a350@airbus.com).

