



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2020-10-013	發布日期 Date issued	2020/10/19
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-252N, A321-253N, A321-271N, A321-272N, A321-251NX, A321-252NX, A321-253NX, A321-271NX and A321-272NX aeroplanes, all manufacturer serial numbers.		
主旨摘要	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment		
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input type="checkbox"/> UK CAA <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	2020-0219	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ <input type="checkbox"/> 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do <input type="checkbox"/> Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	ATA 05. This AD requires new and/or more restrictive tasks which are introduced through Airbus A318/A319/A320/A321 ALS Part 3 Variation 7.1 dated 10 June 2020.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Airworthiness Directive

AD No.: 2020-0219

Issued: 12 October 2020

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A318, A319, A320 and A321 aeroplanes

Effective Date: 26 October 2020

TCDS Number(s): EASA.A.064

Foreign AD: Not applicable

Supersedure: None

ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 3 – Certification Maintenance Requirements – Amendment

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-252N, A321-253N, A321-271N, A321-272N, A321-251NX, A321-252NX, A321-253NX, A321-271NX and A321-272NX aeroplanes, all manufacturer serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The Variation: Airbus A318/A319/A320/A321 Airworthiness Limitations Section (ALS) Part 3 Variation 7.1.

The AMP: The approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane. For A318,



A319, A320 and A321 aeroplanes operated under EU regulation, compliance with the approved AMP is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301, paragraph 3.

New and/or more restrictive tasks: This includes all tasks that are new and all tasks for which a threshold or interval was reduced, which were introduced through the Variation (as defined in this AD) since the previous ALS Revision that is currently incorporated in the AMP.

Reason:

The airworthiness limitations for the Airbus A320 family aeroplanes, which are approved by EASA, are currently defined and published in the A318/A319/A320/A321 ALS document(s). These instructions have been identified as mandatory for continued airworthiness. The airworthiness limitations applicable to the Certification Maintenance Requirements are specified in ALS Part 3.

Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2020-0067, to require accomplishment of all maintenance tasks as described in ALS Part 3 at Revision 07.

Since that AD was issued, Airbus published the Variation, as defined in this AD, which contains new and/or more restrictive tasks that will be incorporated in the next ALS Part 3 revision.

For the reason described above, this AD requires accomplishment of the actions specified in the Variation. EASA AD 2020-0067 is not superseded by this AD.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, within the thresholds and intervals as defined in the Variation (see Note 1 of this AD), accomplish the actions, as specified in the Variation, as applicable to aeroplane model and depending on aeroplane configuration.

Where this AD requires a task which is already required per EASA AD 2020-0067, the instructions of the Variation invalidate the instructions of Airbus A318, A319, A320 and A321 ALS Part 3 Revision 07 for that task.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the 'Compliance Time' pages of the Variation include specific compliance times for certain tasks.

Corrective Action(s):

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable Airbus maintenance documentation. If a detected discrepancy cannot be corrected by using existing Airbus instructions, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.



AMP Revision:

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the tasks and associated thresholds and intervals described in the Variation, as applicable to aeroplane model and depending on aeroplane configuration.

Recording AD compliance:

- (4) When the AMP of an aeroplane has been revised as required by paragraph (3) of this AD, that action ensures continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) of this AD, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Ref. Publications:

Airbus A318/A319/A320/A321 ALS Part 3 Variation 7.1 dated 10 June 2020.

The use of later approved revisions of this document, or ALS Part 3 revisions later than 07, is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 01 September 2020 as PAD 20-129 for consultation until 29 September 2020. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – IIASA; E-mail: account.airworth-eas@airbus.com.

