



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2023-02-005	發布日期 Date issued	2023/2/10
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	All BN2, BN2A, BN2B, BN2T, BN2T-4R and BN2T-4S series Islander aeroplanes fitted with FHL or BNA Landing Gear, and All BN2A-MkIII series Trislander aeroplanes fitted with FHL or BNA Landing Gear.		
主旨摘要 Subject	Landing Gear – Nose and Main Landing Gear – Recording of life / Replacement		
<div style="text-align: center;">民航局 CAA</div> <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	<div style="text-align: center;">設計國民航主管機構 Original Authority</div> <div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> FAA <input type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input checked="" type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div>		
	設計國 AD 編號 Original AD number	G-2023-0001	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	This AD supersedes UK AD G-2003-0013(CAA-2003-11-010) dated 05 November 2003		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax： (02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Civil Aviation Authority

AIRWORTHINESS DIRECTIVE

Number: G-2023-0001

Issue date: 08 February 2023



Note: In this Airworthiness Directive, references to EU regulations are to those regulations as retained and amended in UK domestic law under the European Union (Withdrawal) Act 2018 and are referenced as "UK Regulation (EU) year/number or UK Regulation (EU) No. number/year".

This Airworthiness Directive (AD) is issued by the UK CAA in accordance with UK Regulation (EU) No. 748/2012 Part 21.A.3B, acting as the Authority of the State of Design for the affected product(s), under Article 34 of the Air Navigation Order 2016 (ANO) and UK Regulation (EU) 2018/1139.

In accordance with UK Regulation (EU) No. 1321/2014 Annex I (Part-M), M.A.301 / Annex VB (Part-ML), ML.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified or agreed by the CAA [Part-M, M.A.303 / Part-ML, ML.A.303].

This is a Final AD with Request for Comments and is issued in accordance with the UK CAA Continuing Airworthiness Process. All interested persons may send their comments, referencing the AD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated in the Remarks section.

Design Approval Holder's Name:

Type/Model Designation(s):

BRITTEN-NORMAN AIRCRAFT LTD

BN2 Islander and Trislander aeroplanes

Effective Date:	22 February 2023
TCDS :	UK.TC.00042 (BN2 Islander) and UK.TC.00043 (BN2A Mk III Trislander)
Foreign AD (if applicable):	Not Applicable
Superseding AD:	This AD supersedes UK AD G-2003-0013 dated 05 November 2003

ATA 32 – Landing Gear – Nose and Main Landing Gear – Recording of life / Replacement

Manufacturer(s):

Britten-Norman Aircraft Ltd

Applicability:

All BN2, BN2A, BN2B, BN2T, BN2T-4R and BN2T-4S series Islander aeroplanes fitted with FHL or BNA Landing Gear, and

All BN2A-MkIII series Trislander aeroplanes fitted with FHL or BNA Landing Gear.

Definitions:

The SB: Britten-Norman Service Bulletin 298 (SB 298).

Reason:

It was determined that in order to ensure the continued structural integrity of certain Islander and Trislander landing gear and associated components that it is necessary to require removal of these components from service prior to exceeding established fatigue lives. Accordingly, finite fatigue lives were previously introduced for Fairey Hydraulics Ltd (FHL) landing gear and associated components, installed on affected aeroplanes by Service Bulletin 298 at revision 1 and CAA AD G-2003-0013, issued in October 2003. Since this time, landing gear have also been manufactured by Claverham and Britten Norman Aircraft (BNA) which are identified by new part numbers.

For the reasons described above, this CAA AD retains the requirements of CAA AD G-2003-0013, which is superseded and introduces a revised applicability.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously.

Check

- (1) Within one month after the effective date of this AD, determine the number of landings accumulated on affected main and nose landing gear and components (identified in Tables 1, 2 and 3).

Table 1 Landing Gear Fatigue Lives – Nose Landing Gears

Assembly No. (Part No.)	Fatigue Life (Landings)
3501H1	30000
3501H2	40000
3511H1	No Limit
3811H1	No Limit
3811H2 or BN-NLG01 or BN-NLG03	No Limit
4823H1 or BN-NLG02	40000

Table 2 Landing Gear Fatigue Lives – Main Landing Gears

Assembly No. (Part No.)	Fatigue Life (Landings)
3499H1	30000
3499H2 or BN-MLG01	40000
3570H1	30000
3570H2 or BN-MLG03	40000
4825H1 or BN-MLG02	40000

Table 3 Landing Gear Components - Fatigue Lives

Assembly No.	Component	Part No.	Fatigue Life (Landings)
3499H1	Cylinder	46171	4000
3507H1	Cylinder	46021	4000
	Pin	46043	20000
3507H2 or BN-MLG03	Pin	46043	20000
	Link	46071	30000
4825H1 or BN-MLG02	Link	46071	30000

Corrective action

- (2) Any main or nose landing gear or component which exceed the fatigue life stated in Tables 1,2 or 3 must be withdrawn from service immediately.

Installation of used landing gear components

- (3) Do not install an affected part on any aircraft unless the life of part has been established to be below the associated fatigue life, as stated in Tables 1, 2 or 3.

Reference Publications:

Britten-Norman Service Bulletin 298 Issue 2 dated 13 December 2022.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This AD will be closed for consultation on 08 March 2023.
2. The safety assessment has warranted immediate publication and notification without implementing the full consultation process.
3. If requested and appropriately substantiated, CAA can approve Alternative Methods of Compliance for this AD.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the CAA aviation safety reporting system [Occurrence reporting | Civil Aviation Authority](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. Enquiries regarding this AD should be referred to: Continued.Airworthiness@caa.co.uk
6. For any questions concerning the technical content of the requirements in this AD, please contact: Britten-Norman Aircraft Ltd at email: customer.support@britten-norman.com