



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2025-01-013	發布日期 Date issued	2025/01/17
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Bombardier Inc. model BD-700-1A10 and BD-700-1A11 aeroplanes, serial numbers included in Section 1.A, Effectivity, of Bombardier applicable Service Bulletins (SBs) listed in Table 1 of this AD.		
主旨摘要 Subject	Indicating/Recording Systems - Unsecured maintenance ports		
民航局 CAA <input type="radio"/> 本國產品 Native product <input type="radio"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="radio"/> FAA <input type="radio"/> Germany LBA <input type="radio"/> EASA <input type="radio"/> CAA-NL <input type="radio"/> Brazil <input type="radio"/> UK CAA <input checked="" type="radio"/> Transport Canada Civil Aviation <input type="radio"/> Japan CAB <input type="radio"/> DGAC <input type="radio"/> CAA of Israel <input type="radio"/> Other_____		
	設計國AD編號 Original AD number	CF-2025-03	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as): 2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	ATA 31. Please refer to Table 1 of this AD.		

註： 1. AD內容後附。
2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



AIRWORTHINESS DIRECTIVE

This Airworthiness Directive (AD) is issued pursuant to Canadian Aviation Regulation (CAR) 521.427. No person shall conduct a take-off or permit a take-off to be conducted in an aircraft that is in their legal custody and control, unless the requirements of CAR 605.84 pertaining to ADs are met. Standard 625 - Aircraft Equipment and Maintenance Standards Appendix H provides information concerning alternative means of compliance (AMOC) with ADs.

Number:

CF-2025-03

Effective Date:

29 January 2025

ATA:

31

Type Certificate:

A-177

Subject:

Indicating/Recording Systems – Unsecured maintenance ports

Applicability:

Bombardier Inc. model BD-700-1A10 and BD-700-1A11 aeroplanes, serial numbers included in Section 1.A, Effectivity, of Bombardier applicable Service Bulletins (SBs) listed in Table 1 of this AD.

Compliance:

Within 6 months from the effective date of this AD, unless already accomplished.

Background:

This AD requires the installation of locking features on the applicable network interfaces to prevent unapproved physical accesses.

Corrective Actions:

- A. Install the locking features in accordance with the procedure in Section 2, Accomplishment Instructions, of the applicable Service Bulletin (SB) listed in Table 1 of this AD.

Table 1 – Applicable SBs

Aeroplane Model (Marketing Designation)	Bombardier SBs
BD-700-1A11 (Global 5000 featuring Global Vision Flight Deck, GVFD)	SB 700-46-5008 Basic Issue, dated, 20 July 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A10 (Global 6000)	SB 700-46-6008 Basic Issue, dated, 20 July 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A11 (Global 5500)	SB 700-46-5504 Revision 01, dated, 22 August 2024, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A10 (Global 6500)	SB 700-46-6504 Revision 01, dated, 22 August 2024, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada

- B. This paragraph gives credit for the installation of the locking features, indicated in Paragraph A of this AD, before the effective date of this AD, in accordance with the Basic Issue of SB 700-46-5504 or SB 700-46-6504, dated 20 July 2022.

Authorization:

For the Minister of Transport,

ORIGINAL SIGNED BY

Jenny Young
Chief, Continuing Airworthiness
Issued on 15 January 2025

Contact:

João Falcão, Continuing Airworthiness, Ottawa, telephone 888-663-3639, facsimile 613-996-9178 or e-mail TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca or any Transport Canada Centre.