



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2025-04-001	發布日期 Date issued	2025/04/07
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-841 and A330-941 aeroplanes, manufacturer serial numbers (MSN) as listed in Appendix 1 of this AD.		
主旨摘要 Subject	Fuselage - Central Windshield Frame - Inspection		
民航局 CAA <input type="radio"/> 本國產品 Native product <input type="radio"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="radio"/> FAA <input type="radio"/> Germany LBA <input checked="" type="radio"/> EASA <input type="radio"/> CAA-NL <input type="radio"/> Brazil <input type="radio"/> UK CAA <input type="radio"/> Transport Canada Civil Aviation <input type="radio"/> Japan CAB <input type="radio"/> DGAC <input type="radio"/> CAA of Israel <input type="radio"/> Other_____		
	設計國AD編號 Original AD number	2025-0071	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as): 2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	ATA 53. Ref. Publications: Airbus SB A330-53-3325 original issue dated 13 February 2025.		

註： 1. AD內容後附。
2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464,
adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aviation Administration on Tel：(02)2349-6330 / 6332,
Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2025-0071

Issued: 31 March 2025

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS S.A.S.

Type/Model designation(s):

A330 aeroplanes

Effective Date: 14 April 2025

TCDS Number(s): EASA.A.004

Foreign AD: Not applicable

Supersedure: None

ATA 53 – Fuselage – Central Windshield Frame – Inspection

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-841 and A330-941 aeroplanes, manufacturer serial numbers (MSN) as listed in Appendix 1 of this AD.

Definitions:

For the purpose of this AD, the following definitions apply:

Affected parts: Central windshield frame having Part Number (P/N) F531-23012-200 or P/N F531-23011-200 (also identified as P/N F5312301220000 or P/N F5312301120000 respectively).

The SB: Airbus Service Bulletin (SB) A330-53-3325.

Reason:

An incorrect shot peening application has been implemented in production starting from 2008.

Fatigue life of affected parts could consequently be lower than the certified value.

This condition, if not detected and corrected, could affect the structural integrity of the aeroplane.



To address this potential unsafe condition, Airbus issued the SB, identifying the MSN of the aeroplanes having an affected part installed (also listed in Appendix 1 of this AD), and providing inspection instructions.

For the reason described above, this AD requires repetitive special detailed inspections (SDI) of affected parts and, depending on findings, corrective action(s).

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the actions required by this AD have been already accomplished:

Repetitive Inspections:

- (1) Before exceeding 27 490 flight cycles (FC) since first flight of the aeroplane, and, thereafter, at intervals not exceeding 27 490 FC, inspect the affected parts in accordance with the instructions of the SB.

Corrective Action(s):

- (2) If, during any inspection as required by paragraph (1) of this AD, any crack is found on an affected part, before next flight, contact Airbus for repair instructions and, within the compliance time specified in those instructions, accomplish those instructions accordingly.

Terminating Action:

- (3) Corrective action(s) accomplished on an aeroplane, as required by paragraph (2) of this AD, do not constitute terminating action for the repetitive inspections as required by paragraph (1) of this AD for that aeroplane, unless specified otherwise in the Airbus repair instructions.

Ref. Publications:

Airbus SB A330-53-3325 original issue dated 13 February 2025.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 27 February 2025 as PAD 25-037 for consultation until 27 March 2025. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or



may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.

5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – 1IAL (Airworthiness Office), E-mail: airworthiness.A330-A340@airbus.com.



Appendix 1 – Affected MSNs

1092, 1093, 1094, 1095, 1096, 1097, 1098, 1099, 1100, 1101, 1103
1104, 1105, 1106, 1107, 1108, 1110, 1112, 1114, 1115, 1116, 1118
1120, 1123, 1124, 1126, 1127, 1130, 1131, 1132, 1133, 1135, 1136
1137, 1138, 1141, 1143, 1145, 1146, 1147, 1148, 1149, 1150, 1151
1153, 1155, 1156, 1157, 1159, 1160, 1161, 1163, 1164, 1165, 1167
1168, 1169, 1170, 1171, 1172, 1173, 1174, 1175, 1177, 1178, 1180
1181, 1183, 1184, 1186, 1187, 1188, 1189, 1190, 1191, 1192, 1193
1195, 1196, 1198, 1199, 1200, 1201, 1202, 1203, 1204, 1205, 1206
1208, 1209, 1210, 1211, 1212, 1213, 1214, 1215, 1216, 1217, 1218
1219, 1220, 1221, 1222, 1223, 1224, 1225, 1226, 1227, 1228, 1229
1230, 1231, 1232, 1233, 1234, 1235, 1236, 1237, 1238, 1239, 1240
1241, 1243, 1245, 1246, 1247, 1248, 1249, 1250, 1251, 1252, 1254
1255, 1256, 1258, 1259, 1260, 1261, 1262, 1263, 1264, 1265, 1266
1267, 1268, 1269, 1270, 1271, 1272, 1274, 1275, 1276, 1277, 1278
1279, 1280, 1281, 1282, 1283, 1284, 1285, 1286, 1287, 1288, 1289
1290, 1291, 1292, 1293, 1294, 1295, 1296, 1297, 1298, 1299, 1300
1301, 1302, 1303, 1304, 1305, 1306, 1307, 1308, 1309, 1310, 1311
1312, 1313, 1314, 1315, 1316, 1317, 1318, 1319, 1320, 1321, 1322
1323, 1324, 1325, 1326, 1327, 1328, 1329, 1330, 1331, 1332, 1333
1334, 1335, 1336, 1337, 1338, 1339, 1340, 1341, 1342, 1343, 1344
1345, 1346, 1347, 1348, 1349, 1350, 1351, 1352, 1353, 1354, 1355
1356, 1357, 1358, 1359, 1360, 1361, 1362, 1363, 1364, 1365, 1366
1367, 1368, 1369, 1370, 1371, 1372, 1373, 1374, 1375, 1376, 1377
1378, 1379, 1380, 1381, 1382, 1383, 1384, 1385, 1386, 1387, 1388
1389, 1390, 1391, 1392, 1393, 1394, 1395, 1396, 1397, 1398, 1399
1400, 1401, 1402, 1403, 1404, 1405, 1406, 1407, 1408, 1409, 1410
1411, 1412, 1413, 1414, 1415, 1416, 1417, 1418, 1419, 1420, 1421
1422, 1423, 1425, 1426, 1427, 1428, 1429, 1430, 1431, 1432, 1433
1434, 1435, 1436, 1437, 1438, 1439, 1440, 1441, 1442, 1443, 1444
1445, 1446, 1447, 1448, 1449, 1450, 1451, 1452, 1453, 1454, 1455
1456, 1457, 1458, 1459, 1460, 1461, 1462, 1463, 1464, 1465, 1466
1467, 1468, 1469, 1470, 1471, 1472, 1473, 1474, 1475, 1476, 1477
1478, 1479, 1480, 1481, 1482, 1483, 1484, 1485, 1486, 1487, 1488
1489, 1490, 1491, 1492, 1493, 1494, 1495, 1496, 1497, 1498, 1499
1500, 1501, 1502, 1503, 1504, 1505, 1506, 1507, 1508, 1509, 1510
1511, 1512, 1513, 1514, 1515, 1516, 1517, 1518, 1519, 1520, 1521
1523, 1524, 1525, 1526, 1527, 1528, 1529, 1530, 1531, 1532, 1533
1534, 1535, 1536, 1537, 1538, 1539, 1540, 1541, 1542, 1543, 1544
1545, 1546, 1547, 1548, 1549, 1550, 1551, 1552, 1553, 1554, 1555
1556, 1557, 1558, 1559, 1560, 1561, 1562, 1563, 1564, 1565, 1566
1567, 1568, 1569, 1570, 1571, 1572, 1573, 1574, 1575, 1576, 1577
1578, 1579, 1580, 1581, 1582, 1583, 1584, 1585, 1586, 1587, 1588
1589, 1590, 1591, 1592, 1593, 1594, 1595, 1596, 1597, 1598, 1599
1600, 1601, 1602, 1603, 1604, 1605, 1606, 1607, 1608, 1609, 1610
1611, 1612, 1613, 1614, 1615, 1616, 1617, 1618, 1619, 1620, 1621



1622, 1623, 1624, 1625, 1626, 1627, 1628, 1629, 1630, 1631, 1632
1633, 1634, 1635, 1636, 1637, 1638, 1639, 1640, 1641, 1642, 1643
1644, 1645, 1646, 1647, 1648, 1649, 1650, 1651, 1653, 1654, 1655
1656, 1657, 1658, 1659, 1660, 1662, 1663, 1664, 1665, 1666, 1667
1668, 1669, 1670, 1671, 1672, 1673, 1674, 1675, 1676, 1677, 1678
1679, 1680, 1681, 1684, 1685, 1686, 1687, 1688, 1689, 1690, 1691
1692, 1693, 1694, 1695, 1696, 1697, 1698, 1699, 1700, 1701, 1703
1704, 1706, 1708, 1709, 1710, 1711, 1712, 1713, 1714, 1715, 1716
1718, 1719, 1720, 1721, 1722, 1723, 1724, 1725, 1726, 1727, 1728
1729, 1730, 1731, 1732, 1733, 1734, 1735, 1736, 1737, 1738, 1739
1740, 1741, 1742, 1743, 1744, 1745, 1746, 1747, 1748, 1749, 1750
1751, 1752, 1753, 1754, 1755, 1756, 1757, 1758, 1759, 1760, 1761
1762, 1763, 1764, 1765, 1766, 1767, 1768, 1769, 1770, 1771, 1772
1773, 1774, 1775, 1776, 1777, 1778, 1779, 1780, 1781, 1782, 1783
1784, 1785, 1786, 1787, 1788, 1789, 1790, 1791, 1792, 1793, 1794
1796, 1797, 1798, 1799, 1800, 1801, 1802, 1803, 1804, 1805, 1806
1807, 1808, 1809, 1810, 1811, 1812, 1814, 1815, 1816, 1817, 1818
1819, 1820, 1821, 1822, 1823, 1825, 1826, 1827, 1828, 1829, 1830
1831, 1832, 1833, 1835, 1836, 1837, 1838, 1839, 1840, 1841, 1842
1843, 1844, 1845, 1846, 1847, 1848, 1849, 1850, 1851, 1852, 1854
1855, 1856, 1857, 1858, 1859, 1860, 1861, 1862, 1863, 1864, 1865
1866, 1867, 1868, 1869, 1870, 1871, 1872, 1873, 1874, 1875, 1876
1877, 1878, 1879, 1880, 1881, 1882, 1883, 1884, 1885, 1886, 1887
1888, 1889, 1890, 1891, 1892, 1893, 1894, 1895, 1896, 1897, 1898
1899, 1900, 1901, 1902, 1903, 1904, 1905, 1906, 1907, 1908, 1909
1910, 1911, 1912, 1913, 1914, 1915, 1916, 1917, 1918, 1919, 1920
1921, 1922, 1923, 1924, 1925, 1926, 1927, 1928, 1929, 1931, 1932
1933, 1934, 1935, 1936, 1937, 1938, 1939, 1941, 1942, 1943, 1945
1946, 1947, 1948, 1949, 1950, 1951, 1952, 1953, 1954, 1956, 1957
1958, 1959, 1960, 1961, 1962, 1963, 1964, 1965, 1966, 1967, 1968
1969, 1970, 1971, 1972, 1973, 1975, 1976, 1977, 1978, 1979, 1981
1982, 1983, 1984, 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993
1994, 1995, 1996, 1997, 1998

