



Civil Aeronautics Administration

Aviation Safety Bulletin

ASB No: 95-036/O

Apr 20,2006

Subject :

Pilots must follow ATC taxi clearance.

Background :

A national registered aircraft crossing a parallel and active runway without proper clearance resulted in go-around of other approaching aircraft.

Recommendation :

- 1. Airlines shall review CCAA AC120-015-“Flight Crew Taxi procedures” and ensure that all the contents are covered by company procedures (including checklist) and training syllabi.**
- 2. Operator should continue to educate flight crew to follow the taxi’s SOP. When a taxi clearance received is unclear or in doubt, crew shall reconfirm with ATC.**
- 3. When crossing an active runway, proper use of all aircraft exterior lights is recommended. It will highlight your position and also draw the attention from ATC controllers, ground crews and flight crew in the vicinity.**