



# CIVIL AERONAUTICS ADMINISTRATION

## AVIATION SAFETY BULLETIN

ASB No: 92-005/FS

APRIL, 2003

### **SUBJECT :**

A runway incursion event was caused by a domestic airline and an engineering vehicle collided at night while landing.

### **BACKGROUND :**

Sever places on landing gear and fuselage were damaged and the collided vehicle was destroyed. Two passengers out of three on the vehicle were injured and were sent to hospital for treatment. After the aircraft came to a complete stop on the runway, all crews and passengers were transported to the waiting room by shuttle bus.

### **RECOMMENDATION:**

1. Restate CAA 90-016 "Runway Incursion Prevention Best Practices" NOTAM, to relevant operation personnel, should be highly alert to conditions of runway incursion
2. The construction unit must deploy relevant regulations of the construction contract and construction safety rule.