

 適航指令發布單 Airworthiness Directive Issuance Form		
民航局 AD 編號 AD number	CAA-2016-06-011 發布日期 Date issued	2016/6/24
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	Airbus A350-941 aeroplanes, all serial numbers.	
主旨摘要	Time Limits / Maintenance Checks - Certification Maintenance Requirements - ALS Part 3 - Amendment	
民航局 CAA <input type="checkbox"/> 本國產品 Native products <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authorities <input type="checkbox"/> FAA <input checked="" type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____	
	設計國 AD 編號 Original AD number	2016-0112
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)	
備註 Note	ATA 05. Ref. Publications: Airbus A350 ALS Part 3 Revision 02, issued on 08 January 2016.	
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6331~3, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw		



Airworthiness Directive

AD No.: 2016-0112

Issued: 15 June 2016

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A350 aeroplanes

Effective Date: 29 June 2016

TCDS Number(s): EASA.A.151

Foreign AD: Not applicable

Supersedure: None

ATA 05 – Time Limits / Maintenance Checks – Certification Maintenance Requirements - ALS Part 3 – Amendment

Manufacturer(s):

Airbus

Applicability:

Airbus A350-941 aeroplanes, all serial numbers.

Reason:

The Certification Maintenance Requirements (CMR) for the Airbus A350, which are approved by EASA, are currently defined and published in the Airbus A350 Airworthiness Limitations Section (ALS) document(s). These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

The Revision 02 of A350 ALS Part 3 includes new and/or more restrictive requirements.

For the reason described above, this AD requires accomplishment of the actions specified in Airbus A350 ALS Part 3 Revision 02 (hereafter referred to as 'the ALS' in this AD).



Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

- (1) From the effective date of this AD, accomplish all applicable maintenance tasks before exceeding the thresholds and, thereafter, within the intervals (see Note 1 of this AD), as specified in the ALS.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the ALS include the compliance times as defined in that document for certain tasks.

- (2) **Corrective Action(s):** In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable Airbus maintenance documentation. If a detected discrepancy cannot be corrected by using existing Airbus instructions, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.
- (3) **Aircraft Maintenance Programme (AMP) Revision:** Within 12 months after the effective date of this AD, revise the approved AMP, on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane, by incorporating the maintenance tasks and associated thresholds and intervals described in the ALS.
- (4) **Credit:** For an AMP that, on the effective date of this AD, is already updated to incorporate the maintenance tasks as specified in Airbus A350 ALS Part 3 Revision 01, that action ensures the continued accomplishment of those tasks (see Note 2 of this AD).

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and more restrictive tasks, as defined in and within the compliance times (see Note 1 of this AD) as specified in the ALS to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and more restrictive tasks, as defined in the ALS to comply with paragraph (3) of this AD.

- (5) **Recording AD compliance:** When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures (see Note 2 of this AD) continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Note 2: For affected A350 aeroplanes registered in Europe, complying with the approved AMP, as specified in paragraph (3) or (4) of this AD, as applicable, is required by Commission Regulation (EU) No [1321/2014](#), Part M.A.301, paragraph 3.

Ref. Publications:

Airbus A350 ALS Part 3 Revision 02, issued on 08 January 2016.



The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 09 May 2016 as PAD 16-063 for consultation until 06 June 2016. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. For any question concerning the technical content of the requirements in this AD, please contact: continued-airworthiness.a350@airbus.com.

