



適航指令發布單

Airworthiness Directive Issuance Form

| | | | |
|--|---|---------------------|-----------|
| 民航局 AD 編號 AD number | CAA-2023-02-008 | 發布日期 Date issued | 2023/2/20 |
| 適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable) | Aircraft serial numbers mentioned in SB 365-35-M058 for 737-300/-400 and SB 365-35-M011 for 737-700/-800 certificated in any category. | | |
| 主旨摘要 Subject | Supernumerary oxygen system mask replacement. | | |
| <div style="text-align: center;">民航局 CAA</div> <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other | <div style="text-align: center;">設計國民航主管機構 Original Authority</div> <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <input type="checkbox"/> FAA <input type="checkbox"/> EASA <input type="checkbox"/> Brazil <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> DGAC </div> <div style="width: 45%;"> <input type="checkbox"/> Germany LBA <input type="checkbox"/> CAA-NL <input type="checkbox"/> UK CAA <input type="checkbox"/> Japan CAB <input checked="" type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____ </div> </div> | | |
| | 設計國 AD 編號 Original AD number | ISR I-35-2022-12-9 | |
| | 1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) <div style="margin-left: 40px;"> a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ </div> | | |
| | 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No) | | |
| 備註 Note | Ref. SB 365-35-M058 | | |

註： 1. AD 內容後附。
 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail：
adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail：
adcaa@mail.caa.gov.tw

**State of Israel
Ministry of Transport
Civil Aviation Authority**

**AD ISR I-35-2022-12-9
Date: Feb 8, 2023**

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority of Israel in accordance with the Israeli Air Navigation Regulations applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Aircraft serial numbers mentioned in SB 365-35-M058 for 737-300/-400 and SB 365-35-M011 for 737-700/-800 certificated in any category.

SUBJECT: **Supernumerary oxygen system mask replacement.**

REASON: Due to the lack of performance data available for oxygen mask P/N 28314-12 currently installed on aircraft, an oxygen mask with TSO C64a authorization is required to ensure compliance of each supernumerary oxygen mask & cylinder assembly with the airworthiness regulations.

ACTION: Supernumerary oxygen masks replacement. Oxygen masks P/N 28314-12 (Safran) by Oxygen masks P/N 174097-11 (B/E Aerospace) which are TSO C64a approved.

COMPLIANCE: Unless already accomplished, comply with this AD at the next suitable planned maintenance inspection within the next 12 months from the effective date of this AD

EFFECTIVE DATE: February 08, 2023.

FOR FURTHER INFORMATION CONTACT: Mr. Liran Cohen, Aircraft Certification Department, CAAI - P.O. Box 1101, 3 Golan Street, Airport City, Israel, 70151. Telephone: 972-3-9774529, E-mail: cohenli@mot.gov.il .