



適航指令發布單

Airworthiness Directive Issuance Form

民航局 AD 編號 AD number	CAA-2023-08-005 緊急	發布日期 Date issued	2023/8/9
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	All balloons equipped with fuel cylinders Part Number CB2990 Issue A (Alugas) having serial numbers: OC25001 to OC25202 QI14001 to QI14496 Note: This serial number range covers all CB2990 Issue A (Alugas) cylinders. CB2990 Issue B (Alugas) cylinders are not affected by this Airworthiness Directive. These fuel cylinders are known to be installed on, but not limited to, hot-air balloons and airships manufactured by Cameron Balloons Ltd, Colt Balloons, Lindstrand Balloons Ltd (LBL), Lindstrand Hot Air Balloons Ltd, Sky Balloons, Thunder Balloons, and Thunder & Colt.		
主旨摘要 Subject	Fuel - Fuel Cylinders (for balloons) - Withdrawal from Service		
民航局 CAA <input type="checkbox"/> 本國產品 Native product <input type="checkbox"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="checkbox"/> FAA <input type="checkbox"/> Germany LBA <input type="checkbox"/> EASA <input type="checkbox"/> CAA-NL <input type="checkbox"/> Brazil <input checked="" type="checkbox"/> UK CAA <input type="checkbox"/> Transport Canada Civil Aviation <input type="checkbox"/> Japan CAB <input type="checkbox"/> DGAC <input type="checkbox"/> CAA of Israel <input type="checkbox"/> Other _____		
	設計國 AD 編號 Original AD number	G-2023-0005-E	
	1. 直接採用原 AD 之內容?(Is the original AD directly adopted?) <input checked="" type="checkbox"/> 是(Yes) <input type="checkbox"/> 否(No) _ a. 生效日期另訂為(Re-specify the effective date as) : _____ b. 執行時限另訂為(Re-specify the compliance time or period as) : _____ 2. 使用人是否需要將 AD 執行結果向民航局提出報告?(Do Users need to report the status of compliance to the CAA?) <input type="checkbox"/> 是(Yes) <input checked="" type="checkbox"/> 否(No)		
備註 Note	This AD supersedes UK AD G-2022-0010-E(CAA-2022-05-006 緊急) dated 12 May 2022.		
註： 1. AD 內容後附。 2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。 3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, e-mail： adcaa@mail.caa.gov.tw Note： 1. The AD text is enclosed. 2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval. 3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax： (02)2545-8464, e-mail： adcaa@mail.caa.gov.tw			



Civil Aviation Authority

EMERGENCY AIRWORTHINESS DIRECTIVE



Number: G-2023-0005-E

Issue date: 31 July 2023

Note: In this Airworthiness Directive, references to EU regulations are to those regulations as retained and amended in UK domestic law under the European Union (Withdrawal) Act 2018 and are referenced as "UK Regulation (EU) year/number or UK Regulation (EU) No. number/year".

This Airworthiness Directive (AD) is issued by the UK CAA in accordance with UK Regulation (EU) No. 748/2012 Part 21.A.3B, acting as the Authority of the State of Design for the affected product(s), under Article 34 of the Air Navigation Order 2016 (ANO) and UK Regulation (EU) 2018/1139.

In accordance with UK Regulation (EU) No. 1321/2014 Annex I (Part-M), M.A.301 / Annex VB (Part-ML), ML.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified or agreed by the CAA [Part-M, M.A.303 / Part-ML, ML.A.303].

Design Approval Holder's Name:

CAMERON BALLOONS Ltd

Type Designation(s):

Fuel Cylinders Part Number CB2990
Issue A (Alugas)

Effective Date:	02 August 2023
TCDS Number(s):	Not Applicable
Foreign AD:	Not Applicable
Supersedure:	This AD supersedes UK AD G-2022-0010-E dated 12 May 2022

ATA 28 – Fuel - Fuel Cylinders (for balloons) – Withdrawal from Service

Manufacturer(s):

Cameron Balloons Ltd.

Applicability:

All balloons equipped with fuel cylinders Part Number CB2990 Issue A (Alugas) having serial numbers:
OC25001 to OC25202
QI14001 to QI14496

Note: This serial number range covers all CB2990 Issue A (Alugas) cylinders. CB2990 Issue B (Alugas) cylinders are **not** affected by this Airworthiness Directive.

These fuel cylinders are known to be installed on, but not limited to, hot-air balloons and airships manufactured by Cameron Balloons Ltd, Colt Balloons, Lindstrand Balloons Ltd (LBL), Lindstrand Hot Air Balloons Ltd, Sky Balloons, Thunder Balloons, and Thunder & Colt.

Definitions:

For the purpose of this AD, the following definitions apply:

Affected Part: CB2990 Issue A Fuel Cylinder

The ASB: Cameron Balloons Alert Service Bulletin SB33

Reason:

Five CB2990 Issue A (Alugas) cylinders developed cracks in the weld between the cylinder valve plate and the upper dished end. These cracks allow the release of propane from the cylinder. Failures have been observed during periodic inspection (hydraulic pressure test) and leak test.

It is likely that other CB2990 Issue A cylinders may develop similar failures in service.

To address this potential unsafe condition Alert Service Bulletin 33 Revision 0 was issued to temporarily withdraw all CB2990 Issue A (Alugas) cylinders from service and consequently the CAA issued AD G-2022-0010-E.

Since the issue of AD G-2022-0010-E, a re-design of the affected component (CB2990) has taken place and **Cameron Service Bulletin 33 Revision 2** has been issued to confirm this work, to declare that CB 2990 Issue B standard replaces Issue A, and that all CB2990 Issue A (Alugas) cylinders are permanently withdrawn from service.

(Note; the applicability list has been altered in Service Bulletin 33 Revision 2, and this has been reflected above.)

For the reasons described above this AD has been issued and supersedes AD G-2022-0010-E.

Required Action(s) and Compliance Time(s):

From the effective date of the AD, the affected parts must be removed from service, no further flight is permitted.

Note: The affected parts are unsafe for the storage of LPG and must be emptied and rendered unserviceable for that purpose.

Reference Publications:

Cameron Balloons Limited Alert Service Bulletin No 33 revision 2 dated June 2023

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. The safety assessment has warranted immediate publication and notification without implementing the full consultation process.

2. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the CAA aviation safety reporting system [Occurrence reporting Civil Aviation Authority](#) This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
3. Enquiries regarding this Airworthiness Directive should be referred to: ga@caa.co.uk
4. For any questions concerning the technical content of the requirements in this AD, please contact:

Cameron Balloons Limited
St Johns Street
Bedminster
Bristol, UK
BS3 4NH

Email: technical@cameronballoons.co.uk

Tel: +44 (0)117 9637216