



適航指令發布單

Airworthiness Directive Issuance Form

民航局AD編號 AD number	CAA-2024-07-004	發布日期 Date issued	2024/07/11
適用之航空產品 Applied to (models, serial numbers or part numbers, as applicable)	ATR 42-200, ATR 42-300, ATR 42-320, ATR 42-400 and ATR 42-500 aeroplanes, all manufacturer serial numbers (MSN); and ATR 72-101, ATR 72-102, ATR 72-201, ATR 72-202, ATR 72-211, ATR 72-212 and ATR 72-212A aeroplanes, all MSN.		
主旨摘要 Subject	Fire Protection - Lavatory Compartment Fire Extinguishers - Inspection / Replacement		
民航局 CAA <input type="radio"/> 本國產品 Native product <input type="radio"/> 其他個案 Other	設計國民航主管機構 Original Authority <input type="radio"/> FAA <input type="radio"/> Germany LBA <input checked="" type="radio"/> EASA <input type="radio"/> CAA-NL <input type="radio"/> Brazil <input type="radio"/> UK CAA <input type="radio"/> Transport Canada Civil Aviation <input type="radio"/> Japan CAB <input type="radio"/> DGAC <input type="radio"/> CAA of Israel <input type="radio"/> Other_____		
	設計國AD編號 Original AD number	2024-0132	
	1. 直接採用原AD之內容? (Is the original AD directly adopted?) <input checked="" type="radio"/> 是(Yes) <input type="radio"/> 否(No)_ a. 生效日期另訂為(Re-specify the effective date as): b. 執行時限另訂為(Re-specify the compliance time or period as): 2. 使用人是否需要將AD執行結果向民航局提出報告? (Do users need to report the status of compliance to the CAA?) <input type="radio"/> 需要(Yes) <input checked="" type="radio"/> 不需要(No)		
備註 Note	ATA 26. Ref. Publications: ATR AOM 2024/01 Issue 1 dated 25 January 2024.		

註： 1. AD內容後附。
2. 航空器產品使用人得向民航局提出豁免、替代符合方法、執行時限之展延之申請。
3. 如有任何問題，請聯絡交通部民用航空局初始適航科。Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464,
adcaa@mail.caa.gov.tw

Note： 1. The AD text is enclosed.
2. Exemption, an alternative method of compliance or adjustment of the compliance time may be proposed to the CAA for approval.
3. For further information, please contact Civil Aeronautics Administration on Tel：(02)2349-6330 / 6332, Fax：(02)2545-8464, adcaa@mail.caa.gov.tw



Airworthiness Directive

AD No.: 2024-0132

Issued: 09 July 2024

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

ATR-GIE AVIONS DE TRANSPORT REGIONAL

Type/Model designation(s):

ATR 42 and ATR 72 aeroplanes

Effective Date: 23 July 2024

TCDS Number(s): EASA.A.084

Foreign AD: Not applicable

Supersedure: None

ATA 26 – Fire Protection – Lavatory Compartment Fire Extinguishers – Inspection / Replacement

Manufacturer(s):

ATR-GIE Avions de Transport Régional, formerly EADS ATR - Alenia, Aerospatiale Matra ATR - ALENIA, Aerospatiale - Alenia, Aerospatiale – Aeritalia

Applicability:

ATR 42-200, ATR 42-300, ATR 42-320, ATR 42-400 and ATR 42-500 aeroplanes, all manufacturer serial numbers (MSN); and

ATR 72-101, ATR 72-102, ATR 72-201, ATR 72-202, ATR 72-211, ATR 72-212 and ATR 72-212A aeroplanes, all MSN.

Definitions:

For the purpose of this AD, the following definitions apply:

The AOM: ATR Airworthiness Operators Message (AOM) 2024/01 Issue 1.

Affected part: Lavatory (waste bin) compartment fire extinguisher having Part Number (P/N) BA24320L-1, a serial number (s/n) between 70472 and 113558 inclusive; except those which passed (no defect found) an inspection in accordance with the instructions of the AOM.



Serviceable part: Any lavatory (waste bin) compartment fire extinguishers, eligible for installation in accordance with ATR instructions, which is not an affected part.

Groups: Group 1 aeroplanes are those that have an affected part installed.

Group 2 aeroplanes are those that do not have an affected part installed.

Reason:

A manufacturing defect has been identified in the lavatory fire extinguisher. This defect could potentially result in leakage at the eutectic tip, leading to a loss of pressure in the cylinder, making fire extinguishing capabilities ineffective.

This condition, if not detected and corrected, in combination with fire in the lavatory waste bin, could result in an uncontrolled and rapid fire propagation.

To address this potential unsafe condition, ATR issued the AOM, as defined in this AD, to provide inspection and replacement instructions.

For the reasons described above, this AD requires an inspection of the affected parts, and, depending on findings, replacement. This AD also prohibits (re)installation of affected parts.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Inspection(s):

- (1) For Group 1 aeroplanes: Within 6 months after the effective date of this AD, accomplish a weight check of each affected part, as defined in this AD, in accordance with the instructions of the AOM.

Corrective Action(s):

- (2) If, during the inspection as required by paragraph (1) of this AD, any discrepancy is detected on an affected part, before next flight, replace that affected part with a serviceable part in accordance with the instructions of the AOM.

Parts Installation:

- (3) For Group 1 and Group 2 aeroplanes: From the effective date of this AD, do not install an affected part on any aeroplane (see Note 1 of this AD).

Note 1: Removal of an affected part from an aeroplane and subsequent reinstallation of that affected part on the same aeroplane, accomplished during a single maintenance visit, is not considered as 'install' as specified in paragraph (3) of this AD.

Ref. Publications:

ATR AOM 2024/01 Issue 1 dated 25 January 2024.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.



Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 07 June 2024 as PAD 24-066 for consultation until 05 July 2024. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: ATR - GIE Avions de Transport Régional, Continued Airworthiness Service, Telephone: +33 (0)5 62 21 62 21, Fax: +33 (0) 5 62 21 67 18; E-mail: continued.airworthiness@atr-aircraft.com.

